

**STATE OF WEST VIRGINIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
OFFICE OF OIL AND GAS**

AFFIDAVIT OF PLUGGING AND FILLING WELL

AFFIDAVIT SHOULD BE IN TRIPLICATE, one copy mailed to the Department, one copy to be retained by the Well Operator and the third copy (and extra copies if required) should be mailed to each coal operator at their respective addresses.

Farm Name: Allegheny Forest Lands LL Operator Well No.: ERC & L 7898

Location: Elevation: 402 Quadrangle Swandale
District: Buffalo County Clay
Latitude GPS4260935.787 Feet South of _____ Deg. _____ Min. _____ Sec. _____
Longitude GPS502200.289 Feet West of _____ Deg. _____ Min. _____ Sec. _____

Well Type: Oil _____ Gas X

Company: Range Resources - Pine Mnt Inc. Coal Operator or _____
P O Box 2136 Owner: _____
Abingdon VA 24212

Agent: Tom Young Coal Operator or _____
Owner: _____

Permit Issued Date: 11/9/10

RECEIVED
Office of Oil & Gas
MAY 7 2012
WV Department of
Environmental Protection

AFFIDAVIT

State of West Virginia, County of Lincoln ss:

Paul Stevens and Matthew Adkins being first duly sworn according to law plugging and filling oil and gas wells and were employed by the above named well operator, and participated in the work of plugging and filling the above well say that said work was commenced on the 18th day of April 2011 and the well was plugged and filled in the following manner:


TYPE	FROM	TO	PIPE REMOVED	LEFT
Gel Hole	Surface	2192'		
Cement	2160'	1860'		
Cement	1450'	1200'		
Pull 7"		639'	639'	834'
Cement	660'	560'		10-3/4" - 611'
Cement	465'	400'	Perforate 10" casing	- 443'-440'/253'-250'/153'-150'
Cement	270'	Surface		

Description of monument: Erect monument with API# 47-015-00315 and that the work of plugging and filling said well was completed on the 25th day of April 2011.

And further deponents saith not. Paul Stevens
Matthew Adkins

Sworn and subscribe before me this 27th day of April 2011
My commission expires: 10-7-2012

Notary Public [Signature]
Affidavit reviewed by the
Office of Oil and Gas: [Signature]



Title: Inspector
Not on location during plugging

05/11/2012