



---

west virginia department of environmental protection

---

Office of Oil and Gas  
601 57th Street SE  
Charleston, WV 25304  
(304) 926-0450  
(304) 926-0452 fax

Earl Ray Tomblin, Governor  
Randy C. Huffman, Cabinet Secretary  
www.dep.wv.gov

August 31, 2015

## FINAL INSPECTION REPORT

### New Well Permit Cancelled

MAVERICK ENERGY GROUP, LTD,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-3305134, issued to MAVERICK ENERGY GROUP, LTD, and listed below has been received in this office. The permit has been cancelled as of 8/25/2015.

A handwritten signature in blue ink, appearing to read 'James Martin'.

James Martin  
Chief

Operator: MAVERICK ENERGY GROUP, LTD  
Operator's Well No: MCCLAIN 1  
Farm Name: MCCLAIN, LARRY E.  
**API Well Number: 47-3305134**  
Date Issued: 08/14/2008

Date Cancelled: 08/25/2015

Promoting a healthy environment.

09/04/2015

GPS YES  NO

DATE STARTED/LOCATION:	API #:	WELL NO.
	47-33-5134	McClain 1
DRILLING COMMENCED:	OPERATOR:	
	Maverick Energy Group LLC	
DATE:	DEPTH:	FARM:
		McClain, Larry E
WATER DEPTHS	COAL DEPTHS	

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

- DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:
  - A. CONSTRUCTION YES  NO  (2 PTS)      B. DRILLING YES  NO  (2 PTS) (4 PTS) \_\_\_\_\_
  - WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES  NO  (4 PTS) (4 PTS) \_\_\_\_\_
  - ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES  NO  (4 PTS) (4 PTS) \_\_\_\_\_

- CONSTRUCTION:
  - ARE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?
    - A. DITCHES 1  2  3  4  (PTS)
    - B. CROSS DRAINS 1  2  3  4  5  (PTS)
    - C. BARRIERS 1  2  3  4  5  (PTS)
    - D. CREEK CROSSINGS 1  2  3  (PTS)
    - E. DIVERSION DITCHES 1  2  3  (PTS)
    - F. BARRIERS 1  2  3  (PTS)
  - TEMPORARY SEEDING YES  NO  (10 PTS)      POINTS AVAILABLE FOR QUESTION 4: (33 PTS) \_\_\_\_\_

- HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES  NO  (2 PTS) (2 PTS) \_\_\_\_\_
- IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES  NO  (9 PTS) (9 PTS) \_\_\_\_\_

- RECLAMATION:
  - A. ROADWAY 1  2  3  (PTS)
  - B. LOCATION 1  2  3  (PTS)
  - C. PITS 1  2  3  (PTS)
  - D. PIPELINES 1  2  3  (PTS)
  - E. BANK DIKES 1  2  3  (PTS)
  - F. API INSTALLED YES  NO  (3 PTS)
  - G. EQUIVALE SEEDING MATERIALS 1  2  3  (PTS)
  - H. SEED BED ADEQUATE 1  2  3  (PTS)      POINTS AVAILABLE FOR QUESTION 7: (24 PTS) \_\_\_\_\_

- WAS RECLAMATION COMPLETED WITHIN:
  - 5 MTHS OF TD \_\_\_ 6 PTS ONLY;    4 MTHS OF TD \_\_\_ 12 PTS ONLY;    2 MTHS OF TD \_\_\_ 19 PTS ONLY.
  - MAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS) \_\_\_\_\_

TOTAL MAXIMUM POSSIBLE SCORE OF 99.      TOTAL RECLAMATION SCORE: \_\_\_\_\_

SPECTIONS: Cancel Received

---

AUG 31 2015

1/25/15  
NOT RELEASED

*S. D. Warratt*  
INSPECTOR