



Minimum Error of Closure 1 in 200'

5.625
3.98W

Sources of Elevation Elev. Furbee Well = 1089

- Fracture.....
- New Location.....
- Drill Deeper.....
- Abandonment..... 6-28-73

I, the undersigned, hereby certify that this map is correct to the best of my knowledge and belief and shows all the information required by paragraph 6 of the rules and regulations of the oil and gas section of the mining laws of West Virginia.

Signed: [Signature]
Squares: N E W

Map No.

Company WEST VIRGINIA DEPT. MINES-OIL & GAS DIV.
 Address Charleston, West Va.
 Farm John Haddox
 Tract _____ Acres 192 Lease No. _____
 Well (Farm) No. Two Serial No. _____
 Elevation (Spirit Level) 1153'
 Quadrangle Mannington SC
 County Marion District Mannington
 Engineer [Signature]
 Engineer's Registration No. 1227
 File No. _____ Drawing No. _____
 Date June 23, 1972 Scale 1" = 40p = 660'

STATE OF WEST VIRGINIA
 DEPARTMENT OF MINES
 OIL AND GAS DIVISION
 CHARLESTON

WELL LOCATION MAP

FILE NO. MAR-955 (A)

+ Denotes location of well on United States Topographic Maps, scale 1 to 62,500, latitude and longitude lines being represented by border lines as shown.
 - Denotes one inch spaces on border line of original tracing.

Meson 943A and Mes 955 are ~~entirely~~ different wells. 955 is approximately 1320' south of Mes 943A. The plat on 943A was made in this office from an old South Penn farm map and the topo location is wrong. actually - 943A and 954 ~~are~~ would spot at the same topo location with the 954 topo + correct. Mes 943A was cancelled and re bid and plugged with a corrected plat, and to save (I thought) confusion we used the corrected plat and farm name when we re-advertised and plugged the well.

Marion 943A and Mar 954 are ~~entirely~~ different wells. 955 is approximately 1320' south of Mar 943A. The plat on 943A was made in this office from an old South Penn farm map and the topo location is wrong. actually - 943A and 954 ~~are~~ would spot at the same topo location with the 954 topo + correct. Mar 943A was cancelled and re bid and plugged with a corrected plat, and to save (I thought) confusion we used the corrected Plat and farm name when we readvertised and plugged the well.