

STATE OF WEST VIRGINIA DEPARTMENT OF MINES

1106 - 1883

OIL AND GAS WELLS DIVISION

On A Cispenson

Permit No. 061-0726

AFFIDAVIT OF PLUGGING AND FILLING WEDEPT. OF MINES

Eastern Asso		East	ern Assoc. Coal	Corp	
	FRATOR OR OWNER	RE. 1, BOX NAME OF WELL OPERATOR			
Fairview, WV	26570	Fairview, WV 26570			
	ADORES		COMPLETE AD	DRESS	
COAL	PERATOR OR OWNER	Augu	St 1,	CATION	19 83
		Batt	elle	CATION	District
Mary Walker	& Garnet Brookover	Mono	ngalia		District
Rt. 1 LEASE	OR PROPERTY OWNER		ngaria		County
Fairview, WV		Well N	To. EACC-F2-296		
	ADDRESS		Haught & Walk	or	
			nadgiit d walk		Farm
STATE INSPECTOR	Supervising Plugging W	illiam B	losser	-	-
	AFFIC	AVIT			
STATE OF WEST	VIRGINIA.	7711			
County of Monor	· · · · · · · · · · · · · · · · · · ·			•	
Ray Sm	i +h	M	olssin Baar		
	orn according to law depose	and sow the	elvin Eddy		
plugging and filling	oil and gas malls and many	and say to	at they are experie	nced in the	work of
" on obergior, and I	oil and gas wells and were emparticipated in the work of plu	dding and	#11i AL - L	44	,
was commenced on	the 13th day of July	Rems and	ming the above v	well, that s	aid work
and filled in the following	lowing manner:		$\frac{19}{1}$, and that the	he well was	s plugged
AND OR ZONE RECORD			II		
PORMATION	FILLING MATERIAL		PLUGS USED		SING
			SIZE & KIND	CSG	CSG
				PULLED	LEFT IN
Left old 8" cas	a depth of 1320'.			Set a to	al of 909
Left old 8" cas	ing in well from 1160' to)		Set a to	tal of 909 asing star
Left old 8" cas	ing in well from 1160' to get out).)		Set a to	tal of 909 asing star
Left old 8" cas 1320' (couldn't Ran 4½" casing	ing in well from 1160' to get out). to 1320'. Pumped 25 bags			Set a to	tal of 909 asing star
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation.			Set a to of $4\frac{1}{2}$ " c at the s	tal of 909 asing star urface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of	lur i ng c	eaning because o	Set a to of 4½" c at the s	tal of 90 asing star urface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of f gel, 400 bags of lime,	lur i ng c	eaning because of gel flakes, an	Set a to of 4½" c at the s	tal of 90 asing star urface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of of paper mulch	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation.	luring c 2 bags	of gel flakes, an	Set a to of 4½" c at the s	tal of 90 asing starurface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of of paper mulch Pumped 150 bag	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement.	during c 2 bags	of gel flakes, an	Set a to of 4½" c at the s	tal of 900 asing star
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of paper mulch Pumped 150 bags Pumped 200 bags	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement.	during c 2 bags	of gel flakes, an	Set a to of 4½" c at the s	tal of 90 asing starurface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of of paper mulch Pumped 150 bags Pumped 200 bags surface.	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Proof portland cement and 15	during c 2 bags	of gel flakes, an	Set a to of 4½" c at the s	tal of 90 asing starurface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of of paper mulch Pumped 150 bags Pumped 200 bags surface.	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement.	during c 2 bags	of gel flakes, an	Set a to of 4½" c at the s	tal of 90 asing starurface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of of paper mulch Pumped 150 bags Pumped 200 bags surface.	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Proof portland cement and 15	during c 2 bags	of gel flakes, an	Set a to of 4½" c at the s	tal of 900 asing star
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of of paper mulch Pumped 150 bags Pumped 200 bags surface.	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Proof portland cement and 15	during c 2 bags	of gel flakes, an	Set a to of 4½" c at the s	tal of 900 asing star
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of of paper mulch Pumped 150 bags Pumped 200 bags surface. Set latch down	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Proof portland cement and 15	during c 2 bags	of gel flakes, an	Set a to of 4½" c at the s	tal of 909 asing star urface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of paper mulch Pumped 150 bag Pumped 200 bags surface. Set latch down	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Prof portland cement and 1!	during c 2 bags	casing to a de of Chem-comp cem	Set a to of 4½" c at the s f caving, d 1 bag th of 90 ent to the	asing starurface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of of paper mulch Pumped 150 bags Pumped 200 bags surface. Set latch down COAL SEAMS Pittsburgh 782	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Prof portland cement and 1!	during c 2 bags	casing to a de of Chem-comp cem	Set a to of 4½" c at the s f caving, d 1 bag th of 90 nt to the	asing star urface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of paper mulch Pumped 150 bags Pumped 200 bags surface. Set latch down COAL SEAMS Pittsburgh 782	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Prof portland cement and 1!	during c 2 bags ulled 44 50 bags	casing to a de of Chem-comp cem	Set a to of 4½" c at the s of 4½" c at the s of 1 bag of	asing star urface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of paper mulch Pumped 150 bag Pumped 200 bags surface. Set latch down	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Prof portland cement and 1!	during c 2 bags	casing to a de of Chem-comp cem	Set a to of 4½" c at the s f caving, d 1 bag th of 90 nt to the	asing staurface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of of paper mulch Pumped 150 bags Pumped 200 bags surface. Set latch down COAL SEAMS Pittsburgh 782	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Prof portland cement and 1!	during c 2 bags ulled 44 50 bags	casing to a de of Chem-comp cem	Set a to of 4½" c at the s of 4½" c at the s of 1 bag of	asing staurface. 9'-3". stop
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of paper mulch Pumped 150 bags Pumped 200 bags surface. Set latch down COAL SEAMS Pittsburgh 782	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Prof portland cement and 1. plug at a depth of 889'. '-787'	during c 2 bags ulled 44 50 bags	casing to a de of Chem-comp cem become comp cem casing to a de of Chem-comp cem casing to a de o	Set a to of 4½" c at the s of 4½" c at the s of 1 bag of	asing star urface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of of paper mulch Pumped 150 bags Pumped 200 bags surface. Set latch down COAL SEAMS Pittsburgh 782	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Prof portland cement and 1. plug at a depth of 889'. '-787'	during c 2 bags ulled 44 50 bags	casing to a de of Chem-comp cem become comp cem casing to a de of Chem-comp cem casing to a de o	Set a to of 4½" c at the s of 4½" c at the s of 1 bag of	asing star urface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of paper mulch Pumped 150 bags Pumped 200 bags surface. Set latch down COAL SEAMS Pittsburgh 782	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Prof portland cement and 1!	during c 2 bags ulled 44 50 bags	casing to a de of Chem-comp cem become comp cem casing to a de of Chem-comp cem casing to a de o	Set a to of 4½" c at the s of 4½" c at the s of 90 of the of 90 of the to the with a 2" pipe we alded to	asing star urface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of of paper mulch Pumped 150 bags Pumped 200 bags surface. Set latch down COAL SEAMS Pittsburgh 782 And that the work of July	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Proof portland cement and 1! plug at a depth of 889'. '-787' f plugging and filling said we 19 83	during c 2 bags ulled 44 50 bags	casing to a de of Chem-comp cem become comp cem casing to a de of Chem-comp cem casing to a de o	Set a to of 4½" c at the s of 4½" c at the s of 90 of the of 90 of the to the with a 2" pipe we alded to	asing star urface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of of paper mulch Pumped 150 bags Pumped 200 bags surface. Set latch down COAL SEAMS Pittsburgh 782	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Proof portland cement and 1! plug at a depth of 889'. '-787' f plugging and filling said we 19 83	during c 2 bags ulled 44 50 bags	casing to a de of Chem-comp cem become comp cem casing to a de of Chem-comp cem casing to a de o	Set a to of 4½" c at the s of 4½" c at the s of 90 of the of 90 of the to the with a 2" pipe we alded to	asing star urface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of of paper mulch Pumped 150 bags Pumped 200 bags surface. Set latch down COAL SEAMS Pittsburgh 782 And further depo	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Proof portland cement and 1. plug at a depth of 889'. '-787' 'plugging and filling said we get a saith not.	during c 2 bags ulled 44 50 bags	casing to a de of Chem-comp cem become comp cem casing to a de of Chem-comp cem casing to a de o	Set a to of 4½" c at the s of 4½" c at the s of 90 of the of 90 of the to the with a 2" pipe we alded to	asing star urface.
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of of paper mulch Pumped 150 bags Pumped 200 bags surface. Set latch down COAL SEAMS Pittsburgh 782 And further depo	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Proof portland cement and 1! plug at a depth of 889'. '-787' f plugging and filling said we 19 83	during c 2 bags ulled 44 50 bags ell was co	casing to a de of Chem-comp cem become comp cem casing to a de of Chem-comp cem casing to a de o	Set a to of 4½" c at the s of 4½" c at the s of 1 bag of	asing star urface. 9'-3". stop with a meta the 2" pi
Left old 8" cas 1320' (couldn't Ran 4½" casing of gel and got Pulled 1138' of Pumped 5 bags of of paper mulch Pumped 150 bags Pumped 200 bags surface. Set latch down COAL SEAMS Pittsburgh 782 And further depo	ing in well from 1160' to get out). to 1320'. Pumped 25 bags circulation. 8" casing (put in hole of gel, 400 bags of lime, Got circulation. s of Chem-Comp cement. Prof portland cement and 1! plug at a depth of 889'. '-787' '-787' f plugging and filling said well, 1983 ments saith not.	during c 2 bags ulled 44 50 bags	casing to a de of Chem-comp cem become comp cem casing to a de of Chem-comp cem casing to a de o	Set a to of 4½" c at the s of 4½" c at the s of 1 bag of	asing star urface.