STATE OF WEST VIRGINIA DEPARTMENT OF ENVIRONMENTAL PROTECTION OFFICE OF OIL AND GAS

AFFIDAVIT OF PLUGGING AND FILLING WELL

AFFIDAVIT SHOULD BE IN TRIPLICATE, one copy mailed to the Department, one copy to be retained by the Well Operator and the third copy (and extra copies if required) should be mailed to each coal operator at their respective addresses.

oodi opoidi	0. 0				
Farm name	: Husk, R	alph Ope	erator Well No.: F2-	572	
LOCATION	l: Elevation:	1 2/13'	Quadrangle:	Blacksville	
LOCATION	District:		County:		
	Latitude:			39 Deg. 42 N	
	Longitude:		Feet West of	80 Deg. 12 M	in. 30 Sec.
Well Type:	OIL X GAS			<u> </u>	
71					
Company:	Eastern Associa	ited Coal LLC	Coal Operator:	Eastern Associate	
	1044 Miracle Ru		or Owner	1044 Miracle Rur	
	Fairview, WV 26	3570		Fairview, WV 265	570
			Coal Operator		
Agent:	Matthew L. Bon	nell	or Owner		
Permit Issu	ed Date: Octobe	r 1, 2015	AFFIDAVIT	Appaier assistant of a model apparent	
ST	ATE OF WEST \	/IRGINIA.	711 1 1 1 2 7 1 7 1 1		
	unty of Mononga				
			T	FLANT	peing first duly sworn
1GAL	y c /hom	and	x Jommy ~	-aa 9 56	eing first duly sworn
according t	o law depose an	d say that they ar	e experienced in the	e work of plugging	and filling oil and gas
wells and were employed by the above named well operator, and participated in the work of plugging and					
filling the above well, and Gayne Knitowski, Oil and Gas Inspector representing the Director, say that said					
work was commenced on the 15th <u>day</u> of <u>November</u> , 2015, and that the well was plugged and filled in the following manner:					
TOTIOWING TO	iailiei.				
TYPE	FROM	ТО	PIPE REM	IOVED	LEFT
	the same of the sa		the state of the s		Drilled with a 6" mill
down to 1,3					
Ran logs w	vith Century Wire	line Services. Ba	sed on the logs the	Pittsburgh coal se	am is 878'-885'. The
well deviated 23.9' at the coal seam. Based on the logs there was no casing in the Pittsburgh coal seam.					
There was 7" casing from 1,020' down to 1,330', which appears to have been ripped while cleaning out					
the well. The 7" casing was perforated by Timco Inc. on 50 foot intervals.					
There is a bottom hole cement plug from 1,380' up to 1,110'. Then they set an expanding cement plug					
from 1,110' to 750'. Then from 750' to surface it was filled with cement. There were 730 sacks of Portland and 150 sacks of expanding cement used to plug the well.					
There were	e 730 sacks of Po	rtiand and 150 sa	icks of expanding ce	ement used to plug	ine well.
Description	of monument: 4	1/2" Pipe with m	etal plate, API #, and	date plugged and	that the work of
plugging ar	nd filling said well	was completed o	n the 14 th day of <u>De</u>	cember 2015.	
			0 0-1		
An	d further depone	nts saith not. <u>X</u>	Dary (Mo	mes	
NEST TO	OFFICIAL SEAL	7 7	ommis a	SIL On	
R E	NOTARY PUBLIC	. (_	anomy of a	any y	
STATE OF WEST VIRGINIA					
Sworn and subscribe before me this					
3	AROOMHNISSION OXP	North Comment of the	7 134625		
Notary Public					
Oil and Gas Inspector: Lam D Ky ty 12/16/2015					