

LATITUDE 39° 40' 00"

80° 50' 00"

LONGITUDE

75'

7'5 OGIS topo location

| | | | |
|----------|--------------|---------|--------------|
| 7.5' 10C | <u>1.635</u> | 15' 10C | <u>1.635</u> |
| | <u>1.270</u> | (calc.) | <u>1.270</u> |

A 1467 on Equitans

Company _____

Farm _____

Quad Osage

County Monongahela

District Clay

WELL LOCATION MAP

File No. 061-38A

#228 - 100 sq ft

06-10-17

Plot of the Location of Well No. 1 of the
 Washington Oil Co. at Crofters Pa on the
 Martha A. Miller Farm, consisting of 115 Acres
 Located in Clay District, Monongalia County,



Engineer's Certificate

I, the undersigned, hereby certify that this map and plan
 was drawn to the information in the field of my knowledge and
 belief, required by the act and regulations of the State of West Virginia.

J. B. [Signature]

PROPOSED MANNER OF PLUGGING AND FILLING WELL

(ISSUED BY STATE AND REGULATIONS)

WEST VIRGINIA DEPARTMENT OF MINES

OIL AND GAS DIVISION

WORK ORDER

Well to be plugged and filled as follows: WORK ORDER AS REVISED BY DEPARTMENT OF MINES FOR D. T. Miller Well No. 1.

From the point 1740' from surface
Set wood plug 1740' to 1744.5'
Cement 1744.5' to 1746' sealing hole completely.
Pull a 1/8" casing.
Set bridge at 1800' - 20' below Salt Sand.
Mud or clay 1800' to 1845' - 20' above Salt Sand.
Set wood plug 1845' to 1849'
Cement 1849' to 1850' sealing hole completely.
Set bridge at 1170' - 20' below Big Bushard Sand.
Mud or clay 1170' to 1200' - 20' above Little Bushard
Set wood plug 1200' to 1205'
Cement 1205' to 1206'
Pull a 1/8" casing.
Set bridge or plug at or below 601' - 20' below Pittsburgh Coal.
Cement 601' to 602' - 20' above Pittsburgh Coal.
Mud or clay 601' to 617' - 20' below Westvickley Coal.
Cement 617' to 620' - 20' above Sprickley Coal.
Mud or clay 620' to 624' - 20' below Native Coal.
Cement 624' to 107' - 20' above native coal.
Mud or clay 107' to surface and
spread each marker as is described in Rule 18, 1921 Regulations.
All to be done in a workmanlike manner.

To the Department of Mines,
Coal Office or Operator,
Name or Property Owner.

Conditions:

This "work order" is submitted for your approval and acceptance and unless notified of your disapproval or non-acceptance, the undersigned will proceed with the plugging and filling of said well in the above described manner on the date stated in the course of business to plug and abandon the well and on opposite side of this date.

Very truly yours,

Revised work order submitted by Department of Mines.

W.D. Quinn

No objection here has been filed by the said owner or said operator, or any available official here or person in charge of the same, to the above described plugging and filling of the well in the manner above described on the date stated in the course of business to plug and abandon the well and on opposite side of this date.

Sept 1921

DEPARTMENT OF MINES

[Signature]

V

NOTICE OF INTENTION TO PLUG AND ABANDON WELL
(Governed by Section 4, Article 4, Chapter 20 of the Code)
WEST VIRGINIA DEPARTMENT OF MINES
OIL AND GAS DIVISION

To the Department of Mines,
 Charleston, W. Va.

Martha A. Miller, Agent

and authorized to sign orders

ERT-Sargantown, T. Va.

address

and authorized to sign orders

and authorized to sign orders

address

Washington Oil Company

name of well owner

Box 41, Cove, W. Va.

complete address

September 18, 1931

WELL TO BE ABANDONED

Clay State

Emmonsia County

Vol No. 1

D. T. Miller Agent

Conditions —

The undersigned well operator is about to abandon the above described well and will commence the

work of plugging and abandoning said well on the 18 day of September, 1931, (which date shall not be less than five days after the day on which this notice is mailed to you, or in due season should be received by the Department of Mines).

This notice is given you in order that your respective representatives may be present at the plugging and filling of said well. You are further notified that whether you are represented or not represented the undersigned will proceed on that date, or shortly thereafter, to plug and fill said well in the manner required by Section 20, Article 4, Chapter 20 of the Code and give in detail on the reverse side of this notice, in "Well Order."

This notice is being mailed by registered mail to each of you at the above addresses on the above date.

Very truly yours,

Washington Oil Company

Agent for ERT-Sargantown, T. Va.

NOTE: Upon the abandonment of a well defined under the laws of West Virginia, the operator is to be responsible for the removal of the wellhead and casing, and the filling of the well with cement or other suitable material, and the maintenance of the well in a safe condition. The operator is also to be responsible for the removal of the wellhead and casing, and the filling of the well with cement or other suitable material, and the maintenance of the well in a safe condition. The operator is also to be responsible for the removal of the wellhead and casing, and the filling of the well with cement or other suitable material, and the maintenance of the well in a safe condition.

2773 N.C. 100, 100000
 100000