WELL PLUGGING INSPECTION & RELEASE FORM

PLUGGING COMMENCED 9-11-19 OPERATOR: HG ENERGY, LLC PLUGGING COMPLETED 9-11-19 FARM: DICKINSON FUEL CO				
	AL PERMISSION ON	FARM: DICKINSON FUEL CO. WELL NO: 1		
1.	IS COAL BEING MINED IN THE AREA?	YE	s no	N/A
2.	THE THE THE THE THE TREE TREE TREE TREE			
	A. BOTTOM HOLE PLUGGED B. 100' PLUGS C. LATEX PLUGS USED FOR D. PROPER PLUGS THROUGH E. PROPER PLUGS SET TO P F. PROPER AMOUNT OF GEL	COAL SEAMS YE	S NO N/A	N/A N/A N/A N/A
_	TYPE FROM	TO P	IPE REMO	VED
	ement 1500 ement 858 ement 650	1268 70° 158 550	59-20	पर्भ
-6	ement 340 ement 248	290		
3.	WERE ALL CHANGES APPROVED BY INS	PECTOR?	YES	NO
4.	WAS THE EQUIPMENT USED FOR PULLIS AND RIGGED TO PULL 150% OF THE HITO BE PULLED?	NG CASING PROPERLY SIZED EAVIEST STRING OF PIPE EXPECTEI	YES	NO
5.	DID THE OPERATOR GIVE THE INSPEC	TOR PROPER NOTICE?	(YES	NO
6.	WERE ACCURATE PLUGGING RECORDS KI	EPT BY THE OPERATOR?	(YES)	NO
7.	WAS A PROPER MONUMENT SET WITH A	PI NUMBER ATTACHED?	YES	NO
8.	DID WELL SITE AND ACCESS ROAD MEI REQUIREMENTS? A. RECLAIMED C. MULCHED E. SEEDED G. PIT BACKFILLED O-22-19	B. FENCES REPLACED D. PROPER DRAINAGE F. ALL EQUIPMENT REMOVED MY W	NES NES NES	NO NO NO
	DATE RELEASED	INSPECTOR'S SIGNATURE		
	 -	,	RECEI	VED

RECORD ALL VISITS TO THIS WELL ON PAGE 2

Office of Oil and Gas

OCT 2 2 2019

El Eustin 817

DATE	VISITS
9.30-19	REDN HOLE - CIEN DECIMENTE DOUCESS Tried to March down
	Rig ON Oble - Crew Beginning process tried to break down Well herd fell off from Rust May run hog hater Fluid is at 500 ft in 7" C59
9-5-19	Mixed 18 BBL CEL, Mixed 5 BBL Cement (405KS) Displaced With 2.7 BBL HZO - Well Did NOT CIRCUlate
9-9-18	The ged place of 1368 + t, successful to cut 1" Inch & pull trip & reset bottom plug with 155Ks to tup off
9.10-19	DET Plug 1368 to 1268 t and 858 to 758 to
9-12-19	Set Monument with 50 SKs cont filled gll vious
10-2296	Released Site
· ·	
·	

RECEIVED
Office of Oil and Gas

OCT 22 2019