

west virginia department of environmental protection

Office of Oil and Gas 601 57th Street SE Charleston, WV 25304 (304) 926-0450 (304) 926-0452 fax Earl Ray Tomblin, Governor Randy C. Huffman, Cabinet Secretary www.dep.wv.gov

PERMIT MODIFICATION APPROVAL

February 21, 2014

CHESAPEAKE APPALACHIA, L.L.C. POST OFFICE BOX 6070 CHARLESTON, WV 25362

Re: Permit Modification Approval for API Number 6900159 , Well #: ROY FERRELL OHI 205F Modified casing

Oil and Gas Operator:

The Office of Oil and Gas has reviewed the attached permit modification for the above referenced permit. The attached modification has been approved and well work may begin. Please be reminded that the oil and gas inspector is to be notified twenty-four (24) hours before permitted well work is commenced.

Please call James Martin at 304-926-0499, extension 1654 if you have any questions.


Sincerely,

Gene Smith

Regulatory/Compliance Manager

Office of Oil and Gas







Danielle Southall Regulatory Analyst II

November 15, 2013

Ms. Laura Cooper Office of Oil & Gas 601 57th Street Charleston, WV 25304

Re: Modification for Roy Ferrell OHI 205H API# 47-069-00159

Dear Ms. Cooper:

Enclosed please find a modification request for the above captioned well. We would like to modify the 5 ½" casing, for directional work only. The bottom hole will not move. This well is situated on the Ferrell property, in Triadelphia District, Ohio County, West Virginia.

If you have any questions or require additional information, please contact me at 304-517-1416 ext 86024.

Sincerely

Dee Southall

Enclosure(s)

RECEIVED
Office of Oil and Gas

NOV 1 8 2013

VAV Department of Environmental Protection

STATE OF WEST VIRGINIA DEPARTMENT OF ENVIRONMENTAL PROTECTION, OFFICE OF OIL AND GAS W.VA. CODE §22-6A - WELL WORK PERMIT APPLICATION

Well Operator: Chesapeake Appalachia, LLC		1	1	•
	494477557	69- Ohio	7- Triadelphia	648- Valley Grove
-	Operator ID	County	District	Quadrangle
Operator's Well Number: Roy Ferrell OHI 205H	ν	Vell Pad Nam	e: Roy Ferrall OH	l Pad
•			-	
	evation, proposed	post-construc	uon: 1	1196'
Well Type: (a) Gas Oil				
Other (b) If Gas: Shallow	D			*
** * * * * * * * * * * * * * * * * * * *	Deep			1
Horizontal	· · · · · · · · · · · · · · · · · · ·	}-	78K IIII.	t12013
Existing Pad? Yes or No:		r	70'	
	ad Thiokassas	d Apposisted	Drangues/al-	
Proposed Target Formation(s), Depth(s), Anticipate Target formation-Marcellia, Target top TVD- 6630', Target base TVD- 6690', Anticipate				
Proposed Total Vertical Depth: 6,660				
Formation at Total Vertical Depth: Marcellus				
Proposed Total Measured Depth: 17,100				
Approximate Fresh Water Strata Depths: 34	0'			
	m a water well-4000' WNV	V of the pad		
) Approximate Saltwater Depths: 800				
Approximate Coal Seam Depths: 691	1			
 Approximate Depth to Possible Void (coal mine, less land contain coal seams tributary or adjacen 		691' void aband	loned mine	
n lang igan contain coal ceame tribiliary or goldcen		N/A		
•	it to, active mine?	No.		
Describe proposed well work:			ce basket above and	below
,	e Marcellus, **If we should e	encounter a vold, pla		
Describe proposed well work: Drill and attimutate any potential zones between and including the Benson to the	e Marcellus. **If we should e Run cosing not less than 20	encounter a vold, pla		
Drie and attriuiate any potential zones between and including the Benson to the void area - balance cement to bettom of void and grout from basket to surface. ("If freshwater is encountered deeper than anticipated it must be protected, set	e Marcellus. **If we should e Run casing not less than 20 casing 50' below and cts)	encounter a vold, pla		
Drill and attriutate any potential zones between and including the Benson to the wold area - balance coment to bottom of void and grout from basket to surface. ("If freshwater is encountered deeper than anticipated it must be protected, set") Describe fracturing/stimulating methods in detail:	e Marcellus. **If we should e Run casing not less than 20 casing 50' below and cts)	ncounter a vold, pla ' below vold nor mor	e than 50' below void	
Drie and stimulate any potential zones between and including the Benson to the void area - balance cement to bettom of void and grout from basket to surface. ("If freshwater is encountered deeper than anticipated it must be protected, set	e Marcellus. **If we should a Run casing not less than 20 casing 50' below and cts) and chemical additives at a high	ncounter a vold, pla below vold nor mor	e than 50' below void med in stages with the p	i. Jug and port method along
Describe proposed well work: Drill and attinutate any potential zones between and including the Benson to the wold area - balance coment to bettom of void and grout from basket to surface. ("If freshwater is encountered deeper than anticipated it must be protected, set") Describe fracturing/stimulating methods in detail: Well will be perforated within the target formation and stimulated with a stury of water, sand.	e Marcellus. **If we should e Run casing not less than 20 casing 50' below and cts) and chemical additives at a high on. All stage plugs are then	rate. This wif be perforded out and the w	e than 50' below void med in stages with the p rell is flowed back to	i. Jug and port method along
Drie and attriutate any potential zones between and including the Benson to the void area - balance coment to bettom of void and grout from basket to surface. ("If freshwater is encountered deeper than anticipated it must be protected, set Describe fracturing/stimulating methods in detail: Well will be perforated within the target formation and stimulated within the target formation to the wellbore until the entire lateral has been stimulated within the target formation.	e Marcellus. **If we should e Run casing not less than 20 casing 50' below and cts) and chemical additives at a high on. All stage plugs are then	rate. This wif be perforded out and the w	e than 50' below void med in stages with the p rell is flowed back to	i. Jug and port method along
Drill and attinutate any potential zones between and including the Benson to the void area - balance coment to bottom of void and grout from basket to surface. ("If freshwater is encountered deeper than anticipated it must be protected, set Describe fracturing/stimulating methods in detail: Wet will be perforated within the target formation and stimulated with a stury of water, sand, the wellbore until the entire lateral has been stimulated within the target formation. The well is produced through surface facilities consisting of high pressure produced.	e Marcellus. **If we should e Run casing not less than 20 casing 50° below and cts) and chemical additives at a high ion. All stage plugs are then uction units, vertical separati	rate. This wif be performed and the water an	e than 50' below void med in stages with the p rell is flowed back to	i. Jug and port method along
Drie and attinutate any potential zones between and including the Benson to the void area - balance cement to bettom of void and grout from basket to surface. ("If freshwater is encountered deeper than anticipated it must be protected, set Describe fracturing/stimulating methods in detail: Wet will be perforated within the target formation and stimulated with a stury of water, sand, the wellhore until the entire lateral has been stimulated within the target formation. The well is produced through surface facilities consisting of high pressure produced. Total area to be disturbed, including roads, stockp	a Marcellus. **If we should a Run casing not less than 20 casing 50' below and cts) and chemical additives at a high on. All stage plugs are then untion units, vertical separati pile area, pits, etc,	rate. This wif be performed and the water an	e than 50' below void med in stages with the p real is flowed back to bil storage tanks.	Jug and port method along
Drill and stimulate any potential zones between and including the Benson to the void area - balance coment to bettom of void and grout from basket to surface. ("If freshwater is encountered deeper than anticipated it must be protected, set ("I freshwater is encountered deeper than anticipated it must be protected, set ("I freshwater is encountered deeper than anticipated it must be protected, set ("I freshwater is encountered deeper than anticipated it must be protected, set ("I freshwater is encountered deeper than anticipated it must be protected, set ("I freshwater is encountered deeper than anticipated it must be protected, set ("I freshwater is encountered deeper than anticipated it must be protected, set ("I freshwater is encountered deeper than anticipated it must be protected, set ("I freshwater is encountered deeper than anticipated it must be protected, set ("I freshwater is encountered deeper than anticipated it must be protected, set ("I freshwater is encountered deeper than anticipated it must be protected, set ("I freshwater is encountered deeper than anticipated it must be protected, set ("I freshwater is encountered deeper than anticipated it must be protected, set	a Marcellus. **If we should a Run casing not less than 20 casing 50' below and cts) and chemical additives at a high on. All stage plugs are then untion units, vertical separati pile area, pits, etc,	rate. This wif be performed and the water an	e than 50' below void med in stages with the p real is flowed back to bil storage tanks.	Jug and port method along
Drie and attinutate any potential zones between and including the Benson to the void area - balance cement to bettom of void and grout from basket to surface. ("If freshwater is encountered deeper than anticipated it must be protected, set Describe fracturing/stimulating methods in detail: Wet will be perforated within the target formation and stimulated with a stury of water, sand, the wellhore until the entire lateral has been stimulated within the target formation. The well is produced through surface facilities consisting of high pressure produced. Total area to be disturbed, including roads, stockp	a Marcellus. **If we should a Run casing not less than 20 casing 50' below and cts) and chemical additives at a high on. All stage plugs are then untion units, vertical separati pile area, pits, etc,	rate. This wif be performed out and the world number and the world numbe	med in stages with the preil is flowed back to bil storage tanks.	iug and port method along surface.
Drill and attinutate any potential zones between and including the Benson to the void area - balance coment to bettom of void and grout from basket to surface. ("If freshwater is encountered deeper than anticipated it must be protected, set Describe fracturing/stimulating methods in detail: Well will be perforated within the target formation and stimulated with a sturry of water, sand, the wellhore until the entire lateral has been stimulated within the target formation. The well is produced through surface facilities consisting of high pressure produced. Total area to be disturbed, including roads, stockp	a Marcellus. **If we should a Run casing not less than 20 casing 50' below and cts) and chemical additives at a high on. All stage plugs are then untion units, vertical separati pile area, pits, etc,	rate. This wif be performed out and the word units, water and the word acres):	med in stages with the pred is flowed back to bil storage tanks.	iug and perf method along surface.
Drie and stimutate any potential zones between and including the Benson to the void area - balance cement to bettom of void and grout from basket to surface. ("If freshwater is encountered deeper than anticipated it must be protected, set Describe fracturing/stimulating methods in detail: West will be perforated within the target formation and stimulated within the target formation. The well is produced through surface facilities consisting of high pressure produced. Total area to be disturbed, including roads, stockp	a Marcellus. **If we should a Run casing not less than 20 casing 50' below and cts) and chemical additives at a high on. All stage plugs are then untion units, vertical separati pile area, pits, etc,	rate. This wif be performed out and the word units, water and the word acres):	med in stages with the preil is flowed back to bil storage tanks.	iug and perf method along surface.
Dris and stimutate any potential zones between and including the Benson to the void area - balance coment to bottom of void and grout from basket to surface. ("If freshwater is encountered deeper than anticipated it must be protected, set Describe fracturing/stimulating methods in detail: Wed will be perforated within the larget formation and stimulated with a sturry of water, sand, the wellbore until the entire lateral has been stimulated within the target formation. The well is produced through surface facilities consisting of high pressure produced. Total area to be disturbed, including roads, stockp	a Marcellus. **If we should a Run casing not less than 20 casing 50' below and cts) and chemical additives at a high on. All stage plugs are then untion units, vertical separati pile area, pits, etc,	rate. This will be performed out and the word units, water and continued out.	med in stages with the pred is flowed back to bil storage tanks. 11 RECEIVED of Oil and	iug and perf method along surface.
Drie and attinutate any potential zones between and including the Benson to the void area - balance cement to bettom of void and grout from basket to surface. ("If freshwater is encountered deeper than anticipated it must be protected, set Describe fracturing/stimulating methods in detail: Wet will be perforated within the target formation and stimulated with a stury of water, sand, the wellhore until the entire lateral has been stimulated within the target formation. The well is produced through surface facilities consisting of high pressure produced. Total area to be disturbed, including roads, stockp	a Marcellus. **If we should a Run casing not less than 20 casing 50' below and cts) and chemical additives at a high on. All stage plugs are then untion units, vertical separati pile area, pits, etc,	rate. This will be performed and the warmen and the	med in stages with the pred is slowed back to oil storage tanks. 11 RECEIVED of Oil and OV 1 8 2013	tug and perf method atong surface.
Drill and attinutate any potential zones between and including the Benson to the void area - balance coment to bettom of void and grout from basket to surface. ("If freshwater is encountered deeper than anticipated it must be protected, set Describe fracturing/stimulating methods in detail: Well will be perforated within the target formation and stimulated with a sturry of water, sand, the wellhore until the entire lateral has been stimulated within the target formation. The well is produced through surface facilities consisting of high pressure produced. Total area to be disturbed, including roads, stockp	a Marcellus. **If we should a Run casing not less than 20 casing 50' below and cts) and chemical additives at a high on. All stage plugs are then untion units, vertical separati pile area, pits, etc,	rate. This wif be performed an units, water and continued and the water and continued	med in stages with the pred is flowed back to oil storage tanks. 11 RECEIVED of Oil and OV 1 8 2013	ing and perf method atong surface.
Drill and attinuiate any potential zones between and including the Benson to the void area - balance cement to bettom of void and grout from basket to surface. ("If freshwater is encountered deeper then anticipated it must be protected, set Describe fracturing/stimulating methods in detail: Wet will be perforated within the target formation and stimulated with a stury of water, send, the weithore until the entire lateral has been stimulated within the target formation. The weil is produced through surface facilities consisting of high pressure produced. Total area to be disturbed, including roads, stockp	a Marcellus. **If we should a Run casing not less than 20 casing 50' below and cts) and chemical additives at a high on. All stage plugs are then untion units, vertical separati pile area, pits, etc,	rate. This wif be performed an units, water and continued and the water and continued	med in stages with the pred is flowed back to oil storage tanks. 11 RECEIVED of Oil and OV 1 8 2013	ing and perf method atong surface.
Drill and attinuiate any potential zones between and including the Benson to the void area - balance cement to bettom of void and grout from basket to surface. ("If freshwater is encountered deeper then anticipated it must be protected, set Describe fracturing/stimulating methods in detail: Wet will be perforated within the target formation and stimulated with a stury of water, send, the weithore until the entire lateral has been stimulated within the target formation. The weil is produced through surface facilities consisting of high pressure produced. Total area to be disturbed, including roads, stockp	a Marcellus. **If we should a Run casing not less than 20 casing 50' below and cts) and chemical additives at a high on. All stage plugs are then untion units, vertical separati pile area, pits, etc,	rate. This wif be performed an units, water and continued and the water and continued	med in stages with the pred is flowed back to oil storage tanks. 11 RECEIVED of Oil and OV 1 8 2013	tug and perf method atong surface.

20)

CASING AND TUBING PROGRAM

ТҮРЕ	Size	New or Used	Grade	Weight per ft.	FOOTAGE: For Drilling	INTERVALS: Left in Well	CEMENT: Fill -up (Cu, Ft.)
Conductor	20"	New	J-55	94#	100*	100'	стѕ
Fresh Water	13 3/8"	New	J-55	54.5#	740*	740'	690 SX/CTS
Coal	9 5/8"	New	J-55	40#	2210'	2210'	860 SX/CTS
Intermediate	7"	New	P-110	20#	If Needed	If Needed	If Needed/As Needed
Production	5 1/2"	New	P-110	20#	16,500'	17,100	Lead 988 sx Tail 2442 sx/100' inside Intermediate
Tubing	2 3/8"	New	N-80	4.7#	Арргох. 7,329'	Approx. 7,329'	
Liners							

KDK 11/11/2013

TYPE	Size	Wellbore Diameter	Wall Thickness	Burst Pressure	Cement Type	Cement Yield
Conductor	20*	30*	0.25*	2120	15.6 ppg	1.19/50% Excess
Fresh Water	13 3/8"	17.5"	0.380	2740	15.6 ppg	1.19/50% Excess
Coal	9 5/8"	12 1/4"	0.395	3950	15,6 ppg	1.19/50% Excess
Intermediate	7	8 3/4"	.0317	4360	15.6 ppg	1.19/50% Excess
Production	5 1/2*	8 3/4"	0.361	12360	15.6 ррд	1.20/15% Excess
Tubing	2 3/8*	4.778*	0.190			
Liners						


PACKERS

Kind:	10K Arrowset AS1-X	
Sizes:	5 1 <i>1</i> 2"	
Depths Set:	Approx. 6,197 ¹	On PACE

Office of Oil and Gas

NOV 1 82013

Environmie mai Protection 02/28/2014



69-00159 MOD

