


NOT LOCATED

Plat of the location of Well No. 1 of Frank Golden of Tanner, West Virginia, on the G. W. & Letitia Miller lot consisting of 72 square rods, located at Tanner, in DeKalb District, Gilmer County, West Virginia.

Gil-18-A



Engineers Certificate.

I, the undersigned do hereby certify that this map is correct and shows all the information to the best of my knowledge and belief, required by the oil and gas section of the Mining Laws of West Virginia.

Casa V. Cooper
Engineer.

Acknowledged before me a Notary Public this the 4 day of March, 1931.

My commission expires W. A. Moore
Oct 8 1931

Frank Golden Company
Tanner Address
NO 2

COMPLETION DATA SHEET
NO. 2
FORMATION RECORD

Name	Color	Character	Oil, Gas or Water	Top	Bottom	Thickness	Total Depth	Remarks
Mayon	White	Hard.	Oil	1543	1592	49	15935	
Mil-18-A								

Well was shot with 125 lbs. shot. well was shot at 1548 to 1592

Produced fresh water at 250 feet; fresh water at

Well was producing 100 bbls/day

WEST VIRGINIA DEPARTMENT OF MINES

Oil and Gas Section

PRELIMINARY DATA SHEET NO. 1

File No. Oil-18-A Well No. 1
Company, of Frank Golden
on the BA & Letessia Miller Farm Lot

containing 72 sq RD Acres. Location
District, in Decah - Bitter County, West Virginia

The surface of the above tract is owned in fee by BA & Letessia Miller
of Tanner A V 3 address, and the mineral rights are owned by
BA & Letessia Miller of Tanner A V 3

The oil and gas privileges are held under lease by the above named company, and this well is drilled under
permit No. None issued by the West Virginia Department of Mines, Oil and Gas Section.

Well Drilled in year of 19 22

Elevation of surface at top of well, 800 ft spirit barometric

The number of feet of the different sized casings used in the well.

<u>16</u> feet	<u>1 5/8</u> size Wood conductor
feet <u>1540</u> size, cog <u>6-4</u>	feet _____ sized cog
feet _____ size, cog _____	feet _____ sized cog
feet _____ size, cog _____	feet _____ sized cog
<u>None</u> packer of _____	size, set at _____
_____ packer of _____	size, set at _____
<u>no</u> in casing perforated at _____	feet to _____ feet
_____ in casing perforated at _____	feet to _____ feet

Coal was encountered at None feet; thickness _____ inches, and at _____ feet, thickness _____ inches; and at _____ feet, thickness _____ inches

Liners were used as follows: (Give details) None

Date _____

NOTICE OF INTENTION TO PLUG AND ABANDON WELL
(REQUIRED BY SECTION 9, CHAPTER 86, ACTS 1929)
WEST VIRGINIA DEPARTMENT OF MINES
OIL AND GAS SECTION

TO THE DEPARTMENT OF MINES,
Charleston, W. Va.

Frank Galden
NAME OF WELL OPERATOR

COAL OPERATOR *None*

Panner NVA
COMPLETE ADDRESS

ADDRESS

Probably April 10, 1931
WELL TO BE ABANDONED

COAL OPERATOR

Desob District

ADDRESS

Silver County

COAL OPERATOR

Well No. *1*

ADDRESS

SA x Leticia Miller Farm

Gentlemen:—

The undersigned well operator is about to abandon the above described well and will commence the work of plugging and abandoning said well on the *in April* day of *Probably 10*, 19*31*, (which date shall be not less than five days after the day on which this notice so mailed is received, or in due course should be received by the Department of Mines).

This notice is given you in order that your respective representatives may be present at the plugging and filing of said well. You are further notified that whether you are represented or not represented the undersigned will proceed on that date, or shortly thereafter, to plug and fill said well in the manner required by law.

This notice is being mailed by registered mail to each of you at the above addresses on the above date.

Very truly yours,

Frank Galden
Well Operator.

NOTE: Upon the abandonment of all wells drilled prior to June 1, 1929, a plat prepared by a competent engineer, showing the district and county in which the tract of land is located, the name and acreage of same, the names of the owners of adjacent tracts, and the location of the about to be abandoned well, determined by survey.

April 10, 1931

Mr. Frank Holden
Tanner, W. Va.

Dear Sir:

Regarding the plunging of your No. 1 well on the G. W. & Letitia Miller Farm, DeKalb District, Gilmer County, would advise that owing to the limited information you give in the log of the well, we recommend that you plug and fill it as follows:

Set a wood plug at the top of the Maxton Sand, at the bottom of your 6 5/8 inch casing as a means of bridging the hole at that point; fill the hole with clay 20 feet; set M & F wood plug and fill with mud or clay 20 feet on top of this plug; shoot casing off and remove the same; fill with mud or clay to a point below salt sand at approximately 1448 feet; set plug and fill with mud or clay to 1260 feet or 20 feet above Salt Sand; set plug and fill with mud or clay to 768 feet or 30 feet below the Big Dunkard, set plug and fill with mud or clay to 703 feet and set plug; fill with mud or clay to surface and place marker as required by Rule 6.

This is the manner in which the law required that the sands be protected.

Yours very truly,

STATE DEPARTMENT OF MINES
Oil and Gas Division

By: _____

LWB:g