

47-043-03572 WS May #501 Permitted - 4/26/2017

This well was never drilled. This well was permitted as part of the Griffithsville 2017 drilling program. That development was redesigned in 2018 and some well numbers were reused in the subsequent drilling program. The No.501 was reused as Oliver Hill #501 (47-043-03575), permitted 2/09/18. Oliver Hill No.501 was drilled and completed 6/16/18. When filing the WR-34 for Oliver Hill #501, the field foreman inadvertently used the API number for the originally permitted No.501 (WS May 501 47-043-03572). As shown on the WR-34, the pit fluid was reused in drilling WS May No.502 (47-043-03577). The WR-34 Pit Fluid Disposal Record explains that the Oliver Hill #501 and WS May #500 shared a common drill pit. (See reclamation drawing attached for reference.)

03/29/2024


Reclamation Plan For:

W.S. May No. 500 Oliver Hill No. 501

Oliver Hill
Lease

D. Arthur Raybourn
& Marjorie Raybourn (L.E.)
- Surface

W.S. May
Lease
David Adkins
- Surface



Notes:

- REQUESTED PERMIT IS FOR DRILLING OF NEW WELL.
- ALL ACCESS ROADS ARE EXISTING AND WILL BE MAINTAINED TO WVDEP STANDARDS.
- STOCKPILE TOPSOIL FOR RE-DRESSING LOCATION DURING RECLAMATION
- ALL DISTURBED AREAS WILL BE RE-VEGETATED AS OUTLINED ON FORM WW-9.
- MAINTAIN SEDIMENT BARRIERS AND DRAINAGE STRUCTURES.
- ALL ROAD GRADES <5% EXCEPT AS NOTED.
- LOCATION OF DRILL PIT MAY BE CHANGED BASED ON AS-BUILT CONSIDERATIONS.
- DRAWING NOT TO SCALE.

W.S. May
Lease
David Adkins
- Surface

NOTE
REFER TO THE WVDEP
EROSION AND SEDIMENT CONTROL
FIELD MANUAL VER. MAY 2012 FOR
BMPs CONTROLLING EROSION AND
SEDIMENT FROM SOIL-DISTURBING
OPERATIONS.