API# 47-061-01394-P

STATE OF WEST VIRGINIA DIVISION OF ENVIRONMENTAL PROTECTION OFFICE OF OIL AND GAS

AFFIDAVIT OF PLUGGING AND FILLING WELL

AFFIDAVIT SHOULD BE IN TRIPLICATE, one copy mailed to the Division, one copy to be retained by the Well Operator and the third copy (and extra copies if required) should be mailed to each coal operator at their respective addresses.

marm name: <u>Bett</u>	y Baird	Operator Well No.:_F	2-466	
LOCATION: Elevation District: Latitude	Battelle 8900 Feet South	Quadrangle: Wade County: Mononga of 39 Deg. 40 Min of 80 Deg. 17	111a n. 00 Sec.	
Well Type: OIL X		ofDeg1	Min. Sec.	
<u>1044 M</u> <u>Fairvie</u>	Associated Coal Corp Miracle Run Road W, W. Va. 26570	or Owner <u>1044 M</u>	n Associated Coal liracle Run road ew, W.Va. 26570	<u>C</u> orp.
Agent: Terry O.	<u>Hendersho</u> t	or Owner		······································
Permit Issued Date:	September 8, 2000			
STATE OF WEST County of Monon		AFFIDAVIT		
Jeff Mostut	tler and Craig	Park	being first duly swo	en nanadina ka
and Randall	that they are experienced in the state of th	n the work of plugging and participated in the work and as Inspector repres	and filling oil and gas of plugging and filling enting the Director of	wells and were the above well,
work was commenc and filled in the follo		day of <u>September</u>	20 <u>00,</u> and that the we	ll was plugged
and filled in the follo	FROM TO	day of <u>September</u> ,	20 <u>03,</u> and that the we	was plugged
TYPE Cleaned out to do	FROM TO epth of 1627'	PIPE REMOVED	20 <u>-0</u> , and that the we	was plugged
TYPE Cleaned out to de Logged well gamma Run 1½ tubing to	FROM TO epth of 1627' a Ray, Neutron & 3 Arm 1620 Run 5 sks gel	PIPE REMOVED Caliper 223 sks Portland	LEF	T Control of the cont
TYPE Cleaned out to de Logged well gamma Run I½ tubing to Run 4½" pipe to	FROM TO epth of 1627' a Ray, Neutron & 3 Arm 1620 . Run 5 sks gel	PIPE REMOVED Caliper 223 sks Portland	LEF	was plugged
TYPE Cleaned out to do Logged well gamma Run 1½ tubing to Run 4½" pipe to Pumped Latch down	FROM TO epth of 1627' a Ray, Newtron & 3 Arm 1620 Run 5 sks gel 898 Run 550 sks port n plug to 878. Old 8"	PIPE REMOVED Caliper 223 sks Portland land & 110 sks Chem	LEF	T Control of the cont
TYPE Cleaned out to do Logged well gamma Run I'z tubing to Run 4'z" pipe to Pumped Latch down Bailed water out	FROM TO epth of 1627' a Ray, Newtron & 3 Arm 1620 Run 5 sks gel 898 Run 550 sks port n plug to 878. Old 8" inside 4%" pipe & Che	PIPE REMOVED Caliper 223 sks Portland land & 110 sks Chem	LEF	T Charles and the control of the con
TYPE Cleaned out to do Logged well gamma Run 1½ tubing to Run 4½" pipe to Pumped Latch down	FROM TO epth of 1627' a Ray, Newtron & 3 Arm 1620 Run 5 sks gel 898 Run 550 sks port n plug to 878. Old 8" inside 4%" pipe & Che	PIPE REMOVED Caliper 223 sks Portland land & 110 sks Chem	LEF	T Control of the cont
TYPE Cleaned out to do Logged well gamma Run 1½ tubing to Run 4½" pipe to Pumped Latch down Bailed water out Pittsburgh Coal a Description of mon plugging and filling sa	FROM TO epth of 1627' a Ray, Newtron & 3 Arm 1620 Run 5 sks gel 898. Run 550 sks port n plug to 878. Old 8" inside 4%" pipe & Che 800 to 808 nument: \$% pipe Metal Pl aid well was completed on the	PIPE REMOVED Caliper & 223 sks Portland land & 110 sks Chem pipe From 936' to cked pllug. O.K.	& pulled tubing. Comp 1420 Plugged and that th	T The service is Chica
TYPE Cleaned out to de Logged well gamma Run 1½ tubing to Run 4½" pipe to Pumped Latch down Bailed water out Description of mon	FROM TO epth of 1627' a Ray, Newtron & 3 Arm 1620 Run 5 sks gel 898. Run 550 sks port n plug to 878. Old 8" inside 4%" pipe & Che 800 to 808 nument: \$% pipe Metal Pl aid well was completed on the	PIPE REMOVED Caliper & 223 sks Portland land & 110 sks Chem pipe From 936' to cked pllug. O.K.	& pulled tubing. Comp 1420 Plugged and that th	T Control on the Control of Contr
TYPE Cleaned out to de Logged well gamma Run 1½ tubing to Run 4½" pipe to Pumped Latch down Bailed water out Pittsburgh Coal and Description of mon plugging and filling sa	FROM TO epth of 1627' a Ray, Newtron & 3 Arm 1620 Run 5 sks gel 898. Run 550 sks port n plug to 878. Old 8" inside 4%" pipe & Che 800 to 808 nument: 4% pipe Metal Pl aid well was completed on the ents saith not.	PIPE REMOVED 1 Caliper 223 sks Portland 1 and & 110 sks Chem pipe From 936' to cked pllug. O.K. ate A.P.I. # & Date 27 day of October Out	LEF & pulled tubing. Comp 1420 Plugged and that the comp 21, 00	was plugged T Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Chicago Ch
TYPE Cleaned out to de Logged well gamma Run I½ tubing to Run 4½" pipe to Pumped Latch down Bailed water out Pittsburgh Coal and Description of mon plugging and filling sa And furthur deponders.	FROM TO epth of 1627' a Ray, Newtron & 3 Arm 1620 Run 5 sks gel 898. Run 550 sks port n plug to 878. Old 8" inside 4%" pipe & Che 800 to 808 nument: 4% pipe Metal Pl aid well was completed on the ents saith not.	PIPE REMOVED Caliper & 223 sks Portland land & 110 sks Chem pipe From 936' to cked pllug. O.K.	En LEF & pulled tubing. Comp 1420 Plugged and that the comp 2000	Was plugged T Chicago Chicago Was Department of the chicago