

west virginia department of environmental protection

Office of Oil and Gas 601 57th Street, S.E. Charleston, WV 25304 (304) 926-0450 fax: (304) 926-0452

Harold D. Ward, Cabinet Secretary www.dep.wv.gov

Thursday, April 18, 2024 WELL WORK PLUGGING PERMIT Vertical Plugging

CHESAPEAKE APPALACHIA, L.L.C. 6100 N. WESTERN AVE.

OKLAHOMA CITY, OK 73118

Re:

Permit approval for 21477 47-023-00013-00-00

This well work permit is evidence of permission granted to perform the specified well work at the location described on the attached pages and located on the attached plat, subject to the provisions of Chapter 22 of the West Virginia Code of 1931, as amended, and all rules and regulations promulgated thereunder, and to any additional specific conditions and provisions outlined in the pages attached hereto. Notification shall be given by the operator to the Oil and Gas Inspector at least 24 hours prior to the construction of roads, locations, and/or pits for any permitted work. In addition, the well operator shall notify the same inspector 24 hours before any actual well work is commenced and prior to running and cementing casing. Spills or emergency discharges must be promptly reported by the operator to 1-800-642-3074 and to the Oil and Gas Inspector.

Upon completion of the plugging well work, the above named operator will reclaim the site according to the provisions of WV Code 22-6-30. Please be advised that form WR-38, Affidavit of Plugging and Filling Well, is to be submitted to this office within 90 days of completion of permitted well work, as should form WR-34 Discharge Monitoring Report within 30 days of discharge of pits, if applicable. Failure to abide by all statutory and regulatory provisions governing all duties and operations hereunder may result in suspension or revocation of this permit and, in addition, may result in civil and/or criminal penalties being imposed upon the operators.

Per 35 CSR 4-5.2.g this permit will expire in two (2) years from the issue date unless permitted well work is commenced. If there are any questions, please feel free to contact me at (304) 926-0450.

James A. Martin

Chief

Operator's Well Number:

WEIMER, JOHN BRUCE, ETA Farm Name:

U.S. WELL NUMBER: 47-023-00013-00-00

Vertical Plugging Date Issued: 4/18/2024

PERMIT CONDITIONS

West Virginia Code §22-6-11 allows the Office of Oil and Gas to place specific conditions upon this permit. Permit conditions have the same effect as law. Failure to adhere to the specified permit conditions may result in enforcement action.

CONDITIONS

- 1. All pits must be lined with a minimum of 20 mil thickness synthetic liner.
- 2. In the event of an accident or explosion causing loss of life or serious personal injury in or about the well or while working on the well, the well operator or its contractor shall give notice, stating the particulars of the accident or explosion, to the oil and gas inspector and the Chief within twenty-four (24) hours.
- 3. Well work activities shall not constitute a hazard to the safety of persons.
- 4. Notification shall be given by the operator to the Oil and Gas Inspector at least 24 hours prior to the construction of roads, locations and/or pits for any permitted work. In addition, the well operator shall notify the same inspector 24 hours before any actual well work is commenced and prior to running and cementing casing.

1) Date MAY 19	,	20 24
2)Operator's		
Well No. 21477-PI		
3) APT Well No. 47-23		- 00013

STATE OF WEST VIRGINIA DEPARTMENT OF ENVIRONMENTAL PROTECTION OFFICE OF OIL AND GAS

APPLICATION FOR A PERI	MIT TO PLUG AND ABANDON
4) Well Type: Oil/ Gas X/ Liquid (If "Gas, Production or Und	d injection/ Waste disposal/ derground storage) Deep/ Shallow
5) Location: Elevation 2966 District UNION	Watershed SOUTH FORK LUCINE CREEK County GRANT Quadrangle BLACKBIRD KNOB
6) Well Operator CHESAPEAKE APPALACHIA LLC Address PO BOX 18496 OKLAHOMA CITY, OK 73154-0496	7) Designated Agent ERIC HASKINS - MANAGER REG OPS Address 14 CHESAPEAKE LANE SAYRE, PA 18840
8) Oil and Gas Inspector to be notified Name GAYNE J KNITOWSKI Address 601 57TH STREET SE CHARLESTON, WV 25304	9) Plugging Contractor Name PLANTS AND GOODWIN Address 360 HIGH STREET BRADFORD, PA 16701
10) Work Order: The work order for the mann	ner of plugging this well is as follows:
	R⊂CENED Office of On and Gas
	COR 2 6 2008
	Enground - Committee of the Committee of
Notification must be given to the district of work can commence.	and gas inspector 24 hours before permitted
Knitowski,	Digitally signed by Cayne Colored in Inspector (and the 2014) 12/05/44 Date 3-20-2024

State of West Dirdini: DEPARTMENT OF ENERGY Division of Dil and Gas

023-0013-DD

Well Operator's Report of Well Work Farm name: WEIKER, JOHN BRUCE ETAL. Operator Well No.: 21477 LOCATION: Elevation: 2966.00 Quadrangle: BLACKBIRD KNOB District: UNION County: GRANT Latitude: 10420 Feet South of 39 Des. 7 Min. 30 Sec. Lonsitude 7960 Feet West of 79 Des. 15 Min. 0 Sec. Company: COLUMBIA NATURAL RESOURCE P. 0. BOX 1273 CHARLESTON, WV 1 % Asent: JOSEPH E. CAMPBELL Inspector: PHILLIP TRACY Permit Issued: 11/23/88
Well work Commenced: 12-1-88
Well work Completed: 12=11-88 Verbal Plussins Permission granted on:
Rotary X Cable Rig
Total Depth (feet) 9164'
Fresh water depths (ft)
200' Salt water depths (ft) ______ಟ್ಟರ್ಗಾಗಿ <u>ಟ್ಟರ</u>ಂಬಿಡರಿ Is coal being mined in area (Y/N)? N | | | | Office or On and Gas Coal Depths (ft): Coal Depths (ft)t OPEN FLOW DATA Producing formation Corriganville LS zone depth (ft) 8890 Dependence Gas: Initial open flow_____MCF/d Oil: Initial open flow_____Bbl. Final open flow ______3b1 \rightarrow Time of open flow between thitial and final tests ______48 ... Hours Static rock Pressure ______1450 _____psid (surface pressure) after ______5 days Hours Second producing formation_____ Pay zone depth (ft).... Gas: Initial open flow_____Bol ... Final open flow _____Bbt .. Time of open flow between initial and final tests_____Hour Static rock Pressure______Psid (surface pressure) after _____Houp: NOTE: ON BACK OF THIS FORM PUT THE FOLLOWING: 1). DETAILS OF PERFORATE INTERVALS, FRACTURING OR STIMULATING, PHYSICAL CHANGE, ETC. 2). THE WELLOW WHICH IS A SYSTEMATIC DETAILED GEOLOGICAL RECORD OF ALL FORMATIONS. INCLUDING COAL ENCOUNTERED BY THE WELLBORE. For: COLUMBIA NATURAL BESOURCES INC.

Well 21477

Perforated .36" select fire 12 holes from 8860 - 8885. Treated with 500 gals. FE acid, 100 bbls. 2% KCL water. Avg. 9.3 BPM @ 5000 psi.

Formation

8960 - 9164 Corriganville LS

9164 T.D.

ELUEIV.ED Office or On and Das

KAR 23704

Environmental Communication

IV-35 (Rev 8-81)

State of West Birginia Bepartment of Mines Gil und Gas Bivision

Date	August 13, 1986
Operator	's
Well No.	21477-PI
Farm	Weimer
API No.	47 - 023 - 001 3

WEIL OPERATOR'S REPORT OF

DRILLING, FRACTURING AND/OR STIM	ULATING, O	R PHYSICAL	L CHANGE		
WELL TYPE: Oil / Gas X / Liquid Injectio (If "Gas," Production X / Undergro	und Storag	e/ Deep	p_X_/ Sha	11ow/)	
LOCATION: Elevation; 2966 Watershed S					
District: Union County G	<u>irant</u>	Quadrangl	Black	Bird Knob	
					•
COMPANY Columbia Gas Transmission Corporation					•
ADDRESS P. O. Box 1273, Charleston, WV 25325	Casing	Used in	Left	Cement	ļ
DESIGNATED AGENT Robert C. Weidner	Tubing	Drilling		fill up Cu. ft.	İ
ADDRESS P. O. Box 1273, Charleston, WV 25325	Size	2-+	2. 7.22		
SURFACE OWNER Carl E. Weimer, etal	20-16				
ADDRESS P. O. Box 7, Maysville, WV 26833	Cond.	29	29	_	İ
MINERAL RIGHTS CWNER John B. Weimer, etal	13-10" 9 5/8	2360	2360	922	į
ADDRESS Rt. 1, Box 53, Maysville, WV 26833	8 5/8	2300	2300	 	
OIL AND GAS INSPECTOR FOR THIS WORK Phillip	7		 	 	
Tracy ADDRESS Elkins, WV	5 1/2	8724	8724	680	ĺ
PERMIT ISSUED 1-2-86	4 1/2			Enc	ENÆD
DRILLING COMMENCED 3-27-86	3			Office or 0	
DRILLING COMPLETED 5-10-86	2	8890	8890	* 4.5 5	
TF APPLICABLE: PLUGGING OF DRY HOLE ON CONTINUOUS PROGRESSION FROM DRILLING OR REWORKING. VERBAL PERMISSION OBTAINED ON	Liners used				7.
GEOLOGICAL TARGET FORMATION Oriskany SS		Dep	th 8:	209 feet	
Depth of completed well 8960 feet					
Water strata depth: Fresh 200 feet;	_	_			
Coal seam depths: N/A	-		ed in the	area? No	
OPEN FLOW DATA	_				
Producing formation Oriskany	Pav	zone decr	th 8	740 feet	
Gas: Initial open flow 2020 Mcf/d			•		
Final open flow 2500 Mcf/d					
Time of open flow between init					
Static rock pressure 2920 paig(surfac		-			
(If applicable due to multiple completion	:)				
Second producing formation	Pay	zone dep	th	fe et	
Gas: Initial open flow Mcf/d	Oil: Ini	tial open	flow	Bbl/ *	
Final open flow Mcf/d	Oil: Fir	al open f	low	E)	
Time of open flow between init	tial and fi	nal tests	hc	nrs	
Static rock pressurepsig(surface	neasurens	nt) after	hou		
•		(Conti	m,,, ,,,,,	04/19	<i>3</i> /202

DETAILS OF PERFORATED INTERVALS, FRACTURING OR STIMULATING, PHYSICAL CHANGE, ETC.

Open hole completion over Oriskany from 8726' - 8890'.

Spotted 2500 gallons 7-1/2% MCA. Flowed back. Pumped 2000 gallons 15% MCA.

Swabbed back.

WELL LOG

FORMATION COLOR HARD OR SOFT	TOP FEET	BOTTOM FEET	REMARKS Including indication of all fresh and salt water, coal, oil and gas
Mauch Chunk - Soft Gray	Surface	150	Damp
Big Lime - Soft Gray	150	670	1" stream of fresh water 0 200'
Pocono - Sandy Shale	670	1580	
Hampshire - Soft Gray	1580	2790	
Foreknobs - Silty Sand	2790	4570	Hole damp @ 3700'
Scheer - Dark Gray Sandy Shale	4570	6780	- -
Brallier - Shale	6780	7670	
Harrell - Shale	7670	7970	
Upper Marcellus - Soft Black Shale	7970	8350	
Purcell - Limestone	8350	8530	
Lower Marcellus - Shale	8530	8590	•
Needmore - Shale	8590	8695	
Oriskany - Hard Sandstone	8695	8890	Gas @ 8837' 202 MMCFD
Helderberg - Hard Limestone	8890	8960 TD	T.D.
			; ההספייהם Office or Oil and Gas
			e operation of Employees and a second

(Attach separate sheets as necessary)

Columbia Gas Transmission Corporation
Well Operator
By:
Date:

Note: Regulation 2.02(i) provides as follows:

"The term 'log' or 'well log' shall mean a systematic detailed geological record of all formations, including that, surrountered in the drilling of a well."



Diversing Proposal

300						Plug Details							
#	Туре	Description	Set ID	Plug Height (ft)	Bottom of Plug (ftKB)	Top of Plug (ftKB)	Cement Type	Cement Yield	Cement Density (ppg)	Excess Cement (%)	Cement Volume (bbl)	Cement Volume (sacks)	Tubing Displacement Volume (bbls)
1	CIBP	CIBP Perf Isolation	2.992	2	8,810	8,808	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2	Cement	Cement Perf Isolation	2.992	200	8,808	8,608	Class A	1.28	15.5	0	1.7	7.6	33.1
3	Cement	Prod Csg Stub Plug (Inside Prod Csg)	2.992	50	8,550	8,500	Class A	1.28	15.5	0	0.4	1.9	32.1
3 (con.)	Cement	Prod Csg Stub Plug (Inside Int. Csg)	4.892	150	8,500	8,350	Class A	1.28	15.5	20	4.2	18.4	0.0
4	CIBP	CIBP	4.892	2	8,300	8,298	N/A	N/A	N/A	N/A	N/A	N/A	0.0
5	Cement	Inter Csg Stub Plug (Inside Csg)	4.892	50	7,050	7,000	Class A	1.28	15.5	20	1.4	6.1	26.3
5 (con.)	Cement	Inter Csg Stub Plug (Open Hole)	6.25	150	7,000	6,850	Class A	1.28	15.5	50	8.5	37.5	26.1
6	Cement	Elevation Plug (Open Hole)	6.25	100	3,016	2,916	Class A	1.28	15.5	50	5.7	25.0	0.0
7	Cement	Surface Csg Shoe Plug (Open Hole)	6.25	100	2,460	2,360	Class A	1.28	15.5	50	5.7	25.0	9.5
7 (con.)	Cement	Surface Csg Shoe Plug (Inside csg)	8.921	100	2,360	2,260	Class A	1.28	15.5	20	9.3	40.7	9.1
8	Cement	Surface Plug	8.921	100	100	0	Class A	1.28	15.5	0	7.7	33.9	0.4

RECEIVED
Office of Oil and Gas

MAR 2 9 2024

way begannian of Environmental Fig. (2000)



Spacer Details								
#	Fluid Type	Description	Set ID	Spacer Height	Spacer Density (ppg)	Spacer Viscosity (cp)	Excess Spacer (%)	Spacer Volume (bbls)
1	Gel	Perf Isolation to Prod Csg Stub Plug	2.992	58	9	+	5	0.5
2	Gel	CIBD to Inter Csg Stub Plug	4.892	1,248	9	-	10	31.9
3	Gel	Inter Csg Stub Plug to Elevation Plug	6.25	3,834	9	-	40	203.7
4	Gel	Elevation Plug to Surface Csg Shoe	6.25	456	9	-	40	24.2
5	Gel	Surface Csg Shoe Plug to Surface Plug	8.921	2,160	9	V <u>2</u>	5	175.3

Estimated	Casing Cuts
String	Est. Cut Depth (ftKB)
Intermediate	7000
Production	8,500

RECEIVED Office of Oil and Gas

MAR 2 9 2024

W// Department of Environmental Protection



Well Information

Driving Directions

Surface	Location
County/State	GRANT, WV
Township	UNION
Latitude*	0
Longitude*	0

114		10.0		10000	
*	N	٨	n	02	

CHK Contacts						
Title	Name	Office	Mobile			
Production Superin.	Nick Krut	-	570-886-0256			
Completions Fore.	Lucas Welch		570-423-4236			
Production Manager	John Van Gels	405-766-8012	636-448-1104			
Production Supervisor	Keeley Bergman	405-766-8438	918-991-5520			
Production Engineer	Jordan Lucas	-	740-629-2091			
Regulatory Manager	Eric Haskins	-	607-242-3839			

General Well Data							
КВ	16	Top Perf	8,860	Perf Interval Length	25	PBTD	0
КОР	0	Bottom	8,885	TD	9,160	Elevation	2,96

Office of Oil and Gas

W/y Department of Environmental Projection

		19 116 2		Casin	g Detail	s				
String	Grade	OD	ID	Weight	Drift	Top (ftKB)	Bottom (ftKB)	Capacity (bbl/ft)	Tot. Cap. (bbl)	Hole Size
Conductor	H-40	13.375	12.715	48		-	29	0.157054	4.554561	15
Surface	J-55	9.625	8.921	36	8.765		2,360	0.077311	182.4546	12.25
Intermediate	J-55	5.5	4.892	17	4.767	-	8,724	0.023248	202.817	6.25
Production	P-110	3.5	2.992	9.2		- 12	9,160	0.008696	79.65893	4.5
Production										
DV Tool										

Tubing Details									
Grade	Weight	OD	ID	Length (ft)	Top (ftKB)	Bottom (ftKB)	Burst 80% (PSI)	Capacity (bbl/ft)	Tot. Cap.
L-80	4.7	2.375	1.995	8,860	16	8,876	8,960	0.003866	34
	++								
	-								
				Grade Weight OD ID	Grade Weight OD ID Length (ft)	Grade Weight OD ID Length (ft) Top (ftKB)	Grade Weight OD ID Length (ft) Top (ftKB) Bottom (ftKB)	Grade Weight OD ID Length (ft) Top (ftKB) Bottom (ftKB) (PSI)	Grade Weight OD ID Length (ft) Top (ftKB) Bottom Burst 80% Capacity (bbl/ft)



Plug & Abandon

County/State: GRANT, WV Township: UNION Latitude: Longitude: (NAD 83) API: 4702300013

Summary

The JB WEIMER ETAL 2514 will be plugged and abandoned. The well is located in GRANT County, WV and was spud on 03-27-1986 by Columbia Gas Transmission Corp., targeting the 0 as a VERTICAL well. The last know production date for this well was 12-15-2012 where it produced 2 MCF, 0 BO, and 0 BW.

Vertical well targeting Oriskany. Open hole completion from 8,726 to 8,890'. Later, well was deepened to 9,160 and 3 1/2" was set through the Oriskany. Perfed from 8,860-8,885. Casing grades and weights unkown, all values are assumed. No tubing in well, tubing shown is workstring to be used for P&A.

	Guideline		
Step	Operation Operation		
	The content of this guideline are recommendations based on expected conditions, current equipment, and existing Should actual conditions vary from expected, discuss with your supervisor and all necessary personnel on how to provide the content of this guideline are recommendations based on expected conditions, current equipment, and existing		
	Pre-Job Safety Meeting		
	a. Safety is the highest priority.	RECEI	VED
	b. 2 active barriers must be maintained at all times in accordance with OGB-CHK-STD-001 Barrier Standard. c. Ensure gas monitoring equipment is being utilized on location.	Office of Oil	and Gas
	d. Remind all personnel that everyone has Stop Work Authority.	MAR D	9 2024
	e. Before each shift/day or new scope of work:	MINIS	0
	 Hold well-site safety meetings covering the scope of work with all personnel on location. 	√m Özp8	
	 Review guideline and discuss critical parameters (pressures, volumes, contingency plans, etc.). 	Environment	en Evoluteli
	· Verify that all personnel understand and are prepared for the operation.	Fualiound	
	Review emergency action plans for the operation.		
	Glossary: QHB = Qualified Hydrostatic Barrier, BPV = Back Pressure Valve, TIW = Full Open Safety Valve (Equal ID to TWC = Two Way Check	Work String),	
1	Prior to rig arriving on site:		
	a. Make sure all casing valves are readily accessible and remove water from cellar.		
	b. Perform 72-hour pressure build up test on all annuli.		
	c. Perform negative pressure test on master valve(s) in accordance with APP Master Valve Operational Guidelin	e - PROD-APP-	
	002.		
	c. Make sure A, B, and C section flanges are properly identified.		
	d. Verify regulatory permit and approval to plug and abandon.		
	e. Notify WVDEP, BLM, municipality and surface landowner 1 week prior to commencing operations.		

2	RU Containment.
3	MIRU WOR, pump, and surface equipment.
	Pump FW until a Qualified Hydrostatic Barrier (QHB) is established. Ensure pump is rigged up and ready to pump kill weight fluid
4	for duration of job.
	a. Contact supervisor and OKC engineer if higher weight kill fluid is required.
	· Occurs when pumped FW volume equals or exceeds casing + tubing (if applicable) volume to top perf depth and well
	pressure exceeds 0 psi and/or well does not pass a flow check.
5	SKIP TO STEP 11 IF WELL DOES NOT HAVE TUBING - Contact supervisor and OKC engineer if well does not have a tubing hanger.
•	NU lubricator to closed master valve and pressure test.
	a. Flow Paths:
	· 2.375 Tubing – 1st Barrier = QHB, 2nd Barrier = Master Valve
	· 3.5 Casing – 1st Barrier = QHB, 2nd Barrier = Master Valve
6	Bleed off test pressure, open master valve, and install BPV in tubing hanger. Contact engineer and prepare to set pump through
<u> </u>	plug in tubing with SL, if BPV cannot be installed in hanger.
	a. Flow Paths:
	· 2.375 Tubing – 1st Barrier = QHB, 2nd Barrier = Lubricator
	· 3.5 Casing – 1st Barrier = QHB, 2nd Barrier = Tubing Hanger
	ND lubricator, ND wellhead, NU 7.0625" master valve and NU double 7.0625" BOPs (Top to Bottom: 2.375" Pipe Ram and Blind
	Ram). Stab landing joint in tubing hanger. Close pipe ram and pressure test stack against tubing hanger in accordance with CHK
7	Workover and Completions BOP Manual (outlined in section 2.6). LD landing joint, close master valve and blind ram. Pressure
	test blind ram against master valve in accordance with CHK Workover and Completions BOP Manual (outlined in section 2.6).
	a. Flow Paths:
	· 2.375 Tubing – 1st Barrier = QHB, 2nd Barrier = BPV
•	3.5 Casing – 1st Barrier = QHB, 2nd Barrier = Tubing Hanger
8	NU lubricator and pressure test against master valve. Bleed off test pressure, open master valve and pull BPV.
	a. Flow Paths:
	• 2.375 Tubing – 1st Barrier = QHB, 2nd Barrier = BPV (NU), 2nd Barrier = Lubricator (Pull BPV)
9	3.5 Casing – 1st Barrier = QHB, 2nd Barrier = Tubing Hanger Close Blind Ram and ND lubricator
,	a. Flow Paths:
	• 2.375 Tubing – 1st Barrier = QHB, 2nd Barrier = Blind Ram
	• 3.5 Casing – 1st Barrier = QHB, 2nd Barrier = Tubing Hanger
10	MU lifting sub into tubing hanger. Unscrew tubing lockdown pins and LD tubing hanger. POOH with tubing while standing back.
	a. Flow Paths:
	· 2.375 Tubing – 1st Barrier = QHB, 2nd Barrier = TIW
	· 3.5 Casing – 1st Barrier = QHB, 2nd Barrier = Pipe Ram
	SKIP TO THIS STEP IF WELL DID NOT HAVE TUBING - Close master valve. NU WL packoff and pressure test against master valve.
11	RU WŁ.
	a. Flow Paths:
	· 3.5 Casing – 1st Barrier = QHB, 2nd Barrier = Master Valve
	 5.5 Casing - 1st Barrier = QHB, 2nd Barrier = Csg Head/Slips, 3rd Barrier = Master Valve
	Plug #1 (CIBP Perf Isolation) - TIH with WL and set CIBP as specified under Plug Details table in accordance with Plug 1. Use a CCL
	to ensure the CIBP is not set in a collar. TOOH with WL. Pressure test CIBP to 1,500 psi or 80% of casing burst pressure
12	, · · · · · · · · · · · · · · · · · · ·
12	accounting for hydrostatic to CIBP depth, which ever is less.
12	- Flan Dalin
12	

WAR 28 7571

13	ND WL packoff. RD and release WL.
	a. Flow Paths:
'	· 3.5 Casing – 1st Barrier = QHB, 2nd Barrier = CIBP
	 5.5 Casing – 1st Barrier = QHB, 2nd Barrier = Csg Head/Slips
	ND double 7.0625" BOPs (if applicable), master valve, and necessary wellhead equipment to expose casing slips. Establish hot
14	work permit and tac weld casing slips to casing. Ensure thorough LEL monitoring is in place, fire extinguishers are near wellhead,
	and fire watch is designated as outlined by hot work permit.
	a. Flow Paths:
	· 5.5 Casing – 1st Barrier = QHB, 2nd Barrier = CIBP
	• 9.625 Casing – 1st Barrier = QHB, 2nd Barrier = Csg Head/Slips
15	NU double 11" BOPs (Top to Bottom: 2.375" Pipe Ram and Blind Ram) and 11" annular BOP. Test each ram against the CIBP in
1.5	accordance with CHK Workover and Completions BOP Manual (outlined in section 2.6).
	a. Flow Paths:
	· 3.5 Casing – 1st Barrier = QHB, 2nd Barrier = CIBP
	 5.5 Casing – 1st Barrier = QHB, 2nd Barrier = Csg Head/Slips
	Plug #2 (Cement Perf Isolation) - TIH with work string to bottom depth of Plug 2 as specified under the Plug Details table. Pump
16	balanced cement plug in accordance with Plug 2. Displace tubing with volume specified on Plug Details table. POOH with WS.
	WOC 8 hours.
	a. Flow Paths:
	· 2.375 Tubing – 1st Barrier = QHB, 2nd Barrier = CIBP, 3rd Barrier = TIW
	· 3.5 Casing – 1st Barrier = QHB, 2nd Barrier = CIBP, 3rd Barrier = Pipe Rams
17	NU WL packoff. RU WL.
	a. Flow Paths:
	· 3.5 Casing – 1st Barrier = QHB, 2nd Barrier = CIBP, 3rd Barrier = Cement Plug
	· 5.5 Casing – 1st Barrier = QHB, 2nd Barrier = Csg Head/Slips
18	RIH with CBL, POOH with WL and discuss results with key stakeholders.
	a. Flow Paths:
	· 3.5 Casing – 1st Barrier = QHB, 2nd Barrier = CIBP, 3rd Barrier = Cement Plug, 4th Barrier = WL Packoff (untested)
	5.5 Casing – 1st Barrier = QHB, 2nd Barrier = Csg Head/Slips, 3rd Barrier = WL Packoff (untested)
	Pressure test WL Packoff against cement plug to 500 psi. Ok testing against cement due to CIBP below. RIH with jet cutter and
19	cut csg at TOC as determined by CBL. POOH with WL.
	a. Flow Paths:
	· 3.5 Casing – 1st Barrier = QHB, 2nd Barrier = WL Packoff
	 5.5 Casing – 1st Barrier = QHB, 2nd Barrier = Csg Head/Slips, 3rd Barrier = WL Packoff
	Close blind ram. RD WL. Verify good cut before releasing WL by attempting to establish circulation. Do not exceed a 0.8 psi/ft
	gradient when establishing circulation against open hole accounting for hydrostatic pressure. Example: casing cut at 5,000' with 9
20	ppg fluid in well> Max pressure at cut = 5,000' x 0.8 psi/ft = 4,000 psi. Hydrostatic pressure = 0.052 x 9 ppg x 5,000' = 2,340 psi.
	Max surface circulating pressure = 1,660 psi.
	a. Flow Paths:
	· 3.5 Casing – 1st Barrier = QHB, 2nd Barrier = Blind Ram
	 5.5 Casing – 1st Barrier = QHB, 2nd Barrier = Csg Head/Slips, 3rd Barrier = Blind Ram
21.	NU casing jacks (if applicable), MU casing spear, and open blind ram. Spear casing, LD slips and spear.
	a. Flow Paths:
	· 2.375 Tubing – 1st Barrier = QHB, 2nd Barrier = TIW
	· 3.5 Casing – 1st Barrier = QHB, 2nd Barrier = Blind Ram (Csg Jack NU), 2nd Barrier = Pipe Ram (Spear)
	• 5.5 Casing – 1st Barrier = QHB, 2nd Barrier = Csg Head/Slips (Csg Jack NU), 2nd Barrier = Pipe Ram (Spear)
	a control of the cont

RECEIVED
Office or On and Gas

W.S. 26 2004

English of the section

22	POOH with production casing.
	a. Flow Paths:
	3.5 Casing – 1st Barrier = QHB, 2nd Barrier = Swage Nipple w/ Ball Valve
	• 5.5 Casing – 1st Barrier = QHB, 2nd Barrier = Annular
23	Plug #3 (Prod Csg Stub Plug) - TIH with work string to bottom depth of Plug 3 as specified under the Plug Details table. Pump Spacer 1 as detailed under the Spacer Details table. Pump balanced cement plug in accordance with Plug 3. Displace tubing with volume specified on Plug Details table. POOH 1,500' above estimated TOC. Close pipe ram. WOC 8 hours.
	a. Flow Paths:
	· 2.375 Tubing 1st Barrier = QHB, 2nd Barrier = TIW
	• 5.5 Casing – 1st Barrier = QHB, 2nd Barrier = Pipe Rams
24	Plug #4 (CIBD for BOP Testing) - Open Blind ram. TIH with WL and set CIBP as specified under Plug Details table in accordance
24	with Plug 4. Use a CCL to ensure the CIBP is not set in a collar. TOOH with WL
	a. Flow Paths:
	5.5 Casing – 1st Barrier = QHB, 2nd Barrier = Cement Plug
	9.625 Casing 1st Barrier = QHB, 2nd Barrier = csg Head/Slips
26	Close master valve. ND WL packoff. RD WL. Pressure test CIBP to 1,500 psi or 80% of casing burst pressure accounting for
	hydrostatic to CIBP depth, which ever is less. Release WL. a. Flow Paths:
	5.5 Casing – 1st Barrier = QHB, 2nd Barrier = Cement Plug, 3rd Barrier = Master Valve
	• 9.625 Casing – 1st Barrier = QHB, 2nd Barrier = Csg Head/Slips, 3rd Barrier = Master Valve
	ND double 11" BOPs, 11" annular, and necessary wellhead equipment to expose casing slips. Establish hot work permit and tac
27	weld casing slips to casing. Ensure thorough LEL monitoring is in place, fire extinguishers are near wellhead, and fire watch is
	designated as outlined by hot work permit.
	a. Flow Paths:
	· 5.5 Casing – 1st Barrier = QHB, 2nd Barrier = Cement Plug
	· 9.625 Casing – 1st Barrier = QHB, 2nd Barrier = Csg Head/Slips
28	NU double 11" BOPs (Top to Bottom: 2.375" Pipe Ram and Blind Ram) and 11" annular BOP. Test each ram against the CIBP in accordance with CHK Workover and Completions BOP Manual (outlined in section 2.6). Do not exceed a 1,500 psi test pressure to ensure the cement plug below the CIBP has minimal presssure exposure should the CIBP slip/fail.
	a. Flow Paths:
	• 5.5 Casing – 1st Barrier = QHB, 2nd Barrier = Cement Plug
	9.625 Casing – 1st Barrier = QHB, 2nd Barrier = Csg Head/Slips
29	NU WL packoff and BOP ram. RU WL.
	a. Flow Paths:
	+ 5.5 Casing – 1st Barrier = QHB, 2nd Barrier = Cement Plug, 3rd Barrier = Blind Ram
	9.625 Casing – 1st Barrier = QHB, 2nd Barrier = Csg Head/Slips, 3rd Barrier = Blind Ram
30	Open blind ram. RIH with WL, tag TOC, and run CBL. Discuss results with stakeholders. RIH with jet cutter and cut csg at TOC as
	determined by CBL. POOH with WL.
	 a. Flow Paths: 5.5 Casing – 1st Barrier = QHB, 2nd Barrier = WL Packoff, 3rd Barrier = WL BOP
	• 9.625 Casing — 1st Barrier = QHB, 2nd Barrier = WL Packoff, 3rd Barrier = WL BOP
	Close blind ram. RD WL. Verify good cut before releasing WL by attempting to establish circulation. Do not exceed a 0.8 psi/ft
	gradient when establishing circulation against open hole accounting for hydrostatic pressure. Example: casing cut at 5,000' with 9
31	ppg fluid in well> Max pressure at cut = 5,000' x 0.8 psi/ft = 4,000 psi. Hydrostatic pressure = 0.052 x 9 ppg x 5,000' = 2,340 psi.
	Max surface circulating pressure = 1,660 psi.
	a. Flow Paths:
	· 5.5 Casing – 1st Barrier = QHB, 2nd Barrier = Blind Ram
	• 9.625 Casing – 1st Barrier = QHB, 2nd Barrier = Csg Head/Slips, 3rd Barrier = Blind Ram
32	NU casing jacks (if applicable), MU casing spear, and open blind ram. Spear casing, LD slips and spear.
	a. Flow Paths:
	· 2.375 Tubing – 1st Barrier = QHB, 2nd Barrier = TIW
	· 5.5 Casing – 1st Barrier = QHB, 2nd Barrier = Blind Ram (Csg Jack NU), 2nd Barrier = Pipe Ram (Spear)
	· 9.625 Casing – 1st Barrier = QHB, 2nd Barrier = Csg Head/Slips (Csg Jack NU), 2nd Barrier = Pipe Ram (Spear)
33	POOH with intermediate casing.

 5.5 Casing – 1st Barrier = QHB, 2nd Barrier = 5.5 Swage Nipple w/ Ball Valve 9.625 Casing – 1st Barrier = QHB, 2nd Barrier = Annular Plug #5 (Inter Csg Stub Plug) - TIH with work string to bottom depth of Plug 5 as specifed under the Plug Details table. Pump Spacer 2 as detailed under the Spacer Details table. Pump balanced cement plug in accordance with Plug 5. Displace tubing with volume specified on Plug Details table, POOH, Close blind ram, WOC 8 hours. a. Flow Paths: 2.375 Tubing – 1st Barrier = QHB, 2nd Barrier = TIW 9.625 Casing – 1st Barrier = QHB, 2nd Barrier = Pipe Ram Plug #6 (Elevation) - TIH with work string to bottom depth of Plug 6 as specifed under the Plug Details table. Pump Spacer 3 as detailed under the Spacer Details table. Pump balanced cement plug in accordance with Plug 6. Displace tubing with volume specified on Plug Details table. POOH. Close blind ram. WOC 8 hours. a. Flow Paths: 2.375 Tubing – 1st Barrier = QHB, 2nd Barrier = TIW · 9.625 Casing - 1st Barrier = QHB, 2nd Barrier = Pipe Ram Plug #7 (Surface Csg Shoe Plug) - TIH with work string and tag TOC. PU to bottom depth of Plug 7 as specified under the Plug Details table. Pump Spacer 4 as detailed under the Spacer Details table. Pump balanced cement plug in accordance with Plug 7. Displace tubing with volume specified on Plug Details table. PU a minimum of 500' above estimated TOC. Close pipe ram and WOC 8 hrs. a. Flow Paths: 2.375 Tubing – 1st Barrier = QHB, 2nd Barrier = TIW • 9.625 Casing – 1st Barrier = QHB, 2nd Barrier = Pipe Rams Plug #8 (Surface Plug) - TIH with work string and tag TOC. PU to bottom depth of Plug 8 as specified under the Plug Details table. Pump Spacer 5 as detailed under the Spacer Details table. Pump balanced cement plug in accordance with Plug 8. Displace tubing with volume specified on Plug Details table. POOH. Close blind ram. WOC 8 hours. a. Flow Paths: 2.375 Tubing – 1st Barrier = QHB, 2nd Barrier = TIW · 9.625 Casing - 1st Barrier = QHB, 2nd Barrier = Pipe Ram RDMO. Monitor well for 24 hrs minimum. Establish hot work permit. Perform LEL assessment of well head and ensure LEL monitoring remains in place. Visually check wellbore and cellar for signs of bubbling. Contact supervisor and OKC engineer if LELs or bubbling are present. Place fire extinguishers near wellhead and ensure fire watch is designated as outlined by hot work permit. Cut casing and weld abandonment cap with monument as specified by WVDEP.


Gayne Knitowski, Knitowski, Inspector
Inspector
Oate: 2024.03.20 12:04:42 -04:00*


Office of On and Gas

MAR 2 9 2024

Englowing Control







Schematics are note to scale

WW-4A	
Revised	6-07

1) Date:	3/19/2024	
2) Operator's	s Well Number	-
21477-PI		

3) API Well No.: 47 -

023

00013

STATE OF WEST VIRGINIA DEPARTMENT OF ENVIRONMENTAL PROTECTION, OFFICE OF OIL AND GAS NOTICE OF APPLICATION TO PLUG AND ABANDON A WELL

(a) Name	ner(s) to be served: CARL EDWARD WEIME		(a) Coal Operator	•	
(a) Name Address	5004 DERBY COURT	r, Jr.	— Name Address		
Audress	MURRELLS INLET, SC 2	00576	Address		
(b) Name	WORKELLS INCE 1, SC 2	9370	(b) Coal Ow	ner(s) with Declaration	
Address			(b) Coar Ow Name	CARL EDWARD WEIMER, JR	
Audress			Name Address	5004 DERBY COURT	· · · · · · · · · · · · · · · · · · ·
			Address	MURRELLS INLET, SC 29576	
(c) Name			Name	WOLLD HEELT, GO ESCIO	
Address			Address	·	
			_		
6) Inspector	GAYNE J KNITOWSKI		— (c) Coal Les	see with Declaration	
Address	601 57TH STREET SE		Name	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	CHARLESTON WV 2530	4	Address	-	· <u> </u>
Telephone	304546-8171		_		
accompany Protection, the Applic	ying documents for a permit t , with respect to the well at th	o plug and abandon a ve e location described of mailed by registered	well with the Chief of the n the attached Application or certified mail or deli	operator proposes to file or has file e Office of Oil and Gas, West Virgi on and depicted on the attached For ivered by hand to the person(s) na	nia Department of Environmental rm WW-6. Copies of this Notice.
		Well Operator	CHESAPEAKE APPAL	AÇHIA LLA	amin (ED)
a	Pennsylvania - Notary Seal arris, Notary Public	By:	KERI FIENO	Loud	F. Call and Gas
Canawi	and the second second	Its:	REGULATORY SPEC	ALIST	Office of The grant
Brac	October 22, 2026	Address	PO BOX 18496		1100 S. S. 2014
My commission Commission	on number 1286242	ا	OKLAHOMA CITY, OK	73154-0496	1
Member, Pennsylv	vania Association of Notaries	Telephone	405-766-8791	<u></u>	
			_		Envisation in
<u> </u>	sworn before me thi	3 <u> </u>	ay of March	Notary Public	
My Commission	Expires OC+	Der 21, 3	2026		
Oil and Gas Priva	acy Notice	<u>e</u>			

The Office of Oil and Gas processes your personal information, such as name, address and phone number, as a part of our regulatory duties. Your personal information may be disclosed to other State agencies or third parties in the normal course of business or as needed to comply with statutory or regulatory requirements, including Freedom of Information Act requests. Our office will appropriately secure your personal information. If you have any questions about our use of your personal information, please contact DEP's Chief Privacy Officer at depprivacyoffier@wv.gov.

[EXTERNAL] UPS Delivery Notification, Tracking Number 1ZV3127X0395325468

UPS <pkginfo@ups.com> Thu 3/21/2024 6:46 PM

To:Keri Fieno <KERI.FIENO@CHK.COM>

This Me	ssage Is	From	an Ex	ternal	Sender
---------	----------	------	-------	--------	--------

This message came from outside your organization.

Report Suspicious

UPS logo

Hello, your package has been delivered.

Delivery Date: Thursday, 03/21/2024

Delivery Time: 6:44 PM **Left At:** OTHER-RELEAS

Set Delivery Instructions

Manage Preferences

View My Packages

SAYRECHK

JB WEIMER ETAL 2514 P&A LANDOWNER NOTIFICATION

Tracking Number: <u>1ZV3127X0395325468</u>

CARL EDWARD WEIMER, JR

Ship To: 5004 DERBY COURT

MURRELLS INLET, SC 295765846

US

Number of Packages: 1

UPS Service: UPS Ground

Package Weight: 0.2 LBS

Reference Number: JB WEIMER ETAL 2514 P&A

API	Num	ber	47	_ 023	(0 <u>0</u> 013	
Opera	ator's	Well	No.	BERG	623925		

STATE OF WEST VIRGINIA DEPARTMENT OF ENVIRONMENTAL PROTECTION OFFICE OF OIL AND GAS

FLUIDS/ CUTTINGS DISPOSAL & RECLAMATION PLAN

Operator Name CHESAPEAKE APPALACHIA LLC OP Code 2528
Watershed (HUC 10) SOUTH FORK LUNICE CREEK Quadrangle BLACKBIRD KNOB Do you anticipate
using more than 5,000 bbls of water to complete the proposed well work? Yes No Will a pitised? Yes No Volume Volume No Volume No Volume Volume No No Volume No
If so, please describe anticipated pit waste: ANY WELL EFFLUENT WILL BE CONTAINED IN TANKS AND DISPOSED OFFSITE
Will a synthetic liner be used in the pit? Yes No If so, what ml.?
Proposed Disposal Method For Treated Pit Wastes:
Land Application (if selected provide a completed form WW-9-GPP) Underground Injection (UIC Permit Number) Reuse (at API Number) Off Site Disposal (Supply form WW-9 for disposal location) Other (Explain
Will closed loop systembe used? If so, describe: DRILL CUTTINGS WILL BE CIRCULATED BACK INTO AN OPEN TANK
Drilling medium anticipated for this well (vertical and horizontal)? Air, freshwater, oil based, etc. FRESH WATER
-If oil based, what type? Synthetic, petroleum, etc. N/A
Additives to be used in drilling medium? NONE
Drill cuttings disposal method? Leave in pit, landfill, removed offsite, etc. LANDFILL
-If left in pit and plan to solidify what medium will be used? (cement, lime, sawdust) NO PIT
-Landfill or offsite name/permit number? KIMBLE SANITARY LANDFILL OR MUD MASTERS
Permittee shall provide written notice to the Office of Oil and Cas of any load of drill cuttings or associated waste rejected at any West Virginia solid waste facility. The notice shall be provided within 24 hours of rejection and the permittee shall also disclose where it was properly disposed.
I certify that I understand and agree to the terms and conditions of the GENERAL WATER POLLUTION PERMIT issue on April 1, 2016, by the Office of Oil and Cas of the West Virginia Department of Environmental Protection. I understand that the provisions of the permit are enforceable by law. Violations of any term or condition of the general permit and/or other applicable law or regulation can lead to enforcement action. I certify under penalty of law that I have personally examined and am familiar with the information submitted on the application form and all attachments thereto and that, based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine or imprisonment. Company Official Signature Company Official Title REGULATORY SPECIALIST
Subscribed and sworn before me this day of Warch Commonwealth of Pennsylvania - Notary Seal Readford County My commission expires October 22, 2026 Commission number 1286242 Member, Pennsylvania Association of Notaries Member, Pennsylvania Association of Notaries

Proposed Revegetation Tre			
	eatment: Acres Disturbed 10	Preveg etation p	Н
Lime 3.90	Tons/acre or to correct to pl	1	
Fertilizer type 8-	16-16		
Fertilizer amount	968	lbs/acre	
Mulch_3	Tons	/acre	
		ed Mixtures	
•	Temporary	Perma	nent
Seed Type OATS/ANNUAL	lbs/acre RYE 40LBS/ACRE	Seed Type BIRDSFOOT TREF	lbs/acre OIL 8LBS/ACRE
HAY/STRAW MU	JLCH 3 TONS/ACRE	TALL FESCUE	40LBS/ACRE
hotocopied section of inv			
	Olved 7.5' topographic sheet. Gayne Knitowski, Knitowski, Inspector	== 1746 · · · · · · · · · · · · · · · · · · ·	
lan Approved by:			
	Gayne Knitowski, Digitally signed by Cayne Classpectur Date 204-63, 20 12:09:56		PECENTED
••	Gayne Knitowski, Digitally signed by Gayne Gayne Knitowski, Inspector Onice 2024.03.20 12:03:36 -04:00*		Office Or Oil aid
•• • ——	Gayne Knitowski, Digitally signed by Gayne Gayne Knitowski, Inspector Onice 2024.03.20 12:03:36 -04:00*		Office of Oil and
	Gayne Knitowski, Digitally signed by Gayne Gayne Knitowski, Inspector Onice 2024.03.20 12:03:36 -04:00*		Office Or Oil aid
•• • ——	Gayne Knitowski, Digitally signed by Gayne Gayne Knitowski, Inspector Onice 2024.03.20 12:03:36 -04:00*		Office of City and
• • • • • • • • • • • • • • • • • • • •	Gayne Knitowski, Digitally signed by Gayne Gayne Knitowski, Inspector Onice 2024.03.20 12:03:36 -04:00*		Office of City and
omments:	Gayne Knitowski, Digitally signed by Cayne Knitowski, Inspector Date: 2024-03;20 12-03:36 -04:00		Office of Cit and
	Gayne Knitowski, Digitally signed by Gayne Gayne Knitowski, Inspector Onice 2024.03.20 12:03:36 -04:00*	Date: 3-20-2024	Office of On and

WW-9- GPP Rev. 5/16

			Page		of	
API Nur	nber	47 -	023	_ 0	00013	
Operator's Well No.	вν	VEIM	ER ET	 ΓAL 251	4 (2147	7-PI)

STATE OF WEST VIRGINIA DEPARTMENT OF ENVIRONMENTAL PROTECTION OFFICE OF OIL AND GAS

GROUNDWATER PROTECTION PLAN

Watershed (HUC 10): SOUTH FORK FORK LUCINE Qu	ad: BLACKBIRD KNOB
Farm Name: JB WEIMER ETAL 2514	lau.
ann Name: 16 WEIMER ETAL 2314	
. List the procedures used for the treatment and discharge of fluids. Include a list groundwater.	t of all operations that could contaminate the
SEE ATTACHED	
 Describe procedures and equipment used to protect groundwater quality from the 	e list of potential contaminant sources above.
 List the closest water body, distance to closest water body, and distance fror discharge area. 	n closest Well Head Protection Area to the
	on closest Well Head Protection Area to the
	RFC=N/ED
	RECENTED Office of Orland (
discharge area.	RECEIVED Office of Orland (1777) M. Environd on Orland
	RECEIVED Office of Orland (1777) M. Environd on Orland
discharge area.	RECEIVED Office of Orland (1777) M. Environd on Orland
discharge area.	RECEIVED Office of Orland (1777) M. Environd on Orland
discharge area.	RECEIVED Office of Orland (1777) M. Environd on Orland

5. Discuss any existing groundwater quality data for your facility or an adjacent property.

WW	-9-	GPP
Rev.	5/1	6

	Page	of
API Number 4	7 -023	_000¶3
Operator's Well No	N IR W	FIMER ETAL 2514

	Provide a statement that no waste material will be used for deicing or fill material on the property.
	Describe the groundwater protection instruction and training to be provided to the employees. Job procedures shall provide direction on how to prevent groundwater contamination.
	Office of Oil and C
	Office of Office
	Environment . Sobort
-	
,	Provide provisions and frequency for inspections of all GPP elements and equipment.
	ature: Levelieno

RECOMMENDED PERMANENT SEEDING MIXTURE FOR ALL DISTURBED AREAS

MIXTURE NUMBER	SEASON	SPECIES	SEEDING RATE (Ib/ac)
2	COOL	BIRDSFOOT TREFOIL TALL FESCUE	B / 40

MULCHING

MATERIAL SHALL BE HAY OR STRAW WHICH IS FREE OF WEED AND SEEDS, NOT MOLDY, ROTTEN, AND SHALL BE APPLY TO ALL SLOPES FATTER THAN 3:1 AT A RATE OF 140 LBS/1,000 SF. (APPROXIMATELY TWO BALES PER 1,000 SF OR 3 TON PER AC)

HYDROSEEDING SPECIFICATION


MATERIAL	DESCRIPTION	APPLICATION RATE (PER 1,000 SY)
(1) SEE MIXTURE (% BY WEIGHT)	REDTOP - 10% PENNLAWN FESCUE - 45% KENTUCKY BLUEGRASS - 45%	27 LBS
(2) 8-16-16	COMMERCIAL FERTILIZER	200 LBS
(3) LIME	GROUND COMMERCIAL LIMESTO	NE 1,650 LBS
(4) MULCH	WOOO CELLULOSE FIBER	750 LBS


APPROXIMATE TACK COAT


PROCEDURE: SURFACE TO BE HYDROSEEDED SHALL BE CLEANED OF ALL DEBRIS AND OTHER MATTER HARMFUL TO UNIFORM GERMINATION. A WATER-SURRY MIXTURE COMMPOSED OF THE ABOVE "MATERIALS". ITEMS (1) THROUGHT (3) INCLUSIVE, SHALL BE SPRAYED UNIFORMLY OVER THE AREAS TO BE HYDROSEEDED. IMMEDIATELY, THEREAFTER, ITEM (4) "MULCH" SHALL BE BLOWN ON THE SAME AREA AND TACK-COATED. RATES AND TYPE OF MATERIALS SHALL BE SPECIFIED.

MAINTENANCE AND CUARANTEE

THE CONTRACTOR SHALL GUARANTEE A GOOD STAND OF GRASS IN THE SWALES AND ON BANKS. THE MEANS OF GUARANTEE SHALL BE BY WATERING, MOWING, REGRADING, REMULCHING, AND RESEEDING TO THE SATISFACTION OF THE OWNER UNTIL FINAL ACCEPTANCE. ANY AREAS WHICH FAIL TO SHOW A UNIFORM STAND WITHIN ONE YEAR SHALL BE RESEEDED AND REMULCHED AT THE CONTRACTORS EXPENSE WITH THE SAME MIXTURE ORIGINALLY USED THEREON. ERODED AREAS SHALL BE REPAIRED AND RESTORED TO FINISHED GRADE PRIOR TO RESEEDING AND REMULCHING. ALL SUCH REPAIRING OF EROSION, RESEEDING, AND REMULCHING SHALL BE REPEATED UNTIL ALL EFFECTED AREAS ARE COVERED WITH GRASS.









West Virginia Department of Environmental Protection Office of Oil and Gas

WELL LC	CATION FORM: GPS	•
_{API:} 47-023-00013	WELL NO.: 2	21477-PI
FARM NAME: JB WEIME	R ETAL 2514	
RESPONSIBLE PARTY NAME:	CHESAPEAKE APPA	LACHIA LLC
COUNTY: GRANT	DISTRICT: UN	IION
QUADRANGLE: BLACKBI	RD KNOB	
SURFACE OWNER: CARL	EDWARD WEIMER	, JR
ROYALTY OWNER: CARL	EDWARD WEIMER	, JR
UTM GPS NORTHING: 4328		
UTM GPS EASTING: 648940		_{ION:} 2966'
The Responsible Party named above preparing a new well location plat for above well. The Office of Oil and Othe following requirements: 1. Datum: NAD 1983, Zon height above mean sea let 2. Accuracy to Datum – 3.0 3. Data Collection Method: Survey grade GPS × : Post President in the preparation of	or a plugging permit or assigned as will not accept GPS coordinate: 17 North, Coordinate Units: movel (MSL) – meters. 25 meters	API number on the es that do not meet
	ime Differential	MAR 2 \$ 2074
Mapping Grade GPS: Pos	t Processed Differential	and the second s
Rea	al-Time Differential	E.Witcheller 1997
4. Letter size copy of the of I the undersigned, hereby certify this belief and shows all the information prescribed by the Office of Oil and office of Oil	required by law and the regulation	knowledge and
Signature Signature	Title	3/21/24 Date



Kennedy, James P < james.p.kennedy@wv.gov>

plugging permits issued 4702300013 02300023 02300033

1 message

Kennedy, James P <james.p.kennedy@wv.gov>

Fri, Apr 19, 2024 at 9:41 AM

To: Gayne J Knitowski <gayne.j.knitowski@wv.gov>, Eric Haskins <eric.haskins@chk.com>, jours@assessor.state.wv.us

To whom it may concern, plugging permits have been issued for 4702300013 02300023 02300033.

James Kennedy

WVDEP OOG

3 attachments



4702300013.pdf 2172K



4702300033.pdf 2334K



4702300023.pdf 2764K