

Loc. Entered ✓

NOTICE OF INTENTION TO PLUG AND ABANDON WELL
(REQUIRED BY SECTION 8, CHAPTER 85, ACTS 1922)
WEST VIRGINIA DEPARTMENT OF MINES
OIL AND GAS SECTION

To THE DEPARTMENT OF MINES,
 Charleston, W. Va.

Consolidation Coal Company

COAL OPERATOR

Fairmont, W. Va.,

ADDRESS

HOPE Natural Gas Company

NAME OF WELL OPERATOR

448 West Main Street
Clermont, West Va.,

COMPLETE ADDRESS

September 11, 1929. 19

WELL TO BE ABANDONED

COAL OPERATOR

Coal District

ADDRESS

Harrison County

COAL OPERATOR

Well No. 7372

ADDRESS

S. A. Nixon Farm

Well is below the outcrop.

Gentlemen:—

The undersigned well operator is about to abandon the above described well and will commence the

work of plugging and abandoning said well on the 18th day of September, 1929,
 (which date shall be not less than five days after the day on which this notice so mailed is received, or in
 due course should be received by the Department of Mines).

This notice is given you in order that your respective representatives may be present at the plug-
 ging and filling of said well. You are further notified that whether you are represented or not repre-
 sented the undersigned will proceed on that date, or shortly thereafter, to plug and fill said well in the
 manner required by law.

This notice is being mailed by registered mail to each of you at the above addresses on the above date.

Very truly yours, Hope Natural Gas Company

SEP 13 1929

Asst. Genl. Supt.

[Handwritten Signature]

Well Operator

NOTE. Upon the abandonment of all wells drilled prior to June 1, 1929, a plat prepared by a competent engineer, showing the district and county in which the tract of land is located, the name and address of owner, the names of the owners of adjacent tracts, and the location of the well to be abandoned, with distances by survey, and the courses and distances of such well from two permanent points or landmarks on said tract, shall be submitted with this notice.

Log of well in which well no. 7574 D. A. 1127 was plugged

Commenced plugging well Sept. 10th, 1927 and well was plugged in the following manner.

Pulled and lashed out of hole 2737' 6" of 2" tubing, leaving in hole 260' 6" of 2" tubing and 3-8/8" X 2" Anchor packer set at 1434 ft. Filled hole from 2737' 6" to 2360 ft with clay and cavings then dumped in hole with bailer 100¢ cement at 2360 ft to seal hole. Then filled up solids with clay to 2000 ft and dumped in with bailer 100¢ cement to seal hole, then ~~bridged~~ bridged hole at 2000 ft then filled up solid with clay to 1800 ft. Then bailer 100¢ cement to seal hole. Then bridged hole at 1800 ft and filled up solid with ~~clay~~ clay to 1617 ft steel line measurement. Then put in one 6" wood wedge bridge 16 ft long dumped in with bailer 100¢ cement on top of 6-5/8" lead plug to seal hole. Then tested for gas 48 hours through 1/4" opening and gas would not light. Then pulled 260' 6" of 2-5/8" casing out of hole, leaving in hole 400' 9" of 6-5/8" casing, then filled hole solid with cement to seal hole. Then started to pull 8 1/2" casing, in pulling 8 1/2" casing, pulled five joints at a time filling hole solid with clay while pulling 8 1/2" casing out of hole up to 679 ft then dumped in with bailer 100¢ cement to seal hole. Then filled hole solid with clay from 679 ft to 494 ft then dumped in with bailer 100¢ cement to seal hole, then filled up solid with clay to 416 ft, then dumped in with bailer 100¢ cement to seal hole, then filled up solid with clay to 187 ft. tested for gas each morning while filling up hole

for 7 days no gas would not light through 1/4" opening. Then tried to pull 10" casing, could not pull same, then out 10" casing at 108' and could not pull then out 10" casing at 88 ft and could not pull. then unscrewed 10" casing down hole 18 ft, leaving in hole 108 ft 10" casing, then filled hole solid with clay from 107 ft to top of ground, then constructed concrete monument at top of hole, see reverse side for description of monument

TO BE MADE IN TRIPlicate TO TIME AND MANNER OF
PLUGGING AND FILLING WELL

(REQUIREMENT OF SECTION 8, CHAPTER 20, ACTS 1929)

WEST VIRGINIA DEPARTMENT OF MINES
OIL AND GAS SECTION

COAL OPERATOR

ADDRESS

COAL OPERATOR

ADDRESS

COAL OPERATOR

ADDRESS

NAME OF WELL OPERATOR

COMPLETE ADDRESS

ACTS 18, 1929 19

WELL AND LOCATION

District

County

Well No.

Farm

TO BE MADE IN TRIPlicate TO TIME AND MANNER OF PLUGGING AND FILLING WELL IN THE DEPARTMENT THE COPY TO BE RETURNED BY THE WELL OPERATOR AND THE OTHER COPY AND EXACT COPIES AS REQUIRED TO BE MAILED TO EACH COAL OPERATOR ABOVE NAMED AT THEIR RESPECTIVE ADDRESSES

AFFIDAVIT

STATE OF WEST VIRGINIA

COUNTY OF Farrison

O. Howard Talington and James W. Reed
being first duly sworn according to law depose and say that they are experienced in the work of plugging and filling oil and gas wells and were employed by Hope National Oil Co., well operator, and participated in the work of plugging and filling the above well, that said work was commenced on the 16th day of September, 1929, and that the well was plugged and filled in the following manner:

Manner in which sand was plugged: See reverse side of this sheet

Manner in which coal was plugged: See reverse side of this sheet

Description of monument: Used 4000 Cement and 10000 sand in building monument at top of hole size of monument 2' X 2' X 2' thick, monument extends 30" above surface, monument was reinforced with rock, 1" pipe and sand line.

THE ABOVE DESCRIPTIONS MUST BE IN DETAIL AND IN ACCORDANCE WITH THE PROVISIONS OF SECTION 8, CHAP. 20, ACTS 1929, and that the work of plugging and filling said well was completed on the 13th day of November, 1929.

And further deponents said not.

HW - 13-A
O. Howard Talington

Handwritten notes:
OK
11/13