



---

west virginia department of environmental protection

---

Office of Oil and Gas  
601 57th Street SE  
Charleston, WV 25304  
(304) 926-0450  
(304) 926-0452 fax

Earl Ray Tomblin, Governor  
Randy C. Huffman, Cabinet Secretary  
www.dep.wv.gov

November 19, 2015

## FINAL INSPECTION REPORT

### Well Permit Cancelled

CNX GAS COMPANY LLC ,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-103304, issued to CNX GAS COMPANY LLC , and listed below has been received in this office. The permit has been cancelled as of 11/19/2015.

James Martin  
Chief

Operator: CNX GAS COMPANY LLC  
Operator's Well No: AUD11DHS  
Farm Name: KORTAS, JANEY HANEY  
**API Well Number: 47-103304**  
Date Issued: 11/15/2013

Date Cancelled: 11/19/2015

Promoting a healthy environment.

11/20/2015

INSPECTORS PERMIT SUMMARY FORM

GPS YES [ ] NO [ ]

DATE STARTED/LOCATION: \_\_\_\_\_ OPERATOR: CNX GAS COMPANY LLC  
 DRILLING COMMENCED: \_\_\_\_\_ FARM: KORTAS, JANEY HANEY  
 TO DATE: \_\_\_\_\_ DEPTHS: \_\_\_\_\_ Well No: AUD11DHS  
 WATER DEPTHS: \_\_\_\_\_ COAL DEPTHS \_\_\_\_\_

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT.

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:
 

A. CONSTRUCTION	YES [ ] NO [ ] (2_PTS)	(4_PTS) _____
B. DRILLING	YES [ ] NO [ ] (2_PTS)	
  
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES [ ] NO [ ] (2\_PTS) (4\_PTS) \_\_\_\_\_
  
3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES [ ] NO [ ] (4\_PTS) (4\_PTS) \_\_\_\_\_
  
4. CONSTRUCTIONS:  
 WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?
 

A. ROAD DITCHES (1)_ (2)_ (3)_ (4)_ (PTS)	B. CROSS DRAINS (1)_ (2)_ (3)_ (4)_ (5)_ (PTS)	
C. CULVERTS (1)_ (2)_ (3)_ (4)_ (5)_ (PTS)	D. CREEK CROSSINGS (1)_ (2)_ (3)_ (PTS)	
E. DIVERSION DITCHES (1)_ (2)_ (3)_ (PTS)	F. BARRIERS (1)_ (2)_ (3)_ (PTS)	
G. TEMPORARY SEEDING YES [ ] NO [ ] (10_PTS)		

POINTS AVAILABLE FOR QUESTION 4: (33\_PTS) \_\_\_\_\_
  
5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES [ ] NO [ ] (2\_PTS) (2\_PTS) \_\_\_\_\_
  
6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES [ ] NO [ ] (9\_PTS) (9\_PTS) \_\_\_\_\_
  
7. RECLAMATION:
 

A. ROADWAY (1)_ (2)_ (3)_ (PTS)	B. LOCATION (1)_ (2)_ (3)_ (PTS)	
C. PITS (1)_ (2)_ (3)_ (PTS)	D. PIPELINES (1)_ (2)_ (3)_ (PTS)	
E. TANK DIKES (1)_ (2)_ (3)_ (PTS)	F. API INSTALLED YES [ ] NO [ ] (3_PTS)	
G. ADEQUATE SEEDING MATERIALS (1)_ (2)_ (3)_ (PTS)		
H. WAS SEED BED ADEQUATE (1)_ (2)_ (3)_ (PTS)		

POINTS AVAILABLE FOR QUESTION 7: (24\_PTS) \_\_\_\_\_
  
8. WAS RECLAMATION COMPLETED WITHIN:  
 6 MTHS OF TD 6\_PTS ONLY; 4 MTHS OF TD 12\_PTS ONLY; 2 MTHS OF TD 19\_PTS ONLY;  
 POINTS AVAILABLE FOR QUESTION 8: (19\_PTS) \_\_\_\_\_

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: \_\_\_\_\_

11-19-15  
DATE RELEASED


*Terrence Reynolds*  
INSPECTOR'S SIGNATURE

CANCELLED

RECORD INSPECTIONS TO THIS WELL ON PAGE 2



CANCELLED



Id	Bearing	Distance
L1	N 89°53'24" W	2417.49'
L2	N 68°39'09" E	3063.62'
L3	S 21°16'10" W	1204.73'
L4	S 65°26'00" W	1050.00'

Id	Radius	Arc Length
C1	573.70'	976.28'


NAD 27 WV NORTH SPC		
North	East	Description
215018.44'	1824209.25'	AUD11DHS
214581.90'	1823254.30'	TANGENT POINT
213735.10'	1823089.57'	LANDING POINT
208688.32'	1828501.58'	BOTTOM HOLE

NAD 83 ZONE 17 UTM COORDINATES		
North	East	Description
4,326,998.56 m	576,183.24 m	AUD11DHS
4,326,860.73 m	575,894.51 m	TANGENT PNT.
4,326,601.91 m	575,848.60 m	LANDING PNT.
4,325,091.74 m	577,522.96 m	BOTTOM HOLE

FILE NUMBER: M 14 P 03  
 DRAWING NUMBER: cnxaud11dhsr1.pcs  
 SCALE: 1" = 1,200'  
 MINIMUM DEGREE OF ACCURACY: Submeter  
 PROVEN SOURCE OF ELEVATION: DGPS Survey  
RTK Centimeter System

I THE UNDERSIGNED, HEREBY CERTIFY THAT THIS PLAT IS CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF AND SHOWS ALL THE INFORMATION REQUIRED BY LAW AND THE REGULATIONS ISSUED AND PRESCRIBED BY THE DEPARTMENT OF ENERGY.

(SIGNED) *J. Michael Evans*  
 J. Michael Evans, P. S. #900



STATE OF WEST VIRGINIA  
 DIVISION OF ENVIRONMENTAL PROTECTION  
 OFFICE OF OIL AND GAS  
 #10 McJUNKIN ROAD  
 NITRO, WV 25143-2506  
 FORM WW-6

LAND SURVEYING SERVICES  
 21 CEDAR LANE, BRIDGEPORT, WV 26330  
 PHONE: 304-842-2018 OR 842-5762

DATE: January 17, 2013  
 OPERATORS WELL NO.: AUD11DHS

WELL TYPE: OIL  GAS  LIQUID INJECTION  WASTE DISPOSAL   
 (IF "GAS") PRODUCTION  STORAGE  DEEP  SHALLOW   
 LOCATION: ELEVATION 1,525.94 (465.11 m) WATERSHED Buckhannon River  
 DISTRICT Union COUNTY Barbour  
 QUADRANGLE Audra 7.5'

API WELL NO. 47-001-03304H6A  
 STATE WV COUNTY Barbour PERMIT CANCELLED

SURFACE OWNER Janey Haney Kortas (Map 14 / Parcel 03) ACREAGE 302  
 OIL & GAS ROYALTY OWNER see four leases above LEASE ACREAGE 810.50  
 PROPOSED WORK: DRILL  CONVERT  DRILL DEEPER  REDRILL  FRACTURE OR STIMULATE  PLUG OFF OLD FORMATION   
 PERFORATE NEW FORMATION  OTHER PHYSICAL CHANGE (SPECIFY) Horizontal  
 TARGET FORMATION Marcellus PLUG & ABANDON  CLEAN OUT & REPLUG   
 ESTIMATED DEPTH TVD=8,000' / TMD=18,200'  
 WELL OPERATOR CNX Gas Company LLC DESIGNATED AGENT Jeremy Jones  
 ADDRESS P. O. Box 1248, Jane Lew, WV 26378 ADDRESS P. O. Box 1248, Jane Lew, WV 26378

COUNTY NAME  
 PERMIT

11/20/2015