



---

west virginia department of environmental protection

---

Office of Oil and Gas  
601 57<sup>th</sup> Street, S.E.  
Charleston, WV 25304  
(304) 926-0450  
fax: (304) 926-0452

Harold D. Ward, Cabinet Secretary  
[www.dep.wv.gov](http://www.dep.wv.gov)

Thursday, February 17, 2022  
NOTICE OF PERMIT CANCELLATION  
Horizontal 6A / New Drill

ANTERO RESOURCES CORPORATION  
1615 WYNKOOP STREET

DENVER, CO 80202

Re: Permit cancellation for PETER UNIT 1H  
47-017-06866-00-00

The FINAL INSPECTION REPORT for the CANCELLED PERMIT, issued for U.S. Well Number 47-017-06866-00-00 , has been received by the Office of Oil and Gas. The permit has been cancelled as of 2/17/2022 .

If there are any questions, please feel free to contact me at (304) 926- 0450.

A handwritten signature in blue ink, appearing to read 'James A. Martin', is written over a light blue circular stamp.

James A. Martin  
Chief

Operator's Well Number: PETER UNIT 1H  
Farm Name: PHILLIP N. HILL ET AL  
U.S. WELL NUMBER: 47-017-06866-00-00  
Horizontal 6A New Drill  
Date Cancelled: 2/17/2022

Promoting a healthy environment.

02/25/2022

INSPECTORS PERMIT SUMMARY FORM

PAGE 1

GPS YES \_\_\_ NO X

DATE STARTED/LOCATION: Cancel Never Drilled API #: 47-017-06866 WELL NO. Peter Unit 1H  
 DRILLING COMMENCED: \_\_\_\_\_ OPERATOR: Anders Resources Corporation  
 TD DATE: \_\_\_\_\_ DEPTH: \_\_\_\_\_ FARM: Phillip N. Hill ETAL  
 WATER DEPTHS \_\_\_\_\_ COAL DEPTHS \_\_\_\_\_

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:  
 A. CONSTRUCTION YES \_\_\_ NO \_\_\_ (2 PTS) B. DRILLING YES \_\_\_ NO \_\_\_ (2 PTS) (4 PTS) 0  
 2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES \_\_\_ NO \_\_\_ (4 PTS) (4 PTS) 0  
 3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES \_\_\_ NO \_\_\_ (4 PTS) (4 PTS) 0

4. CONSTRUCTION:  
 WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?  
 A. ROAD DITCHES 1 \_\_\_ 2 \_\_\_ 3 \_\_\_ 4 \_\_\_ (PTS) B. CROSS DRAINS 1 \_\_\_ 2 \_\_\_ 3 \_\_\_ 4 \_\_\_ 5 \_\_\_ (PTS)  
 C. CULVERTS 1 \_\_\_ 2 \_\_\_ 3 \_\_\_ 4 \_\_\_ 5 \_\_\_ (PTS) D. CREEK CROSSINGS 1 \_\_\_ 2 \_\_\_ 3 \_\_\_ (PTS)  
 E. DIVERSION DITCHES 1 \_\_\_ 2 \_\_\_ 3 \_\_\_ (PTS) F. BARRIERS 1 \_\_\_ 2 \_\_\_ 3 \_\_\_ (PTS)  
 G. TEMPORARY SEEDING YES \_\_\_ NO \_\_\_ (10 PTS) POINTS AVAILABLE FOR QUESTION 4: (33 PTS) 0

5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES \_\_\_ NO \_\_\_ (2 PTS) (2 PTS) 0  
 6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES \_\_\_ NO \_\_\_ (9 PTS) (9 PTS) 0

7. RECLAMATION:  
 A. ROADWAY 1 \_\_\_ 2 \_\_\_ 3 \_\_\_ (PTS) B. LOCATION 1 \_\_\_ 2 \_\_\_ 3 \_\_\_ (PTS)  
 C. PITS 1 \_\_\_ 2 \_\_\_ 3 \_\_\_ (PTS) D. PIPELINES 1 \_\_\_ 2 \_\_\_ 3 \_\_\_ (PTS)  
 E. TANK DIKES 1 \_\_\_ 2 \_\_\_ 3 \_\_\_ (PTS) F. API INSTALLED YES \_\_\_ NO \_\_\_ (3 PTS)  
 G. ADEQUATE SEEDING MATERIALS 1 \_\_\_ 2 \_\_\_ 3 \_\_\_ (PTS)  
 H. WAS SEED BED ADEQUATE 1 \_\_\_ 2 \_\_\_ 3 \_\_\_ (PTS) POINTS AVAILABLE FOR QUESTION 7: (24 PTS) 0

8. WAS RECLAMATION COMPLETED WITHIN:  
 A. CONVENTIONAL:  
 6 MTHS OF TD \_\_\_ 6 PTS ONLY; 4 MTHS OF TD \_\_\_ 12 PTS ONLY; 2 MTHS OF TD \_\_\_ 19 PTS ONLY.  
 B. HORIZONTAL:  
 3 YRS OF PAD COMPLETION \_\_\_ 19 PTS ONLY; 4 YRS OF PAD COMPLETION \_\_\_ 16 PTS ONLY;  
 5 YRS OF PAD COMPLETION \_\_\_ 13 PTS ONLY

MAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS) 0

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: 0

2/10/2022  
DATE RELEASED

S. D. W. Smith  
INSPECTOR

Cancel Never Drilled

02/18/2022