

INSPECTORS REPORT

Operator: Consolidation Coal Company

API Number: 47-049-00177 R-278

Findings:

The rig is cleaning hole and preparing to start plugging. No problems were found during this inspection.

Does this inspection identify any dust issues? Yes No. If Yes, explain.

Sam Ward

Oil & Gas Inspector

11/7/2018

Date