



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street, S.E.
Charleston, WV 25304
(304) 926-0450
fax: (304) 926-0452

Harold D. Ward, Cabinet Secretary
www.dep.wv.gov


Monday, March 29, 2021
NOTICE OF PERMIT CANCELLATION
Horizontal 6A / Horizontal 6A Well - 1

TRANS ENERGY, INC.
P O BOX 393
210 SECOND STREET
ST. MARYS, WV 26170

Re: Permit cancellation for ELLIOTT 2H
47-049-02303-00-00

The FINAL INSPECTION REPORT for the CANCELLED PERMIT, issued for U.S. Well Number 47-049-02303-00-00 , has been received by the Office of Oil and Gas. The permit has been cancelled as of 3/29/2021 .

If there are any questions, please feel free to contact me at (304) 926- 0450.



James A. Martin
Chief

Operator's Well Number: ELLIOTT 2H
Farm Name: CONSOLIDATION COAL COMPANY
U.S. WELL NUMBER: 47-049-02303-00-00
Horizontal 6A Horizontal 6A Well - 1
Date Cancelled: 3/29/2021

Promoting a healthy environment.

04/02/2021

PAGE 1

GPS YES NO

DATE STARTED/LOCATION: API #: 4902303 WELL NO. Elliott 2H
 DRILLING COMMENCED: OPERATOR: Trans Energy
 TD DATE: DEPTH: FARM:
 WATER DEPTHS COAL DEPTHS

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:
 A. CONSTRUCTION YES NO (2 PTS) B. DRILLING YES NO (2 PTS) (4 PTS) _____

2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES NO (4 PTS) (4 PTS) _____

3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES NO (4 PTS) (4 PTS) _____

4. CONSTRUCTION:

WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?

A. ROAD DITCHES 1 2 3 4 (PTS) B. CROSS DRAINS 1 2 3 4 5 (PTS)
 C. CULVERTS 1 2 3 4 5 (PTS) D. CREEK CROSSINGS 1 2 3 (PTS)
 E. DIVERSION DITCHES 1 2 3 (PTS) F. BARRIERS 1 2 3 (PTS)
 G. TEMPORARY SEEDING YES NO (10 PTS) POINTS AVAILABLE FOR QUESTION 4: (33 PTS) _____

5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES NO (2 PTS) (2 PTS) _____

6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES NO (9 PTS) (9 PTS) _____

7. RECLAMATION:

A. ROADWAY 1 2 3 (PTS) B. LOCATION 1 2 3 (PTS)
 C. PITS 1 2 3 (PTS) D. PIPELINES 1 2 3 (PTS)
 E. TANK DIKES 1 2 3 (PTS) F. API INSTALLED YES NO (3 PTS)
 G. ADEQUATE SEEDING MATERIALS 1 2 3 (PTS)
 H. WAS SEED BED ADEQUATE 1 2 3 (PTS) POINTS AVAILABLE FOR QUESTION 7: (24 PTS) _____

8. WAS RECLAMATION COMPLETED WITHIN:

6 MTHS OF TD ___ 6 PTS ONLY; 4 MTHS OF TD ___ 12 PTS ONLY; 2 MTHS OF TD ___ 19 PTS ONLY.

MAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS) _____

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: _____

INSPECTIONS:

Needs Canceled

3-29-21
DATE RELEASED

Bayan Harris
INSPECTOR

04/02/2021