(REV 08)							
]	INSPECTORS PE	RMIT SU					
	Old 4 D 1 M	/D 0.5	G	PS YES [] NO[]		
DATE STARTED/LOCATION: 3/28/2014		/R-35	OPERATO	R: CHE	VRON APPALAC	N APPALACHIA, LLC	
DRILLING COMMENCED: never drilled			FARM:	KNA	KNABENSHUE, SARAH J. ET AL		
TO DATE: <u>n/a</u>	DEPTHS:n/a_		Well No:	CON	NER 1HR		
WATER DEPTHS:			COAL DE	PTHS			
QUESTIONS FOR THIS REPO 4-12.1 AND 35CSR 4-16 AND						ONS 35CSR	
POINTS ARE TO BE GIVEN	I UP TO MAXIMI	J M AS SH	OWN BASE	ED ON PER	FORMANCE.		
1. DID OPERATOR GIVE P	ROPER NOTICE T	O INSPEC	TOR BEFO	RE THE FO	LLOWING:		
A. CONSTRUCTION			NO[](2			(4_PTS)	
B. DRILLING		YES[]	NO[] (2	_PTS)		` _ ′	
2. WAS THE TIMBER CUT, BEFORE DIRT WORK ST			SED FOR SE		ARRIERS	(4_PTS)	
3. ARE ALL LOCATION AN	D/OR ROAD BAN	KS BEING	SLOPED?	YES[]	NO[] (4_PTS)	(4_PTS)	
4. CONSTRUCTIONS: WERE THE FOLLOWING A. ROAD DITCHES C. CULVERTS E. DIVERSION DITCHES G. TEMPORARY SEEDIN	(1)_(2)_(3)_(4)_ (1)_(2)_(3)_(4)_ S (1)_(2)_(3)_(PT	_(PTS) _(5)_(PTS) S)	B. CROSSD. CREEFF. BARR	S DRAINS K CROSSIN		(4)_(5)_(PTS) (PTS)	
G. TEMI ORUM BEEDI	TEO [] INC		•	ARLE FOR	QUESTION 4:	(33_PTS)	
5. HAS TOP SOIL (IF ANY)	BEEN STOCKED				•	(2_PTS)	
6. IS THE PIT PROPERLY II			_			(9_PTS)	
7. RECLAMATION:		VAL ALL \ 1. AL	.22. 120[,	(>_1 ()	(>_1 15)	
A. ROADWAY	(1)_(2)_(3)_(PTS)	E	B. LOCATIO	NC	(1)_(2)_(3)_(P	ΓS)	
	(1)_(2)_(3)_(PTS)		D. PIPELIN		(1)_(2)_(3)_(P		
	(1)_(2)_(3)_(PTS)	F	E. API INST	TALLED	YES[] NO	[] (3_PTS)	
G. ADEQUATE SEEDING		(1)_(2)_(3	3)_(PTS)				
H. WAS SEED BED ADE	EQUATE	(1)_(2)_(3	3)_(PTS)				
		POI	NTS AVAILA	ABLE FOR	QUESTION 7:	(24_PTS)	
8. WAS RECLAMATION CO							
6 MTHS OF TD 6_PTS O	NLY; 4 MTHS O	F TD 12_P	TS ONLY;	2 MTHS OF	FTD 19_PTS ON	LY;	
		POI	NTS AVAILA	ABLE FOR	QUESTION 8:	(19_PTS)	

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

never drilled
Permit Expired 1/8/2017

DATE RELEASED

INSPECTOR'S SIGNATURE

TOTAL RECLAMATION SCORE:

INSPECTIONS: