IR - 26 (REV 08)

INSPECTORS PERMIT SUMMARY FORM

GPS YES [] NO []

DATE STARTED/LOCATION:	6/23/2014	OPERATOR:	SWN PRODUCTION CO	OMPANY, LLO
DRILLING COMMENCED:	never drilled	FARM:	STROPE, RUSSELL W.	
TO DATE: <u>n/a</u>	DEPTHS:	Well No:	CRAIG STROPE MSH 2	01H
WATER DEPTHS:		COAL DEPTHS	· · · · · · · · · · · · · · · · · · ·	
QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT.				
POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.				
1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:				
A. CONSTRUCTION] NO[] (2_PTS	•	(4_PTS)
B. DRILLING] NO[] (2_PTS)		
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS (4_PTS) BEFORE DIRT WORK STARTED? YES [] NO [] (2_PTS)				
3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES [] NO [] (4_PTS) (4_PTS)				
 4. CONSTRUCTIONS: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED? A. ROAD DITCHES (1)_(2)_(3)_(4)_(PTS) B. CROSS DRAINS (1)_(2)_(3)_(4)_(5)_(PTS) C. CULVERTS (1)_(2)_(3)_(4)_(5)_(PTS) D. CREEK CROSSINGS (1)_(2)_(3)_(PTS) E. DIVERSION DITCHES (1)_(2)_(3)_(PTS) F. BARRIERS (1)_(2)_(3)_(PTS) G. TEMPORARY SEEDING YES[] NO[] (10_PTS) 				
	PC	DINTS AVAILABL	E FOR QUESTION 4:	(33_PTS)
5. HAS TOP SOIL (IF ANY)	BEEN STOCKED PILED?	YES []	NO[] (2_PTS)	(2_PTS)
6. IS THE PIT PROPERLY IN	STALLED AND MAINTA	INED? YES []	NO[] (9_PTS)	(9_PTS)
7. RECLAMATION:				
	(1)_(2)_(3)_(PTS)	B. LOCATION	(1)_(2)_(3)_(PTS)
		D. PIPELINES	(1)_(2)_(3)_(PTS	•
	(1)_(2)_(3)_(PTS)	F. API INSTALL	ED YES [] NO [] (3_PTS)
G. ADEQUATE SEEDING		_(3)_(PTS)		
H. WAS SEED BED ADE		_(3)_(PTS)		
	PO	DINTS AVAILABLE	FOR QUESTION 7:	(24_PTS)
 WAS RECLAMATION COMPLETED WITHIN: 6 MTHS OF TD 6_PTS ONLY; 4 MTHS OF TD 12_PTS ONLY; 2 MTHS OF TD 19_PTS ONLY; 				
				(19_PTS)
TOTAL MAXIMUM POSSIBLE SCORE OF 99. TOTAL RECLAMATION SCORE:				
never drilled Permit Expired 2/5/20	018	IOTALK	June Vicherland	
DATE RELEASED		The	SPECTOR'S SIGNATURE	

RECORD INSPECTIONS TO THIS WELL ON PAGE 2

IR - 26 PAGE 2

.

API No. 47-5101876

INSPECTIONS:

.