IR-26 Rev 08	INSPECTORS PERMIT SUMMARY FORM	09/28/2018
PAGE 1	GPS YES NO	
DATE STARTED/LOCATIO	N: already existing API #: 47-051-01940-00-00 WELL NO. AR	
DRILLING COMMENCED:		THUR WARYCK UP MSH 7H
TD DATE: n/a		
WATER DEPTHS	COAL DEPTHS	L & DEBORAH ELLEN
QUESTIONS FOR THIS REF AND REGULATIONS 35CS	ORT ARE IN ACCORDANCE OF WV CODE 22-6-30 R 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTR	ROL PERMIT
POINTS ARE TO BE GIVE	N UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.	
1. DID OPERATOR GIVE PE	OPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:	
A. CONSTRUCTION YES	NO (2_PTS) B. DRILLING YES NO (2_PTS)	(4 PTS)
2. WAS THE TIMBER CUT,	STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE	(4115)
DIRT WORK STARTED?	YES NO (4_PTS)	(4 PTS)
	ND/OR ROAD BANKS BEING SLOPED? YES NO (4_PTS)	(4 PTS)
4. CONSTRUCTION: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?		
A. ROAD DITCHES (1) (2)	B. CROSS DRAINS (1) (2) (3) (4) (5) (PTS)	D?
C. CULVERTS (1)_(2)_(3)_ E. DIVERSION DITCHES ($(4)_(5)_(PTS).$ D. CREEK CROSSINGS $(1)_{(2)}_{(3)}$ (PTS)	
G. TEMPORARY SEEDING	1)_(2)_(3)_(PTS) F. BARRIERS (1)_(2)_(3)_(PTS) YES NO (10_PTS) POINTS AVAILABLE FOR QUESTION 4:	(33 PTS)
5. HAS TOP SOIL (IF ANY)	BEEN STOCKED PILED? YES NO 2_PTS)	(2 PTS)
6. IS THE PIT PROPERLY IN	ISTALLED AND MAINTAINED? YES NO (9 PTS)	(9 PTS)
7. RECLAMATION: A. ROADWAY (1)_(2)_(3)_ C. PITS (1)_(2)_(3)_(PTS E. TANK DIKES (1)_(2)_(3) G. ADEQUATE SEEDING M H. WAS SEED BED ADEQU) D. PIPELINES (1)_(2)_(3)_(PTS))_(PTS) F. API INSTALLED YES OR NO 3_(PTS) ATERIALS (1) (2) (3) (PTS)	(24 PTS)
& WAS RECLAMATION CO	MPI ETED WITHIN:	
MTHS OF TD 6_PTS O		(19 PTS)
TOTAL MAXIMUM PO	SSIBLE SCORE OF 99.	
TOTAL RECLAMATION SCORE:		
INSPECTIONS:		
Brittanny Woody, Regulatory Analy	st for Southwestern Energy, requested cancellation of permit via email on 9/24/2018.	
	1 () -	
cancelled per SWN 9/25/18	the alexan	
DATE RELEASED	INSPECTOR	