IR-26 Rev 19

INSPECTORS PERMIT SUMMARY FORM

Sec."

PAGE 1			GPS YES	5 NO	
DATE STARTED/LOCATION:	11/15/2010	API #:	47-051-01946	WELL NO.	UD MSH 4H
DRILLING COMMENCED:	ever drilled OPE	RATOR:	SWN Productio	n Company, L	LC
TD DATE: never drilled	DEPTH: n	/a	FARM: Colu		nsmission, LLC
WATER DEPTHS QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT					
POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.					
 DID OPERATOR GIVE PROPER A. CONSTRUCTION YES N WAS THE TIMBER CUT, STAC DIRT WORK STARTED? YES 	O (2 PTS) B CKED, AND BRUSH USE	DRILLING	YES NO	_(2 PTS)	(4 PTS) (4 PTS)
3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES NO (4 PTS)					
4. CONSTRUCTION: WERE THE FOLLOWING SEDIM A. ROAD DITCHES 12_3_ C. CULVERTS 1_2_3_4 E. DIVERSION DITCHES 12	4 (PTS) 5 (PTS) 3 (PTS)	B. CROSS D. CREEK F. BARRIE	DRAINS 12 CROSSINGS 1 ERS 123_	345 23(P' (PTS)	(PTS) I'S)
G. TEMPORARY SEEDING YES	NO (10 PTS)	POINTS A	VAILABLE FOR	QUESTION 4:	(33 PTS)
5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES NO (2 PTS)					(2 PTS)
6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES NO (9 PTS)					(9 PTS)
7. RECLAMATION: A. ROADWAY 12_3(P C. PITS 12_3(PTS) E. TANK DIKES 12_3(G. ADEQUATE SEEDING MATER H. WAS SEED BED ADEQUATE 1	D. PIPELIN PTS) F. API INST IALS 12_3_ (P	ES 12 FALLED Y TS)	3(PTS) /ESNO(3 I		(24 PTS)
8. WAS RECLAMATION COMPLE A. CONVENTIONAL: 6 MTHS OF TD6 PTS B. HORIZONTAL:		ՐD12 Բ	PTS ONLY; 2 N	ATHS OF TD	19 PTS ONLY.
3 YRS OF PAD COMPLET 5 YRS OF PAD COMPLET	ION 13 PTS ONLY				
	MAXIMUM I	'OINTS AV	AILABLE FOR (QUESTION 8:	(19 PTS)
TOTAL MAXIMUM POSSIBI	LE SCORE OF 99.				

Permit Cancelled-Never Drilled 12/5/2019

June Vichorborn

TOTAL RECLAMATION SCORE: n/a