## State of West Virginia Office of Oil and Gas

## **INSPECTORS REPORT**

Operator:	UNKNOWN OPERA	TOR
API Number:	47 - 059 - 00682	WELL 2
FINDING:		
I completed a preplug site inspection on 11/21/2018. The well is in a valley fill. The well will be covered up to 150 Ft after plugging is completed.		
Does this inspection identify any dust issues? YESNO If yes, explain.		
AllanFlo		
11/21/2	018	
Date		