D

_____Operator Well No.: <u>F2-503</u>

STATE OF WEST VIRGINIA DEPARTMENT OF ENVIRONMENTAL PROTECTION OFFICE OF OIL AND GAS

AFFIDAVIT OF PLUGGING AND FILLING WELL

AFFIDAVIT SHOULD BE IN TRIPLICATE, one copy mailed to the Department, one copy to be retained by the Well Operator and the third copy (and extra copies if required) should be mailed to each coal operator at their respective addresses.

Farm name: Sarah Wilson tract, current- Clyde Wilson, Hrs.

LOCATION: Elevation: 1,319' Quadrangle: Blacksville	
District: Clay County: Monongalia	
Latitude: 13,456 Feet South of 39 Deg. 42 Min. 30 Sec	
Longitude: 8,783 Feet West of 80 Deg. 12 Min. 30 Sec.	
Well Type: OIL GAS _X_	
Company: Footory Associated On 1 O	
Company: <u>Eastern Associated Coal Corp.</u> Coal Operator <u>Eastern Associated Coal Corp.</u>	
1044 Miracle Run Road or Owner 1044 Miracle Run Road	
Fairview, WV 26570 Fairview, WV 26570	
Coal Operator	
Agent: Edward Y. Hoy or Owner	
Permit Issued Date: May 25, 2004	
A ECID AND	
AFFIDAVIT STATE OF WEST VIRGINIA,	
County I at a	
Mens of being first duly sworn according to law depose and say that they are experienced in the work of plugging and filling oil and gas	
according to law denose and say that thou are experienced in the world	
wells and were employed by the above named well are experienced in the work of plugging and filling oil and gas	
wells and were employed by the above named self-based in the work of plugging and filling the above well and Torrellabor Olland Operator, and participated in the work of plugging	
and filling the above well, and Terry Urban, Oil and Gas Inspector representing the Director, say that	
said work was commenced on the 14 th day of September, 2004, and that the well was plugged and filled in the following manner:	
TYPE TOO TOO TOO TOO TOO TOO TOO TOO TOO TO	
COLUMN TO THE PRINT OF THE PRIN	
Cleaned out to 893' with 10" bit. Cleaned out to 923' with 8" bit. Cleaned out to 1,300' with 6" bit.	
Logged Hole with Century Geophysical. Pittsburgh coal at 990' to 996' from logs	
Ran 1-1/2" tubing to 1,300' and pumped bottom with 100 sacks of cement and 2 sacks of gel	
Cleaned back out to 1,094' (100' below the coal).	
Ran 1,100' of 4-1/2" casing with latch down plug at 1,080'.	
Pumped top plug through 4-1/2" casing with 640 sacks of cement 105 sacks of F1K cement and 3 gol	
Did not get return. Following day ran 316' of 1-1/2" tubing outside of 4-1/2" casing to finish top plug.	
Pumped total of 315 additional sacks of cement to complete the top plug.	
Swabbed water off latch down plug at 1,082'	
Note: Pulled very little steel from the hole. Logo show easing "settles" the	
Note: Pulled very little steel from the hole. Logs show casing "rotten" through the coal seam horizon.	
Description of monument: 4 1/2" Pine with motal plate. A DL # and data along the later than the	
Description of monument: 4 ½" Pipe with metal plate, API #, and date plugged and that the worldflide of Oil & O Office of Chie	
And furthur deponents saith not.	л [
) <i>)</i> .
DEC 2 7 200	75
from Whelle	
Sworn and subscribe before me this 20 day of DECEUSE 2004 WV Department Professional Professiona	
Sworn and subscribe before me this 20 day of <u>VECEUBER</u> , 2004 My commission expires: 2001	ection
JAN 0 7 2	2005
VAILANTE	,00J
OFFICIAL SEAL	1
Notary-Public Notary Public	<i>y</i>
Oil and Gas Inspector: Wall Aland 3/07	HIGHA
SOS Altra Visto Avenue	e }
Fairmont, West Virginia 2	3554

4 6841 ONOW