IR-8
(REV 4-99)

API NO.: 47-061-01825

# WELL PLUGGING INSPECTION & RELEASE FORM

PLUGGING COMMENCED_____
PLUGGING COMPLETED_____
VERBAL PERMISSION ON_____

OPERATOR: Colidated Coal Co.
FARM: Consol Mining Co.
WELL NO: 4376

1. IS COAL BEING MINED IN THE AREA? YES ✔ NO N/A

2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS?
   - A. BOTTOM HOLE PLUGGED YES ✔ NO N/A
   - B. 100' PLUGS YES ✔ NO N/A
   - C. LATEX PLUGS USED FOR $H_2S$ GAS YES NO N/A ✔
   - D. PROPER PLUGS THROUGH COAL SEAMS YES ✔ NO N/A
   - E. PROPER PLUGS SET TO PROTECT FRESHWATER YES ✔ NO N/A
   - F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS YES NO N/A ✔

| TYPE | FROM | TO | PIPE REMOVED |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

3. WERE ALL CHANGES APPROVED BY INSPECTOR? YES ✔ NO

4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? YES ✔ NO

5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? YES ✔ NO

6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? YES ✔ NO

7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? YES ✔ NO

8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS?
   - A. RECLAIMED YES ✔ NO
   - B. FENCES REPLACED YES ✔ NO
   - C. MULCHED YES ✔ NO
   - D. PROPER DRAINAGE YES ✔ NO
   - E. SEEDED YES ✔ NO
   - F. ALL EQUIPMENT REMOVED YES ✔ NO
   - G. PIT BACKFILLED YES ✔ NO

6-6-19
DATE RELEASED

Gayne Knitowski
INSPECTOR'S SIGNATURE

**RECORD ALL VISITS TO THIS WELL ON PAGE 2**

**IR-8**
**PAGE 2**
**API NO:** 47-061-01825

| DATE | VISITS |
| --- | --- |