



7.5' loc  
 0.50 S 37°32'30"  
 2.09 W 79°47'30"  
 15' loc calc  
 3.38 S  
 4.34 W

3.50 S.  
 4.44 W.  
 7 WC (I-12)

New Location...   
 Drill Deeper.....   
 Abandonment.....

Company BENEDUM-TREES OIL COMPANY  
 Address BENEDUM-TREES BUILDING  
PITTSBURGH 22, PENNA.  
 Farm A.C. SIMMONS  
 Tract \_\_\_\_\_ Acres 30 Lease No. \_\_\_\_\_  
 Well (Farm) No. 1 Serial No. \_\_\_\_\_  
 Elevation (Spirit Level) 2960  
 Quadrangle DURBIN-SE Greenbank 7.5' grid  
 County POCAHONTAS District GREEN BANK  
 Engineer D.W. Carpenter  
 Engineer's Registration No. 765  
 File No. E2-5259 Drawing No. \_\_\_\_\_  
 Date 5-2-59 Scale 1"=300'

STATE OF WEST VIRGINIA  
 DEPARTMENT OF MINES  
 OIL AND GAS DIVISION  
 CHARLESTON

WELL LOCATION MAP

FILE NO. Poca-16

+ Denotes location of well on United States Topographic Maps, scale 1 to 62,500, latitude and longitude lines being represented by border lines as shown.  
 - Denotes one inch spaces on border line of original tracing.

No Samples 5-0-0 very Deep Well



STATE OF WEST VIRGINIA  
DEPARTMENT OF MINES  
OIL AND GAS DIVISION *22*

Quadrangle Durbin

WELL RECORD

Permit No. POCA-16

Oil or Gas Well Dry  
(KIND)

Company Benedum-Trees Oil Company  
Address Benedum-Trees Building, Pittsburgh  
Farm A. C. Simmons Acres 30  
Location (waters) See reverse  
Well No. 1 Elev. 2960  
District Greenbank County Pocahontas  
The surface of tract is owned in fee by Simmons  
Durbin, W. Va. Address  
Mineral rights are owned by same  
Address  
Drilling commenced 5-19-59  
Drilling completed 8-19-59  
Date Shot From To  
With  
Open Flow /10ths Water in dry Inch  
/10ths Merc. in dry Inch  
Volume Cu. Ft.  
Rock Pressure lbs. hrs.  
Oil bbls., 1st 24 hrs.  
WELL ACIDIZED none  
WELL FRACTURED none

Casing and Tubing	Used in Drilling	Left in Well	Packers
Size			Kind of Packer
16			
13			
10 9 5/8	1206	1206	Size of
8 1/4			Depth set
6 5/8			
5 3/16			
3			Perf. top
2			Perf. bottom
Liners Used			Perf. top
			Perf. bottom

CASING CEMENTED SIZE 9 5/8 No. Ft. 6-10 Date  
425 sacks

COAL WAS ENCOUNTERED AT none FEET INCHES  
FEET INCHES FEET INCHES  
FEET INCHES FEET INCHES

RESULT AFTER TREATMENT

ROCK PRESSURE AFTER TREATMENT

Fresh Water unknown Feet Salt Water 5790 Feet

Formation	Color	Hard or Soft	Top	Bottom	Oil, Gas or Water	Depth	Remarks
Lime	gray	Hard	0	196			
Shale	"	"	196	558			
Lime	"	"	558	954			
Sand	"	"	954	1207			
Shale	"	"	1207	5415			Calcareous
Lime	"	"	5415	5560			
Chert	clear	"	5560	5700			
Sand	"	"	5700	5900	<i>Onondagan</i> <i>Oriskany</i>	5790	Salt water
Lime	gray	"	5900	6702	none		
Shale	"	Soft	6702	6928			
Lime	"	Hard	6928	7349		5560	
Shale	dark	"	7349	7397		2960	
Lime	"	"	7397	7534		2500	
Sand-shale	light	"	7534	7577			
Lime	white	"	7577	7750			
Shale	brown	"	7750	7900			
Sand	white	"	7900	8120	<i>White Medina (Tudcarora)</i>		
Sand	red	"	8120	8210	<i>Red Medina</i>		
Sand	red, gray, green	"	8210	8327			Total depth
							8120 2960 5160

(over)



*Dry*

Formation	Color	Hard or Soft	Top <u>22</u>	Bottom	Oil, Gas or Water	Depth Found	Remarks
Location: 17700' South of 38 35' 23000' West of 79 45' 1200' East of Greenbrier River							

A&P RECORDED

Date August 20, 19 59  
 APPROVED BENLDUM-TREES OIL COMPANY, Owner  
 By \_\_\_\_\_, Field Supt.  
 (Title)