



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street SE
Charleston, WV 25304
(304) 926-0450
(304) 926-0452 fax

Earl Ray Tomblin, Governor
Randy C. Huffman, Cabinet Secretary
www.dep.wv.gov

August 12, 2015

FINAL INSPECTION REPORT

Well Permit Cancelled

ANTERO RESOURCES APPALACHIAN CORPORATION,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-8510022, issued to ANTERO RESOURCES APPALACHIAN CORPORATION, and listed below has been received in this office. The permit has been cancelled as of 8/10/2015.

James Martin
Chief

Operator: ANTERO RESOURCES APPALACHIAN CO
Operator's Well No: MCCABE UNIT 2H
Farm Name: ANDREW WILLIAMSON ET AL
API Well Number: 47-8510022
Date Issued: 02/19/2013

Date Cancelled: 08/10/2015

Promoting a healthy environment.

08//14/2015

2-29-13

INSPECTORS PERMIT SUMMARY FORM

GPS YES [] NO []

DATE STARTED LOCATION: Received

OPERATOR: ANTERO RESOURCES APPALACH

DRILLING COMMENCED: _____

FARM: ANDREW WILLIAMSON ET AL

TO DATE: _____ DEPTHS: AUG 12

Well No: MCCABE UNIT 2H

WATER DEPTHS: _____

COAL DEPTHS _____

Office of Oil and Gas
WV Dept. of Environmental Protection

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT.

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

- 1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:
 - A. CONSTRUCTION YES [] NO [] (2_PTS) (4_PTS)
 - B. DRILLING YES [] NO [] (2_PTS)

- 2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES [] NO [] (2_PTS) (4_PTS)

- 3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES [] NO [] (4_PTS) (4_PTS)

- 4. CONSTRUCTIONS: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?
 - A. ROAD DITCHES (1)_ (2)_ (3)_ (4)_ (PTS)
 - B. CROSS DRAINS (1)_ (2)_ (3)_ (4)_ (5)_ (PTS)
 - C. CULVERTS (1)_ (2)_ (3)_ (4)_ (5)_ (PTS)
 - D. CREEK CROSSINGS (1)_ (2)_ (3)_ (PTS)
 - E. DIVERSION DITCHES (1)_ (2)_ (3)_ (PTS)
 - F. BARRIERS (1)_ (2)_ (3)_ (PTS)
 - G. TEMPORARY SEEDING YES [] NO [] (10_PTS)

POINTS AVAILABLE FOR QUESTION 4: (33_PTS)

- 5. HAS TOP SOIL (IF ANY) BEEN STOCKED/PILED? YES [] NO [] (2_PTS) (2_PTS)

- 6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES [] NO [] (9_PTS) (9_PTS)

- 7. RECLAMATION:
 - A. ROADWAY (1)_ (2)_ (3)_ (PTS)
 - B. LOCATION (1)_ (2)_ (3)_ (PTS)
 - C. PITS (1)_ (2)_ (3)_ (PTS)
 - D. PIPELINES (1)_ (2)_ (3)_ (PTS)
 - E. TANK DIKES (1)_ (2)_ (3)_ (PTS)
 - F. API INSTALLED YES [] NO [] (3_PTS)
 - G. ADEQUATE SEEDING MATERIALS (1)_ (2)_ (3)_ (PTS)
 - H. WAS SEED BED ADEQUATE (1)_ (2)_ (3)_ (PTS)

POINTS AVAILABLE FOR QUESTION 7: (24_PTS)

- 8. WAS RECLAMATION COMPLETED WITHIN:
 - 6 MTHS OF TD 6_PTS ONLY; 4 MTHS OF TD 12_PTS ONLY; 2 MTHS OF TD 19_PTS ONLY;

POINTS AVAILABLE FOR QUESTION 8: (19_PTS)

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

8-10-15
DATE RELEASED

TOTAL RECLAMATION SCORE: _____

[Signature]
INSPECTOR'S SIGNATURE 08/14/2015