



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street SE
Charleston, WV 25304
(304) 926-0450
(304) 926-0452 fax

Earl Ray Tomblin, Governor
Randy C. Huffman, Cabinet Secretary
www.dep.wv.gov

December 23, 2015

FINAL INSPECTION REPORT

Well Permit Cancelled

ANTERO RESOURCES APPALACHIAN CORPORATION,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-8510037, issued to ANTERO RESOURCES APPALACHIAN CORPORATION, and listed below has been received in this office. The permit has been cancelled as of 12/21/2015.

James Martin
Chief

Operator: ANTERO RESOURCES APPALACHIAN CO
Operator's Well No: BLANCHE UNIT 2H
Farm Name: ANNIE B. HAYMOND, ET AL
API Well Number: 47-8510037
Date Issued: 05/31/2013

Date Cancelled: 12/21/2015

Promoting a healthy environment.

12/25/2015

INSPECTORS PERMIT SUMMARY FORM

GPS YES [] NO []

DATE STARTED/LOCATION: _____ OPERATOR: ANTERO RESOURCES APPALACHI
 DRILLING COMMENCED: _____ FARM: ANNIE B. HAYMOND, ET AL
 TO DATE: _____ DEPTHS: _____ Well No: BLANCHE UNIT 2H
 WATER DEPTHS: _____ COAL DEPTHS _____

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT.

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:
 - A. CONSTRUCTION YES [] NO [] (2_PTS) (4_PTS) _____
 - B. DRILLING YES [] NO [] (2_PTS)
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES [] NO [] (2_PTS) (4_PTS) _____
3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES [] NO [] (4_PTS) (4_PTS) _____
4. CONSTRUCTIONS:
WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?
 - A. ROAD DITCHES (1)_(2)_(3)_(4)_(PTS) B. CROSS DRAINS (1)_(2)_(3)_(4)_(5)_(PTS)
 - C. CULVERTS (1)_(2)_(3)_(4)_(5)_(PTS) D. CREEK CROSSINGS (1)_(2)_(3)_(PTS)
 - E. DIVERSION DITCHES (1)_(2)_(3)_(PTS) F. BARRIERS (1)_(2)_(3)_(PTS)
 - G. TEMPORARY SEEDING YES [] NO [] (10_PTS)

POINTS AVAILABLE FOR QUESTION 4: (33_PTS) _____

5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES [] NO [] (2_PTS) (2_PTS) _____
6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES [] NO [] (9_PTS) (9_PTS) _____
7. RECLAMATION:
 - A. ROADWAY (1)_(2)_(3)_(PTS) B. LOCATION (1)_(2)_(3)_(PTS)
 - C. PITS (1)_(2)_(3)_(PTS) D. PIPELINES (1)_(2)_(3)_(PTS)
 - E. TANK DIKES (1)_(2)_(3)_(PTS) F. API INSTALLED YES [] NO [] (3_PTS)
 - G. ADEQUATE SEEDING MATERIALS (1)_(2)_(3)_(PTS)
 - H. WAS SEED BED ADEQUATE (1)_(2)_(3)_(PTS)

POINTS AVAILABLE FOR QUESTION 7: (24_PTS) _____

8. WAS RECLAMATION COMPLETED WITHIN:
6 MTHS OF TD 6_PTS ONLY; 4 MTHS OF TD 12_PTS ONLY; 2 MTHS OF TD 19_PTS ONLY;
POINTS AVAILABLE FOR QUESTION 8: (19_PTS) _____

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

Cancelled By Request
12/21/15

 DATE RELEASED

TOTAL RECLAMATION SCORE: _____

Michael Goff

 INSPECTOR'S SIGNATURE

RECORD INSPECTIONS TO THIS WELL ON PAGE 2