



---

west virginia department of environmental protection

---

Office of Oil and Gas  
601 57th Street SE  
Charleston, WV 25304  
(304) 926-0450  
(304) 926-0452 fax

Earl Ray Tomblin, Governor  
Randy C. Huffman, Cabinet Secretary  
[www.dep.wv.gov](http://www.dep.wv.gov)

October 19, 2015

## FINAL INSPECTION REPORT

### Re-Work Permit Cancelled

KRAKROW, INC.,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-8700321, issued to KRAKROW, INC., and listed below has been received in this office. The permit has been cancelled as of 9/30/2015.

James Martin  
Chief

Operator: KRAKROW, INC.  
Operator's Well No: BOGGESS 2  
Farm Name: VALENTINE FAMILY TRUST  
**API Well Number: 47-8700321**  
Date Issued: 05/27/2008

Date Cancelled: 09/30/2015

Promoting a healthy environment.

10/23/2015

INSPECTORS PERMIT SUMMARY FORM

PAGE 1

GPS YES [ ] NO [ ]

DATE STARTED/LOCATION: \_\_\_\_\_ API #: 417-87-00321 WELL NO. Boggs 2  
 DRILLING COMMENCED: \_\_\_\_\_ OPERATOR: Krskrow Inc.  
 TD DATE: \_\_\_\_\_ DEPTH: \_\_\_\_\_ FARM: Ulenline Family Trust  
 WATER DEPTHS \_\_\_\_\_ COAL DEPTHS \_\_\_\_\_

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:  
 A. CONSTRUCTION YES [ ] NO [ ] (2\_PTS) B. DRILLING YES [ ] NO [ ] (2\_PTS)
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES [ ] NO [ ] (4\_PTS) (4 PTS) \_\_\_\_\_
3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES [ ] NO [ ] (4\_PTS) (4 PTS) \_\_\_\_\_
4. CONSTRUCTION:  
 WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?  
 A. ROAD DITCHES (1)\_ (2)\_ (3)\_ (4)\_ (PTS) B. CROSS DRAINS (1)\_ (2)\_ (3)\_ (4)\_ (5)\_ (PTS)  
 C. CULVERTS (1)\_ (2)\_ (3)\_ (4)\_ (5)\_ (PTS) D. CREEK CROSSINGS (1)\_ (2)\_ (3)\_ (PTS)  
 E. DIVERSION DITCHES (1)\_ (2)\_ (3)\_ (PTS) F. BARRIERS (1)\_ (2)\_ (3)\_ (PTS)  
 G. TEMPORARY SEEDING YES [ ] NO [ ] (10\_PTS) POINTS AVAILABLE FOR QUESTION 4: (33 PTS) \_\_\_\_\_
5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES [ ] NO [ ] (2\_PTS) (2 PTS) \_\_\_\_\_  
 THE PIT PROPERLY INSTALLED AND MAINTAINED? YES [ ] NO [ ] (9\_PTS) (9 PTS) \_\_\_\_\_
7. RECLAMATION:  
 A. ROADWAY (1)\_ (2)\_ (3)\_ (PTS) B. LOCATION (1)\_ (2)\_ (3)\_ (PTS)  
 C. PITS (1)\_ (2)\_ (3)\_ (PTS) D. PIPELINES (1)\_ (2)\_ (3)\_ (PTS)  
 E. TANK DIKES (1)\_ (2)\_ (3)\_ (PTS) F. API INSTALLED YES OR NO 3\_(PTS)  
 G. ADEQUATE SEEDING MATERIALS (1)\_ (2)\_ (3)\_ (PTS)  
 H. WAS SEED BED ADEQUATE (1)\_ (2)\_ (3)\_ (PTS) POINTS AVAILABLE FOR QUESTION 7: (24 PTS) \_\_\_\_\_
8. WAS RECLAMATION COMPLETED WITHIN:  
 6 MTHS OF TD 6\_PTS ONLY; 4 MTHS OF TD 12\_PTS ONLY; 2 MTHS OF TD 19\_PTS ONLY.  
 MAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS) \_\_\_\_\_

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: \_\_\_\_\_

INSPECTIONS :

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

RECEIVED  
Office of Oil and Gas

OCT 13 2015

WV Department of  
Environmental Protection

9-30-15

DATE RELEASED

*[Signature]*

INSPECTOR

10/23/2015