



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street SE
Charleston, WV 25304
(304) 926-0450
(304) 926-0452 fax

Earl Ray Tomblin, Governor
Randy C. Huffman, Cabinet Secretary
www.dep.wv.gov

October 19, 2015

FINAL INSPECTION REPORT

Re-Work Permit Cancelled

KRAKROW, INC.,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-8704076, issued to KRAKROW, INC., and listed below has been received in this office. The permit has been cancelled as of 9/30/2015.

James Martin
Chief

Operator: KRAKROW, INC.
Operator's Well No: STANLEY 5
Farm Name: SNYDER, MARY B.
API Well Number: 47-8704076
Date Issued: 08/10/2012

Date Cancelled: 09/30/2015

Promoting a healthy environment.

10/23/2015

INSPECTORS PERMIT SUMMARY FORM

PAGE 1

GPS YES [] NO []

DATE STARTED/LOCATION: API #: WELL NO.

DILLING COMMENCED: OPERATOR:

TD DATE: DEPTH: FARM:

WATER DEPTHS COAL DEPTHS

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:

A. CONSTRUCTION YES [] NO [] (2_PTS) B. DRILLING YES [] NO [] (2_PTS)

2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES [] NO [] (4_PTS) (4 PTS) _____

3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES [] NO [] (4_PTS) (4 PTS) _____

4. CONSTRUCTION: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?

A. ROAD DITCHES (1)_ (2)_ (3)_ (4)_ (PTS) B. CROSS DRAINS (1)_ (2)_ (3)_ (4)_ (5)_ (PTS)

C. CULVERTS (1)_ (2)_ (3)_ (4)_ (5)_ (PTS) D. CREEK CROSSINGS (1)_ (2)_ (3)_ (PTS)

E. DIVERSION DITCHES (1)_ (2)_ (3)_ (PTS) F. BARRIERS (1)_ (2)_ (3)_ (PTS)

G. TEMPORARY SEEDING YES [] NO [] (10_PTS) POINTS AVAILABLE FOR QUESTION 4: (33 PTS) _____

Handwritten in red: **NO ANSWERS!!!**

5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES [] NO [] (2_PTS) (2 PTS) _____

THE PIT PROPERLY INSTALLED AND MAINTAINED? YES [] NO [] (9_PTS) (9 PTS) _____

7. RECLAMATION:

A. ROADWAY (1)_ (2)_ (3)_ (PTS) B. LOCATION (1)_ (2)_ (3)_ (PTS)

C. PITS (1)_ (2)_ (3)_ (PTS) D. PIPELINES (1)_ (2)_ (3)_ (PTS)

E. TANK DIKES (1)_ (2)_ (3)_ (PTS) F. API INSTALLED YES OR NO 3_(PTS)

G. ADEQUATE SEEDING MATERIALS (1)_ (2)_ (3)_ (PTS)

H. WAS SEED BED ADEQUATE (1)_ (2)_ (3)_ (PTS) POINTS AVAILABLE FOR QUESTION 7: (24 PTS) _____

8. WAS RECLAMATION COMPLETED WITHIN:
 6 MTHS OF TD 6_PTS ONLY; 4 MTHS OF TD 12_PTS ONLY; 2 MTHS OF TD 19_PTS ONLY.
 MAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS) _____

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: _____

INSPECTIONS :

RECEIVED
Office of Oil and Gas

OCT 13 2015

WV Department of
Environmental Protection

9-30-15
DATE RELEASED

Handwritten signature

 INSPECTOR

10/23/2015