

## west virginia department of environmental protection

Office of Oil and Gas 601 57th Street SE Charleston, WV 25304 (304) 926-0450 (304) 926-0452 fax Earl Ray Tomblin, Governor Randy C. Huffman, Cabinet Secretary www.dep.wv.gov

March 07, 2016

## FINAL INSPECTION REPORT

## Horizontal Well Permit Cancelled

HARD ROCK EXPLORATION, INC.,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-8704712, issued to HARD ROCK EXPLORATION, INC., and listed below has been received in this office. The permit has been cancelled as of 3/1/2016.

James Martin Chief

Operator: HARD ROCK EXPLORATION, INC.

Operator's Well No: HR-454


Farm Name: DAVIS, KYLE

**API Well Number: 47-8704712** 

Date Issued: 11/23/2011

Date Cancelled: 03/01/2016

Promoting a healthy environment.



03/11/2016

## INSPECTORS PERMIT SUMMARY FORM

GPS YES   NO	<b>GPS</b>	YES	[ ]	NOI	1
--------------	------------	-----	-----	-----	---

		11									
DATE STARTED/LOCATION: Never Drilled			-4	OPERATOR:	HARD ROCK EXPLORATION, INC.						
DRILLING COMMENCED:				FARM:	DAVIS, KYLE						
TO	DATE:	DEPTHS:		Well No:	HR-454						
WA	ΓER DEPTHS:			COAL DEPTHS	S						
QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT.											
POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.											
1.	DID OPERATOR GIVE PA. CONSTRUCTION B. DRILLING	TOR BEFORE THE FOLLOWING:  NO[] (2_PTS)  NO[] (2_PTS)			(4_PTS)						
2.	WAS THE TIMBER CUT BEFORE DIRT WORK S	, STACKED, AND BR FARTED? YE	USH USE ES [ ] N	D FOR SEDIM NO [ ] (2_PT	EDIMENT BARRIERS (4_PTS)						
3.	ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES[] NO[] (4_PTS) (4_PTS)										
4. CONSTRUCTIONS: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED? A. ROAD DITCHES (1)_(2)_(3)_(4)_(PTS) B. CROSS DRAINS (1)_(2)_(3)_(4)_(5)_(PTS) C. CULVERTS (1)_(2)_(3)_(4)_(5)_(PTS) D. CREEK CROSSINGS (1)_(2)_(3)_(PTS) E. DIVERSION DITCHES (1)_(2)_(3)_(PTS) F. BARRIERS (1)_(2)_(3)_(PTS) G. TEMPORARY SEEDING YES[] NO[] (10_PTS)											
			POIN'	TS AVAILABL	E FOR Q	UESTION 4:	(33_PTS)				
5.	HAS TOP SOIL (IF ANY)	BEEN STOCKED PII	LED?	YES[]	NO[]	(2_PTS)	(2_PTS)				
6.	IS THE PIT PROPERLY I	NSTALLED AND MA	INTAINE	D? YES[]	NO[]	(9_PTS)	(9_PTS) ——				
7.	RECLAMATION: A. ROADWAY C. PITS E. TANK DIKES G. ADEQUATE SEEDIN H. WAS SEED BED ADI	(1)_(2)_(3)_(PTS) (1)_(2)_(3)_(PTS) G MATERIALS (1	D. F. ()_(2)_(3)_ ()_(2)_(3)_		.ED	(1)_(2)_(3)_(PTS (1)_(2)_(3)_(PTS YES[] NO[	5)				
8.	WAS RECLAMATION CO 6 MTHS OF TD 6_PTS O		TD 12_PTS	S ONLY; 2 M			/; (19_PTS)				
T	OTAL MAXIMUM POSS	IBLE SCORE OF 99		TOTAL R	ECLAM	ATION SCORE:					
	3/1/2014 DATE RELEASE	ancelled		Jacque	SPECTO	Thornton R'S SIGNATURE					