

WELL PLUGGING INSPECTION & RELEASE FORM

PLUGGING COMMENCED \_\_\_\_\_  
PLUGGING COMPLETED \_\_\_\_\_  
VERBAL PERMISSION ON \_\_\_\_\_

OPERATOR: Consolidation Coal Co.  
FARM: Albert E. & Brenda S. Reynolds  
WELL NO: 8276

- 1. IS COAL BEING MINED IN THE AREA? YESX NO N/A
- 2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS?
  - A. BOTTOM HOLE PLUGGED YES NOX N/A
  - B. 100' PLUGS YESX NO N/A
  - C. LATEX PLUGS USED FOR H<sub>2</sub>S GAS YES NO N/AX
  - D. PROPER PLUGS THROUGH COAL SEAMS YESX NO N/A
  - E. PROPER PLUGS SET TO PROTECT FRESHWATER YESX NO N/A
  - F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS YES NO N/A

TYPE	FROM	TO	PIPE REMOVED
	Plugged according to Coal Co. Requirements		

- 3. WERE ALL CHANGES APPROVED BY INSPECTOR? YES NOX
- 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? YESX NO
- 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? YES NOX
- 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? YES NO
- 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? YES NOX
- 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS?
  - A. RECLAIMED YESX NO
  - B. FENCES REPLACED YESX NO
  - C. MULCHED YESX NO
  - D. PROPER DRAINAGE YESX NO
  - E. SEEDED YESX NO
  - F. ALL EQUIPMENT REMOVED YESX NO
  - G. PIT BACKFILLED YES NO

3/22/21  
DATE RELEASED

Bryan Harris  
INSPECTOR'S SIGNATURE