

STATE OF WEST VIRGINIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
OFFICE OF OIL AND GAS

AFFIDAVIT OF PLUGGING AND FILLING WELL

AFFIDAVIT SHOULD BE IN TRIPLICATE, one copy mailed to the Department, one copy to be retained by the Well Operator and the third copy (and extra copies if required) should be mailed to each coal operator at their respective addresses.

Farm name: Heartwood Forestland Operator Well No.: PC-014C

LOCATION: Elevation: 1,854.4' Quadrangle: Pineville
District: Baileysville County: Wyoming
Latitude: 3,721 Feet South of 37 Deg. 35 Min. 00 Sec.
Longitude: 6,921 Feet West of 81 Deg. 35 Min. 00 Sec.

Well Type: OIL _____ GAS XXX

Company Ultra Production Company, LLC Coal Operator Boone East Development Co.
PO Box 289 or Owner _____
Cedar Bluff, VA 24609 _____
Agent Andy Hrovatic Coal Operator _____
Permit Issued Date _____ or Owner _____

AFFIDAVIT

STATE OF WEST VIRGINIA,
County of Wyoming ss:

Andy Hrovatic and Mike Byrd being first duly sworn according to law depose and say that they are experienced in the work of plugging and filling oil and gas wells and were employed by the above named well operator, and participated in the work of plugging and filling the above well say that said work was commenced on the 10th day of October, 2021, and the well was plugged and filled in the following manner:

TYPE	FROM	TO	PIPE REMOVED	LEFT
Cement	1037	0	No	7 inch - 940 feet
Bentonite	Horizontals	981 (P3)	No	


Description of monument: 6" pipe w/ steel plate w/ API Number and Name and that the work of plugging and filling said well was completed on the 22th day of October, 2021.

And further deponents saith not. [Signature]
Mike Byrd

Sworn and subscribe before me this 26th day of October, 2021

My commission expires: 12-31-2022

Shelli E. Jackson
Notary Public



Affidavit reviewed by the Office of Oil and Gas: [Signature] Title: Inspector

WELL PLUGGING INSPECTION & RELEASE FORM

PLUGGING COMMENCED 10/10/21
 PLUGGING COMPLETED 10/22/21
 VERBAL PERMISSION ON _____

OPERATOR: Ultra Production
 FARM: ~~Heatwood~~ Heatwood Forestland
 WELL NO: PC-014C

1. IS COAL BEING MINED IN THE AREA? YES NO N/A
2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS?
 - A. BOTTOM HOLE PLUGGED YES NO N/A
 - B. 100' PLUGS YES NO N/A
 - C. LATEX PLUGS USED FOR H₂S GAS YES NO N/A
 - D. PROPER PLUGS THROUGH COAL SEAMS YES NO N/A
 - E. PROPER PLUGS SET TO PROTECT FRESHWATER YES NO N/A
 - F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS YES NO N/A

TYPE	FROM	TO	PIPE REMOVED
<u>Cement</u>	<u>1037'</u>	<u>Surface</u>	
<u>Horizontal Lateral</u>			
<u>filled w/ Bentonite</u>			

3. WERE ALL CHANGES APPROVED BY INSPECTOR? YES NO
4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? YES NO
5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? YES NO
6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? YES NO
7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? YES NO
8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS?

A. RECLAIMED	<input checked="" type="radio"/> YES	NO	B. FENCES REPLACED	<input checked="" type="radio"/> YES	NO
C. MULCHED	<input checked="" type="radio"/> YES	NO	D. PROPER DRAINAGE	<input checked="" type="radio"/> YES	NO
E. SEEDED	<input checked="" type="radio"/> YES	NO	F. ALL EQUIPMENT REMOVED	<input checked="" type="radio"/> YES	NO
G. PIT BACKFILLED	<input checked="" type="radio"/> YES	NO			

11/22/21
DATE RELEASED

[Signature]
INSPECTOR'S SIGNATURE

RECORD ALL VISITS TO THIS WELL ON PAGE 2