



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street, S.E.
Charleston, WV 25304
(304) 926-0450
fax: (304) 926-0452

Austin Caperton, Cabinet Secretary
www.dep.wv.gov

Tuesday, September 18, 2018
NOTICE OF PERMIT CANCELLATION
Horizontal 6A / Horizontal 6A Well - 1

CNX GAS COMPANY LLC
POST OFFICE BOX 1248

JANE LEW, WV 263786506

Re: Permit cancellation for AUD7EHS
47-001-03285-00-00

The FINAL INSPECTION REPORT for the CANCELLED PERMIT, issued for U.S. Well Number 47-001-03285-00-00 , has been received by the Office of Oil and Gas. The permit has been cancelled as of 9/18/2018 .

If there are any questions, please feel free to contact me at (304) 926- 0450.

A handwritten signature in blue ink, appearing to read 'James A. Martin', is positioned above the printed name and title.

James A. Martin
Chief

Operator's Well Number: AUD7EHS
Farm Name: MURPHY, BRIAN E. & LISA
U.S. WELL NUMBER: 47-001-03285-00-00
Horizontal 6A Horizontal 6A Well - 1
Date Cancelled: 9/18/2018

PAGE 1

GPS YES NO

DATE STARTED/LOCATION: [] API #: 47-001-03285-00-00 WELL NO. AUD7EHS

DRILLING COMMENCED: [] OPERATOR: CNX GAS COMPANY LLC

TD DATE: [] DEPTH: [] FARM: MURPHY, BRIAN E. & LISA L.

WATER DEPTHS [] COAL DEPTHS []

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

- 1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:
 A. CONSTRUCTION YES NO (2_PTS) B. DRILLING YES NO (2_PTS) (4 PTS)_____
- 2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES NO (4_PTS) (4 PTS)_____
- 3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES NO (4_PTS) (4 PTS)_____

- 4. CONSTRUCTION:
 WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?
 A. ROAD DITCHES (1)_(2)_(3)_(4)_ (PTS) B. CROSS DRAINS (1)_(2)_(3)_(4)_(5)_ (PTS)
 C. CULVERTS (1)_(2)_(3)_(4)_(5)_ (PTS) D. CREEK CROSSINGS (1)_(2)_(3)_ (PTS)
 E. DIVERSION DITCHES (1)_(2)_(3)_ (PTS) F. BARRIERS (1)_(2)_(3)_ (PTS)
 G. TEMPORARY SEEDING YES NO (10_PTS) POINTS AVAILABLE FOR QUESTION 4: (33 PTS)_____

- 5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES NO (2_PTS) (2 PTS)_____
- 6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES NO (9_PTS) (9 PTS)_____

- 7. RECLAMATION:
 A. ROADWAY (1)_(2)_(3)_ (PTS) B. LOCATION (1)_(2)_(3)_ (PTS)
 C. PITS (1)_(2)_(3)_ (PTS) D. PIPELINES (1)_(2)_(3)_ (PTS)
 E. TANK DIKES (1)_(2)_(3)_ (PTS) F. API INSTALLED YES OR NO 3_(PTS)
 G. ADEQUATE SEEDING MATERIALS (1)_(2)_(3)_ (PTS)
 H. WAS SEED BED ADEQUATE (1)_(2)_(3)_ (PTS) POINTS AVAILABLE FOR QUESTION 7: (24 PTS)_____

8. WAS RECLAMATION COMPLETED WITHIN:
 MTHS OF TD 6_PTS ONLY; MTHS OF TD 12_PTS ONLY; MTHS OF TD 19_PTS ONLY.
 MAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS)_____

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: _____

INSPECTIONS :

NO DRILLED 9-18-15
 DATE ~~RELEASED~~ INSPECTOR
 CANCELED