



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street, S.E.
Charleston, WV 25304
(304) 926-0450
fax: (304) 926-0452

Austin Caperton, Cabinet Secretary
www.dep.wv.gov

Wednesday, January 16, 2019
NOTICE OF PERMIT CANCELLATION
Vertical / Plugging

EQT PRODUCTION COMPANY
625 LIBERTY AVE., SUITE 1700

PITTSBURGH, PA 15222

Re: Permit cancellation for WV 607672 (P. C. TAYLOR 1)
47-007-00087-00-00

The FINAL INSPECTION REPORT for the CANCELLED PERMIT, issued for U.S. Well Number 47-007-00087-00-00 , has been received by the Office of Oil and Gas. The permit has been cancelled as of 1/16/2019 .

If there are any questions, please feel free to contact me at (304) 926- 0450.

A handwritten signature in blue ink, appearing to read "James A. Martin".

James A. Martin
Chief

Operator's Well Number: WV 607672 (P. C. TAYLOR 1)
Farm Name: McCOURT, GARY & JANETTE
U.S. WELL NUMBER: 47-007-00087-00-00
Vertical Plugging
Date Cancelled: 1/16/2019

WELL PLUGGING INSPECTION & RELEASE FORM

PLUGGING COMMENCED NA OPERATOR: EQT PRODUCTION COMPANY
PLUGGING COMPLETED _____ FARM: McCOURT, GARY & JANETTE
VERBAL PERMISSION ON _____ WELL NO: WV 607672 (P. C. TAYLOR 1)

- 1. IS COAL BEING MINED IN THE AREA? YES NO N/A
- 2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS?
 - A. BOTTOM HOLE PLUGGED YES NO N/A
 - B. 100' PLUGS YES NO N/A
 - C. LATEX PLUGS USED FOR H₂S GAS YES NO N/A
 - D. PROPER PLUGS THROUGH COAL SEAMS YES NO N/A
 - E. PROPER PLUGS SET TO PROTECT FRESHWATER YES NO N/A
 - F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS YES NO N/A

| TYPE | FROM | TO | PIPE REMOVED |
|--------------------------------------|------|----|--------------|
| <i>No + Plugged</i> | | | |
| <i>Permit Cancelled for Transfer</i> | | | |

- 3. WERE ALL CHANGES APPROVED BY INSPECTOR? YES NO
- 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? YES NO
- 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? YES NO
- 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? YES NO
- 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? YES NO
- 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS?

| | | | | | |
|-------------------|-----|----|--------------------------|-----|----|
| A. RECLAIMED | YES | NO | B. FENCES REPLACED | YES | NO |
| C. MULCHED | YES | NO | D. PROPER DRAINAGE | YES | NO |
| E. SEEDED | YES | NO | F. ALL EQUIPMENT REMOVED | YES | NO |
| G. PIT BACKFILLED | YES | NO | | | |

1/18/19
DATE RELEASED

[Signature]
INSPECTOR'S SIGNATURE