IR-26 Rev 08

CANLELED

(ANGLED ED INSPECTORS PERMIT SUMMARY FORM

PAGE 1 GPS YES NO	1
DATE STARTED/LOCATION: API #: 47.000: 0.07.7.2 WELL NO.	
DPH I INC COMMENCED	2014
TD DATE: Southwestern Production Co	
WATER DEPTHS COAL DEPTHS	
QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CO	NTPOL DEDINE
POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.	NIKOL PERMII
1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING: A. CONSTRUCTION YES NO (2 PTS) B. DRILLING YES NO (2 PTS)	0//1
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES NO (4_PTS)	(4 PTS) / (4 PTS)
3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES NO (4_PTS)	(4 PTS)
4. CONSTRUCTION: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAI A. ROAD DITCHES (1) (2) (3) (4) (PTS) B. CROSS DRAINS (1) (2) (3) (4) (5) (PTS) C. CULVERTS (1) (2) (3) (4) (5) (PTS) E. DIVERSION DITCHES (1) (2) (3) (PTS) G. TEMPORARY SEEDING YES NO (10 PTS) POINTS AVAILABLE FOR QUESTION	
5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES NO 2_PTS)	(2 PTS)
6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES NO (9_PTS)	(9 PTS)
7. RECLAMATION: A. ROADWAY (1)_(2)_(3)_ (PTS	(24 PTS)
8. WAS RECLAMATION COMPLETED WITHIN: MTHS OF TD 6_PTS ONLY; MAXIMUM POINTS AVAILABLE FOR QUESTION 8:	LY. (19 PTS)
TOTAL MAXIMUM POSSIBLE SCORE OF 99.	NIA
TOTAL RECLAMATION	ON SCORE: ///
INSPECTIONS:	
KANCE LED	
,	
11.F.19 (. B/L)	
DATE RELEASED INSPECTOR	