



---

west virginia department of environmental protection

---

Office of Oil and Gas  
601 57<sup>th</sup> Street, S.E.  
Charleston, WV 25304  
(304) 926-0450  
fax: (304) 926-0452

Harold D. Ward, Cabinet Secretary  
[www.dep.wv.gov](http://www.dep.wv.gov)

Thursday, October 27, 2022  
NOTICE OF PERMIT CANCELLATION  
Horizontal 6A / Horizontal 6A Well - 1


ANTERO RESOURCES CORPORATION  
1615 WYNKOOP STREET

DENVER, CO 80202

Re: Permit cancellation for CONNELLY UNIT 2H  
47-017-06674-00-00

The FINAL INSPECTION REPORT for the CANCELLED PERMIT, issued for U.S. Well Number 47-017-06674-00-00 , has been received by the Office of Oil and Gas. The permit has been cancelled as of 1/23/2015 .

If there are any questions, please feel free to contact me at (304) 926- 0450.



James A. Martin  
Chief

Operator's Well Number: CONNELLY UNIT 2H  
Farm Name: PLAUGHER, CAROLYN N.  
U.S. WELL NUMBER: 47-017-06674-00-00  
Horizontal 6A Horizontal 6A Well - 1  
Date Cancelled: 1/23/2015

Promoting a healthy environment.

10/28/2022

PAGE 1

GPS YES \_\_\_ NO \_\_\_

DATE STARTED/LOCATION:		API #:	4701706674	WELL NO.	Connley 2H
DRILLING COMMENCED:	Canceled	OPERATOR:	Antero Resources Corporation		
TD DATE:		DEPTH:		FARM:	Carolyn N Plaughter
WATER DEPTHS			COAL DEPTHS		

WATER DEPTHS

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30

AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

**POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.**

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:  
 A. CONSTRUCTION YES \_\_\_ NO \_\_\_ (2 PTS)      B. DRILLING YES \_\_\_ NO \_\_\_ (2 PTS) (4 PTS) \_\_\_\_\_

2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES \_\_\_ NO \_\_\_ (4 PTS) (4 PTS) \_\_\_\_\_

3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES \_\_\_ NO \_\_\_ (4 PTS) (4 PTS) \_\_\_\_\_

4. CONSTRUCTION:

WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?

A. ROAD DITCHES 1\_\_2\_\_3\_\_4\_\_ (PTS)      B. CROSS DRAINS 1\_\_2\_\_3\_\_4\_\_5\_\_ (PTS)  
 C. CULVERTS 1\_\_2\_\_3\_\_4\_\_5\_\_ (PTS)      D. CREEK CROSSINGS 1\_\_2\_\_3\_\_ (PTS)  
 E. DIVERSION DITCHES 1\_\_2\_\_3\_\_ (PTS)      F. BARRIERS 1\_\_2\_\_3\_\_ (PTS)  
 G. TEMPORARY SEEDING YES \_\_\_ NO \_\_\_ (10 PTS)      **POINTS AVAILABLE FOR QUESTION 4:** (33 PTS) \_\_\_\_\_

5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES \_\_\_ NO \_\_\_ (2 PTS) (2 PTS) \_\_\_\_\_

6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES \_\_\_ NO \_\_\_ (9 PTS) (9 PTS) \_\_\_\_\_

7. RECLAMATION:

A. ROADWAY 1\_\_2\_\_3\_\_ (PTS)      B. LOCATION 1\_\_2\_\_3\_\_ (PTS)  
 C. PITS 1\_\_2\_\_3\_\_ (PTS)      D. PIPELINES 1\_\_2\_\_3\_\_ (PTS)  
 E. TANK DIKES 1\_\_2\_\_3\_\_ (PTS)      F. API INSTALLED YES \_\_\_ NO \_\_\_ (3 PTS)  
 G. ADEQUATE SEEDING MATERIALS 1\_\_2\_\_3\_\_ (PTS)  
 H. WAS SEED BED ADEQUATE 1\_\_2\_\_3\_\_ (PTS)      **POINTS AVAILABLE FOR QUESTION 7:** (24 PTS) \_\_\_\_\_

8. WAS RECLAMATION COMPLETED WITHIN:

A. CONVENTIONAL:

6 MTHS OF TD \_\_\_ 6 PTS ONLY; 4 MTHS OF TD \_\_\_ 12 PTS ONLY; 2 MTHS OF TD \_\_\_ 19 PTS ONLY.

B. HORIZONTAL:

3 YRS OF PAD COMPLETION \_\_\_ 19 PTS ONLY; 4 YRS OF PAD COMPLETION \_\_\_ 16 PTS ONLY;  
5 YRS OF PAD COMPLETION \_\_\_ 13 PTS ONLY

**MAXIMUM POINTS AVAILABLE FOR QUESTION 8:** (19 PTS) \_\_\_\_\_

**TOTAL MAXIMUM POSSIBLE SCORE OF 99.**

**TOTAL RECLAMATION SCORE:** \_\_\_\_\_

**CANCELED 10/24/2022**

*Douglas Newlon*

DATE RELEASED

INSPECTOR

10/28/2022