

09/21/2018



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street, S.E.
Charleston, WV 25304
(304) 926-0450
fax: (304) 926-0452

Austin Caperton, Cabinet Secretary
www.dep.wv.gov

Wednesday, September 19, 2018
NOTICE OF PERMIT CANCELLATION
Horizontal 6A / Horizontal 6A Well - 1

CNX GAS COMPANY LLC
POST OFFICE BOX 1248

JANE LEW, WV 263786506

Re: Permit cancellation for RNST13AHS
47-021-05782-00-00

The FINAL INSPECTION REPORT for the CANCELLED PERMIT, issued for U.S. Well Number 47-021-05782-00-00 , has been received by the Office of Oil and Gas. The permit has been cancelled as of 9/19/2018 .

If there are any questions, please feel free to contact me at (304) 926- 0450.

James A. Martin
Chief

Operator's Well Number: RNST13AHS
Farm Name: COASTAL TIMBERLANDS COMPANY
U.S. WELL NUMBER: 47-021-05782-00-00
Horizontal 6A Horizontal 6A Well - 1
Date Cancelled: 9/19/2018

Promoting a healthy environment.

PAGE 1

GPS YES [] NO []

DATE STARTED/LOCATION:			API #:			WELL NO.		
DRILLING COMMENCED:			OPERATOR:					
TD DATE:			DEPTH:			FARM:		
WATER DEPTHS				COAL DEPTHS				

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:
 - A. CONSTRUCTION YES [] NO [] (2_PTS)
 - B. DRILLING YES [] NO [] (2_PTS)

(4 PTS) _____
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES [] NO [] (4_PTS) (4 PTS) _____
3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES [] NO [] (4_PTS) (4 PTS) _____
4. CONSTRUCTION: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?
 - A. ROAD DITCHES (1)_ (2)_ (3)_ (4)_ (PTS)
 - B. CROSS DRAINS (1)_ (2)_ (3)_ (4)_ (5)_ (PTS)
 - C. CULVERTS (1)_ (2)_ (3)_ (4)_ (5)_ (PTS)
 - D. CREEK CROSSINGS (1)_ (2)_ (3)_ (PTS)
 - E. DIVERSION DITCHES (1)_ (2)_ (3)_ (PTS)
 - F. BARRIERS (1)_ (2)_ (3)_ (PTS)
 - G. TEMPORARY SEEDING YES [] NO [] (10_PTS)

POINTS AVAILABLE FOR QUESTION 4: (33 PTS) _____
5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES [] NO [] (2_PTS) (2 PTS) _____
6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES [] NO [] (9_PTS) (9 PTS) _____
7. RECLAMATION:
 - A. ROADWAY (1)_ (2)_ (3)_ (PTS)
 - B. LOCATION (1)_ (2)_ (3)_ (PTS)
 - C. PITS (1)_ (2)_ (3)_ (PTS)
 - D. PIPELINES (1)_ (2)_ (3)_ (PTS)
 - E. TANK DIKES (1)_ (2)_ (3)_ (PTS)
 - F. API INSTALLED YES OR NO 3_(PTS)
 - G. ADEQUATE SEEDING MATERIALS (1)_ (2)_ (3)_ (PTS)
 - H. WAS SEED BED ADEQUATE (1)_ (2)_ (3)_ (PTS)

POINTS AVAILABLE FOR QUESTION 7: (24 PTS) _____
8. WAS RECLAMATION COMPLETED WITHIN:
 - 6 MTHS OF TD 6_PTS ONLY;
 - 4 MTHS OF TD 12_PTS ONLY;
 - 2 MTHS OF TD 19_PTS ONLY.

MAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS) _____

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: _____

INSPECTIONS :

DATE RELEASED _____

Danny Mullins
INSPECTOR

PAGE 1

GPS YES ___ NO ___

DATE STARTED/LOCATION:		API #:		WELL NO.	
DRILLING COMMENCED:		OPERATOR:			
TD DATE:		DEPTH:		FARM:	
WATER DEPTHS		COAL DEPTHS			

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:
 - A. CONSTRUCTION YES ___ NO ___ (2 PTS)
 - B. DRILLING YES ___ NO ___ (2 PTS)

(4 PTS) _____
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES ___ NO ___ (4 PTS) **(4 PTS) _____**
3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES ___ NO ___ (4 PTS) **(4 PTS) _____**
4. CONSTRUCTION: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?

A. ROAD DITCHES 1___ 2___ 3___ 4___ (PTS)	B. CROSS DRAINS 1___ 2___ 3___ 4___ 5___ (PTS)
C. CULVERTS 1___ 2___ 3___ 4___ 5___ (PTS)	D. CREEK CROSSINGS 1___ 2___ 3___ (PTS)
E. DIVERSION DITCHES 1___ 2___ 3___ (PTS)	F. BARRIERS 1___ 2___ 3___ (PTS)

G. TEMPORARY SEEDING YES ___ NO ___ (10 PTS) **POINTS AVAILABLE FOR QUESTION 4: (33 PTS) _____**
5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES ___ NO ___ (2 PTS) **(2 PTS) _____**
6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES ___ NO ___ (9 PTS) **(9 PTS) _____**
7. RECLAMATION:

A. ROADWAY 1___ 2___ 3___ (PTS)	B. LOCATION 1___ 2___ 3___ (PTS)
C. PITS 1___ 2___ 3___ (PTS)	D. PIPELINES 1___ 2___ 3___ (PTS)
E. TANK DIKES 1___ 2___ 3___ (PTS)	F. API INSTALLED YES___ NO___ (3 PTS)

G. ADEQUATE SEEDING MATERIALS 1___ 2___ 3___ (PTS)

H. WAS SEED BED ADEQUATE 1___ 2___ 3___ (PTS) **POINTS AVAILABLE FOR QUESTION 7: (24 PTS) _____**
8. WAS RECLAMATION COMPLETED WITHIN:

6 MTHS OF TD ___ 6 PTS ONLY; 4 MTHS OF TD ___ 12 PTS ONLY; 2 MTHS OF TD ___ 19 PTS ONLY.

MAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS) _____

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: _____

INSPECTIONS:

DATE RELEASED

J. Cragin Blevins

INSPECTOR

