

Form IR-11A
Rev. 8/21/2013

State of West Virginia
Office of Oil and Gas

INSPECTORS REPORT

Operator: EQT Production Company
API Number: 47-033-00359 McKinley 8184

Findings:

The plugging rig has the bottom hole plug set, and plug up to the bottom of the 5". The rig tried to pull the 5" and it parted at 641'. A new joint of casing was threaded into the 5" and it pulled out at 15,000lb. the second attempt, the threads pulled out at 4,000lb. Verbal permission was given to shoot and cement to above elevation. No problems were found during this inspection.

Does this inspection identify any dust issues? Yes No. If Yes, explain.

Sam Ward
Oil & Gas Inspector

6/19/2019
Date