

INSPECTORS REPORT

Operator: Dominion Energy Transmission, INC.

API Number: 47-033-02133 #7570

Findings:

The rig finished the final plug to surface, prepare to RDMO. No problems were found during this inspection.

Does this inspection identify any dust issues? Yes No. If Yes, explain.

Sam Ward

Oil & Gas Inspector

10/13/2020

Date