

INSPECTORS REPORT

Operator: Antero

API Number: 33-03256

Findings:

Working on setting plug to cover the 5th sand at 2,500'. Containment and soil erosion

Measures in place.

Gayne Knitowski

Oil & Gas Inspector

7-31-2018

Date