



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street SE
Charleston, WV 25304
(304) 926-0450
(304) 926-0452 fax

Earl Ray Tomblin, Governor
Randy C. Huffman, Cabinet Secretary
www.dep.wv.gov

July 16, 2015

FINAL INSPECTION REPORT

Well Permit Cancelled

ANTERO RESOURCES APPALACHIAN CORPORATION,

The FINAL INSPECTION REPORT for the CANCELLED permit, API Well Number: 47-3305633, issued to ANTERO RESOURCES APPALACHIAN CORPORATION, and listed below has been received in this office. The permit has been cancelled as of 12/16/2014.

James Martin
Chief

Operator: ANTERO RESOURCES APPALACHIAN CO
Operator's Well No: HESS UNIT 1H
Farm Name: MALE, KIMBERLY A.
API Well Number: 47-3305633
Date Issued: 08/14/2012

Date Cancelled: 12/16/2014

Promoting a healthy environment.

DATE STARTED/LOCATION: [] API #: 47-33-5633 WELL NO. Hess Unit 7H
 DRILLING COMMENCED: [] OPERATOR: Antero Resources Corporation
 TD DATE: [] DEPTH: [] FARM: Maley, Kimberly A
 WATER DEPTHS [] COAL DEPTHS []

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

- 1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:
 - A. CONSTRUCTION YES [] NO [] (2_PTS)
 - B. DRILLING YES [] NO [] (2_PTS)
- 2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES [] NO [] (4_PTS)
- 3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES [] NO [] (4_PTS)
- 4. CONSTRUCTION: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?
 - A. ROAD DITCHES (1)_ (2)_ (3)_ (4)_ (PTS)
 - B. CROSS DRAINS (1)_ (2)_ (3)_ (4)_ (5)_ (PTS)
 - C. CULVERTS (1)_ (2)_ (3)_ (4)_ (5)_ (PTS)
 - D. CREEK CROSSINGS (1)_ (2)_ (3)_ (PTS)
 - E. DIVERSION DITCHES (1)_ (2)_ (3)_ (PTS)
 - F. BARRIERS (1)_ (2)_ (3)_ (PTS)
 - G. TEMPORARY SEEDING YES [] NO [] (10_PTS) PC
- 5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES [] NO [] (2_PTS)
- 6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES [] NO [] (9_PTS)
- 7. RECLAMATION:
 - A. ROADWAY (1)_ (2)_ (3)_ (PTS)
 - B. LOCATION (1)_ (2)_ (3)_ (PTS)
 - C. PITS (1)_ (2)_ (3)_ (PTS)
 - D. PIPELINES (1)_ (2)_ (3)_ (PTS)
 - E. TANK DIKES (1)_ (2)_ (3)_ (PTS)
 - F. API INSTALLATION (1)_ (2)_ (3)_ (PTS)
 - G. ADEQUATE SEEDING MATERIALS (1)_ (2)_ (3)_ (PTS)
 - H. WAS SEED BED ADEQUATE (1)_ (2)_ (3)_ (PTS)
- 8. WAS RECLAMATION COMPLETED WITHIN:
 - 6 MTHS OF TD 6_PTS ONLY; 4 MTHS OF TD 12_PTS ONLY; 2 MTHS OF TD 19_PTS ONLY.

*Sam
 Public said this well was not drilled and should be cancelled. Should you send me a cancel check!*

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: _____

INSPECTIONS :

Conditional release in order to allow a plugging permit to be issued. Reclamation must be completed as required by 22-6-30 and 22-6A-14 where applicable, when plugging is complete within the required time limits in order to release the well pad for reclamation.

[Signature]

RECEIVED
 Office of Oil and Gas
 DEC 16 2014

WV Department of Environmental Protection

12/16/2014
 DATE RELEASED
 Canceled

[Signature]
 INSPECTOR