



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street, S.E.
Charleston, WV 25304
(304) 926-0450
fax: (304) 926-0452

Austin Caperton, Cabinet Secretary
www.dep.wv.gov

Tuesday, September 18, 2018
NOTICE OF PERMIT CANCELLATION
Horizontal 6A / Horizontal 6A Well - 1

CNX GAS COMPANY LLC
POST OFFICE BOX 1248

JANE LEW, WV 263786506

Re: Permit cancellation for KST2DHS
47-033-05859-00-00

The FINAL INSPECTION REPORT for the CANCELLED PERMIT, issued for U.S. Well Number 47-033-05859-00-00 , has been received by the Office of Oil and Gas. The permit has been cancelled as of 9/18/2018 .

If there are any questions, please feel free to contact me at (304) 926-0450.

A blue ink signature of James A. Martin, written in a cursive style.

James A. Martin
Chief

Operator's Well Number: KST2DHS
Farm Name: COFFINDAFFER, MARK & E_{II}
U.S. WELL NUMBER: 47-033-05859-00-00
Horizontal 6A Horizontal 6A Well - 1
Date Cancelled: 9/18/2018

GPS YES NO

| | | | | | |
|------------------------|-------------|-------------|---------------------|----------|------------------------------------|
| DATE STARTED/LOCATION: | Never Built | API #: | 47-033-05859-00-00 | WELL NO. | KST2DHS |
| DRILLING COMMENCED: | | OPERATOR: | CNX GAS COMPANY LLC | | |
| TD DATE: | | DEPTH: | | FARM: | COFFINDAFFER, MARK & ESTEVE, DIANA |
| WATER DEPTHS | | COAL DEPTHS | | | |

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:
 - A. CONSTRUCTION YES NO (2_PTS)
 - B. DRILLING YES NO (2_PTS)
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES NO (4_PTS) (4 PTS) _____
3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES NO (4_PTS) (4 PTS) _____
4. CONSTRUCTION: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?
 - A. ROAD DITCHES (1)_ (2)_ (3)_ (4)_ (PTS)
 - B. CROSS DRAINS (1)_ (2)_ (3)_ (4)_ (5)_ (PTS)
 - C. CULVERTS (1)_ (2)_ (3)_ (4)_ (5)_ (PTS)
 - D. CREEK CROSSINGS (1)_ (2)_ (3)_ (PTS)
 - E. DIVERSION DITCHES (1)_ (2)_ (3)_ (PTS)
 - F. BARRIERS (1)_ (2)_ (3)_ (PTS)
 - G. TEMPORARY SEEDING YES NO (10_PTS)

POINTS AVAILABLE FOR QUESTION 4: (33 PTS) _____
5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES NO (2_PTS) (2 PTS) _____
6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES NO (9_PTS) (9 PTS) _____
7. RECLAMATION:
 - A. ROADWAY (1)_ (2)_ (3)_ (PTS)
 - B. LOCATION (1)_ (2)_ (3)_ (PTS)
 - C. PITS (1)_ (2)_ (3)_ (PTS)
 - D. PIPELINES (1)_ (2)_ (3)_ (PTS)
 - E. TANK DIKES (1)_ (2)_ (3)_ (PTS)
 - F. API INSTALLED YES OR NO 3_(PTS)
 - G. ADEQUATE SEEDING MATERIALS (1)_ (2)_ (3)_ (PTS)
 - H. WAS SEED BED ADEQUATE (1)_ (2)_ (3)_ (PTS)

POINTS AVAILABLE FOR QUESTION 7: (24 PTS) _____
8. WAS RECLAMATION COMPLETED WITHIN:
 - MTHS OF TD 6_PTS ONLY; MTHS OF TD 12_PTS ONLY; MTHS OF TD 19_PTS ONLY.

MAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS) _____

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: _____

INSPECTIONS :

CANCEL NEVER BUILT/DRILLED

[Handwritten Signature]

 INSPECTOR