



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street, S.E.
Charleston, WV 25304
(304) 926-0450
fax: (304) 926-0452

Austin Caperton, Cabinet Secretary
www.dep.wv.gov

Wednesday, January 16, 2019
NOTICE OF PERMIT CANCELLATION
Vertical / Fracture - 2

BLAZER ENERGY CORPORATION
1710 PENNSYLVANIA AVENUE

CHARLESTON, WV 253110000

Re: Permit cancellation for A-8-S-127981
47-035-00147-00-00

The FINAL INSPECTION REPORT for the CANCELLED PERMIT, issued for U.S. Well Number 47-035-00147-00-00 , has been received by the Office of Oil and Gas. The permit has been cancelled as of 1/16/2019 .

If there are any questions, please feel free to contact me at (304) 926- 0450.

A blue ink signature of James A. Martin, written in a cursive style.

James A. Martin
Chief

Operator's Well Number: A-8-S-127981
Farm Name: CARTE, ROGER
U.S. WELL NUMBER: 47-035-00147-00-00
Vertical Fracture - 2
Date Cancelled: 1/16/2019

PAGE 1

GPS YES NO

DATE STARTED/LOCATION: NA API #: 47-035-00147-00-00 WELL NO. A-8-S-127981
 DRILLING COMMENCED: NA OPERATOR: BLAZER ENERGY CORPORATION
 TD DATE: _____ DEPTH: _____ FARM: CARTE, ROGER
 WATER DEPTHS _____ COAL DEPTHS _____

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:
 A. CONSTRUCTION YES NO (2_PTS) B. DRILLING YES NO (2_PTS) (4 PTS) _____
 2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES NO (4_PTS) (4 PTS) _____
 3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES NO (4_PTS) (4 PTS) _____
 4. CONSTRUCTION:
 WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?
 A. ROAD DITCHES (1)_ (2)_ (3)_ (4)_ (PTS) B. CROSS DRAINS (1)_ (2)_ (3)_ (4)_ (5)_ (PTS)
 C. CULVERTS (1)_ (2)_ (3)_ (4)_ (5)_ (PTS) D. CREEK CROSSINGS (1)_ (2)_ (3)_ (PTS)
 E. DIVERSION DITCHES (1)_ (2)_ (3)_ (PTS) F. BARRIERS (1)_ (2)_ (3)_ (PTS)
 G. TEMPORARY SEEDING YES NO (10_PTS) POINTS AVAILABLE FOR QUESTION 4: (33 PTS) _____
 5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES NO (2_PTS) (2 PTS) _____
 6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES NO (9_PTS) (9 PTS) _____
 7. RECLAMATION:
 A. ROADWAY (1)_ (2)_ (3)_ (PTS) B. LOCATION (1)_ (2)_ (3)_ (PTS)
 C. PITS (1)_ (2)_ (3)_ (PTS) D. PIPELINES (1)_ (2)_ (3)_ (PTS)
 E. TANK DIKES (1)_ (2)_ (3)_ (PTS) F. API INSTALLED YES OR NO 3_ (PTS)
 G. ADEQUATE SEEDING MATERIALS (1)_ (2)_ (3)_ (PTS)
 H. WAS SEED BED ADEQUATE (1)_ (2)_ (3)_ (PTS) POINTS AVAILABLE FOR QUESTION 7: (24 PTS) _____
 8. WAS RECLAMATION COMPLETED WITHIN:
 MTHS OF TD 6_PTS ONLY; MTHS OF TD 12_PTS ONLY; 2 MTHS OF TD 19_PTS ONLY.
 MAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS) _____

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE: _____

INSPECTIONS :

Frac Permit
Cancelled For Transfer

1/16/19 DATE RELEASED
[Signature] INSPECTOR