

INSPECTORS REPORT

Operator: Consolidation Coal Company

API Number: 47-049-00942 R-285

Findings:

The bottom hole plug has been pumped and the 5-1/2" casing has been cut and being pulled. No problems were found during this inspection.

Does this inspection identify any dust issues? Yes No. If Yes, explain.

Sam Ward

Oil & Gas Inspector

12/12/2018

Date