Cance (INSPECTORS PERMIT SUMMARY FORM

INSPECTORS PERMIT SUMMARY FORM	
PAGE 1 GPS YES NO X	
DATE STARTED/LOCATION: C API #: WELL NO	
DRILLING COMMENCED: Cancel 17-049-2338 "DEETIC. Fe	nn A 3H
TD DATE: DEPTH: FARM FARM	
COAL DEPTHS	
WATER DEPTHS QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30 AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT	
POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE. 1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING: A. CONSTRUCTION YES NO (2 PTS) B. DRILLING YES NO (2 PTS)	
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE	(4 PTS)
SHOW WORK STARTED! YES NO (4 PTS)	(4 PTS)
3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES NO (4 PTS)	(4 PTS)
4. CONSTRUCTION: WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED	
A PAND DITCHEO 1 A A	
C CHI VERTS 1 2 2 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1	
E. DIVERSION DITCHES 1 2 3 (PTS) E. DIVERSION DITCHES 1 2 3 (PTS) F. BARRIERS 1 2 3 (PTS)	
G. TEMPORARY SEEDING VES NO (10 PTS) POINTS AVAILABLE AND TO THE POINTS AVAILABLE AND THE POINTS	
POINTS AVAILABLE FOR QUESTION 4:	(33 PTS)
5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES NO (2 PTS)	(2 PTS)
6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES NO (9 PTS)	(9 PTS)
7. RECLAMATION:	
A. ROADWAY 123(PTS) B. LOCATION 123(PTS)	
C. PITS 1 2 3 (PTS) D. PIPELINES 1 2 3 (PTS)	
E. TANK DIKES 1 2 3 (PTS) F. API INSTALLED YES NO (3 PTS)	
G. ADEQUATE SEEDING MATERIALS 123(PTS)	
H. WAS SEED BED ADEQUATE 1 2 3 (PTS) POINTS AVAILABLE FOR QUESTION 7:	(24 PTS)
8. WAS RECLAMATION COMPLETED WITHIN: A. CONVENTIONAL:	
6 MTHS OF TD6 PTS ONLY; 4 MTHS OF TD12 PTS ONLY; 2 MTHS OF TD19	DTS ONI V
B. HORIZONTAL:	I IS UNL I.
3 YRS OF PAD COMPLETION 19 PTS ONLY; 4 YRS OF PAD COMPLETION 16 PTS ONLY	NLY;
MAXIMUM POINTS AVAILABLE FOR QUESTION 8:	(19 PTS)

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE:

Cancel 5/13/2020 DATE RELEASED

SIPWandt INSPECTOR