



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street, S.E.
Charleston, WV 25304
(304) 926-0450
fax: (304) 926-0452

Austin Caperton, Cabinet Secretary
www.dep.wv.gov

Thursday, January 10, 2019
NOTICE OF PERMIT CANCELLATION
Vertical / Plugging

CONSOL GAS COMPANY
1000 CONSOL ENERGY DRIVE

CANNONSBURG, PA 163176506

Re: Permit cancellation for 11414
47-061-00327-00-00

The FINAL INSPECTION REPORT for the CANCELLED PERMIT, issued for U.S. Well Number 47-061-00327-00-00 , has been received by the Office of Oil and Gas. The permit has been cancelled as of 1/8/2019 .

If there are any questions, please feel free to contact me at (304) 926- 0450.

A handwritten signature in blue ink, appearing to read "James A. Martin", is written over a faint, circular official stamp. The signature is fluid and cursive.

James A. Martin
Chief

Operator's Well Number: 11414
Farm Name: CREEEK, DECKERS
U.S. WELL NUMBER: 47-061-00327-00-00
Vertical Plugging
Date Cancelled: 1/8/2019

IR-8
(REV 4-99)

API NO.: 47-061-00327-00-00

WELL PLUGGING INSPECTION & RELEASE FORM

PLUGGING COMMENCED _____
PLUGGING COMPLETED NA
VERBAL PERMISSION ON NA

OPERATOR: CONSOL GAS COMPANY
FARM: CREEEK, DECKERS
WELL NO: 11414

- 1. IS COAL BEING MINED IN THE AREA? YES NO N/A
- 2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS?
 - A. BOTTOM HOLE PLUGGED YES NO N/A
 - B. 100' PLUGS YES NO N/A
 - C. LATEX PLUGS USED FOR H₂S GAS YES NO N/A
 - D. PROPER PLUGS THROUGH COAL SEAMS YES NO N/A
 - E. PROPER PLUGS SET TO PROTECT FRESHWATER YES NO N/A
 - F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS YES NO N/A

| TYPE | FROM | TO | PIPE REMOVED |
|---|------|----|--------------|
| <u>Not Plugged</u> | | | |
| <u>Permit Cancelled for Well Transfer</u> | | | |
| | | | |
| | | | |
| | | | |

- 3. WERE ALL CHANGES APPROVED BY INSPECTOR? YES NO
- 4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED? YES NO
- 5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE? YES NO
- 6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR? YES NO
- 7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED? YES NO
- 8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS?
 - A. RECLAIMED YES NO
 - B. FENCES REPLACED YES NO
 - C. MULCHED YES NO
 - D. PROPER DRAINAGE YES NO
 - E. SEEDED YES NO
 - F. ALL EQUIPMENT REMOVED YES NO
 - G. PIT BACKFILLED YES NO

1/8/19
DATE RELEASED

[Signature]
INSPECTOR'S SIGNATURE