



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street, S.E.
Charleston, WV 25304
(304) 926-0450
fax: (304) 926-0452

Harold D. Ward, Cabinet Secretary
www.dep.wv.gov

Friday, September 12, 2025
NOTICE OF PERMIT CANCELLATION
Horizontal 6A / New Drill

JAY-BEE OIL & GAS, INC.
23 EGANFUSKEE ST., SUITE 126

JUPITER, FL 33477

Re: Permit cancellation for P7N1
47-073-02594-00-00

The FINAL INSPECTION REPORT for the CANCELLED PERMIT, issued for U.S. Well Number 47-073-02594-00-00, has been received by the Office of Oil and Gas. The permit has been cancelled as of 9/12/2025.

If there are any questions, please feel free to contact me at (304) 926- 0450.


James A. Martin
Chief

Operator's Well Number: P7N1
Farm Name: JOHN P. RIGGS & BRENDA J. RIGGS
U.S. WELL NUMBER: 47-073-02594-00-00
Horizontal 6A New Drill
Date Cancelled: 9/12/2025

Promoting a healthy environment.

09/19/2025

INSPECTORS PERMIT SUMMARY FORM

PAGE 1

GPS YES ☐ NO ☐

DATE STARTED/LOCATION:	CANCELLED	API #:	47-073-02594	WELL NO.	P7N1
DRILLING COMMENCED:	CANCELLED	OPERATOR:	JAY-BEE OIL & GAS, INC.		
TD DATE:		DEPTH:		FARM:	JOHN P. RIGGS & BRENDA J. RIGGS
		COAL DEPTHS			

WATER DEPTHS

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30

AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:

A. CONSTRUCTION YES ☐ NO ☐ (2 PTS) B. DRILLING YES ☐ NO ☐ (2 PTS)(4 PTS) 2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES ☐ NO ☐ (4 PTS)(4 PTS) 3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES ☐ NO ☐ (4 PTS)(4 PTS)

4. CONSTRUCTION:

WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?

A. ROAD DITCHES 1 ☐ 2 ☐ 3 ☐ 4 ☐ (PTS)B. CROSS DRAINS 1 ☐ 2 ☐ 3 ☐ 4 ☐ 5 ☐ (PTS)C. CULVERTS 1 ☐ 2 ☐ 3 ☐ 4 ☐ 5 ☐ (PTS)D. CREEK CROSSINGS 1 ☐ 2 ☐ 3 ☐ (PTS)E. DIVERSION DITCHES 1 ☐ 2 ☐ 3 ☐ (PTS)F. BARRIERS 1 ☐ 2 ☐ 3 ☐ (PTS)G. TEMPORARY SEEDING YES ☐ NO ☐ (10 PTS)POINTS AVAILABLE FOR QUESTION 4: (33 PTS) 5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES ☐ NO ☐ (2 PTS)(2 PTS) 6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES ☐ NO ☐ (9 PTS)(9 PTS)

7. RECLAMATION:

A. ROADWAY 1 ☐ 2 ☐ 3 ☐ (PTS)B. LOCATION 1 ☐ 2 ☐ 3 ☐ (PTS)C. PITS 1 ☐ 2 ☐ 3 ☐ (PTS)D. PIPELINES 1 ☐ 2 ☐ 3 ☐ (PTS)E. TANK DIKES 1 ☐ 2 ☐ 3 ☐ (PTS)F. API INSTALLED YES ☐ NO ☐ (3 PTS)G. ADEQUATE SEEDING MATERIALS 1 ☐ 2 ☐ 3 ☐ (PTS)H. WAS SEED BED ADEQUATE 1 ☐ 2 ☐ 3 ☐ (PTS)POINTS AVAILABLE FOR QUESTION 7: (24 PTS)

8. WAS RECLAMATION COMPLETED WITHIN:

A. CONVENTIONAL:

6 MTHS OF TD ☐ 6 PTS ONLY; 4 MTHS OF TD ☐ 12 PTS ONLY; 2 MTHS OF TD ☐ 19 PTS ONLY.

B. HORIZONTAL:

3 YRS OF PAD COMPLETION ☐ 19 PTS ONLY; 4 YRS OF PAD COMPLETION ☐ 16 PTS ONLY;
5 YRS OF PAD COMPLETION ☐ 13 PTS ONLYMAXIMUM POINTS AVAILABLE FOR QUESTION 8: (19 PTS)

TOTAL MAXIMUM POSSIBLE SCORE OF 99.

TOTAL RECLAMATION SCORE:

9/12/25

DATE RELEASED

Sherman King

INSPECTOR

09/19/2025