

STATE OF WEST VIRGINIA  
DEPARTMENT OF ENVIRONMENTAL PROTECTION  
OFFICE OF OIL AND GAS

AFFIDAVIT OF PLUGGING AND FILLING WELL

AFFIDAVIT SHOULD BE IN TRIPLICATE, one copy mailed to the Department, one copy to be retained by the Well Operator and the third copy (and extra copies if required) should be mailed to each coal operator at their respective addresses.

Farm name: ROWLAND LAND CO. Operator Well No.: 50

LOCATION: Elevation: 2199' Quadrangle: PILOT KNOB  
District: MARSH FORK County: RALEIGH  
Latitude: 7600' Feet South of 37 Deg. 50 Min. 00 Sec.  
Longitude: 2610' Feet West of 81 Deg. 30 Min. 00 Sec.

Well Type: OIL \_\_\_\_\_ GAS X

Company DIVERSIFIED PRODUCTION LLC Coal Operator ROWLAND LAND COMPANY, LLC  
414 SUMMER STREET or Owner 405 CAPITAL STREET, SUITE 609  
CHARLESTON, WV 25301 CHARLESTON WV 25301  
Coal Operator NO DECLARATIONS  
Agent JEFF MAST or Owner \_\_\_\_\_  
Permit Issued Date 07/12/21

AFFIDAVIT

STATE OF WEST VIRGINIA,  
County of JACKSON ss:

MELVIN MYERS and JAMES PURSLEY being first duly sworn according to law depose and say that they are experienced in the work of plugging and filling oil and gas wells and were employed by the above named well operator, and participated in the work of plugging and filling the above well say that said work was commenced on the 26TH day of AUGUST, 2021, and the well was plugged and filled in the following manner:

TYPE	FROM	TO	PIPE REMOVED	LEFT
8 SACKS C1A CEMENT	3342'	3230'		
10 SACKS C1A CEMENT	2875'	2568'		
10 SACKS C1A CEMENT	2234'	2110'		
20 SACKS C1A CEMENT	1525'	1425'	1474' OF 4 1/2" CASING	2000' OF 4 1/2" CASING
20 SACKS C1A CEMENT	802'	702'		752' OF 7" CASING CTS
60 SACKS C1A CEMENT	270'	SURFACE		307' OF 9 5/8" CASING CTS
				<u>6% Gel Between Plugs</u>


Description of monument: 7" CSG WITH API # 36" ABOVE GROUND and that the work of plugging and filling said well was completed on the 1ST day of SEPTEMBER, 2021.

And further deponents saith not. [Signature]

Sworn and subscribe before me this 14th day of October, 2021

My commission expires: 5/9/24

[Signature]  
Notary Public



Affidavit reviewed by the Office of Oil and Gas: [Signature] Title: Inspector

10/22/2021

WELL PLUGGING INSPECTION & RELEASE FORM

PLUGGING COMMENCED 8/26/21 OPERATOR: Dyersford Production  
 PLUGGING COMPLETED 9/1/21 FARM: Roland Cand. Co.  
 VERBAL PERMISSION ON \_\_\_\_\_ WELL NO: 50

1. IS COAL BEING MINED IN THE AREA? YES NO N/A
2. WERE CEMENT AND GEL MIXED AND USED IN ACCORDANCE WITH ACCEPTED INDUSTRY STANDARDS?
- A. BOTTOM HOLE PLUGGED  YES NO N/A
  - B. 100' PLUGS  YES NO N/A
  - C. LATEX PLUGS USED FOR H<sub>2</sub>S GAS  YES NO  N/A
  - D. PROPER PLUGS THROUGH COAL SEAMS  YES NO N/A
  - E. PROPER PLUGS SET TO PROTECT FRESHWATER  YES NO N/A
  - F. PROPER AMOUNT OF GEL USED TO DISPLACE PLUGS  YES NO N/A

TYPE	FROM	TO	PIPE REMOVED
Cement class "A"	3342'	3230'	1474' 4.5 casing
Cement Class "A"	2675'	2569'	
Class "A" Cement	2234'	2110'	
Class "A" Cement	1525'	1425'	
Class "A" Cement	802'	702'	
Class "A" Cement	270'	Surface	
6% Gel Between Plugs			

3. WERE ALL CHANGES APPROVED BY INSPECTOR?  YES NO
4. WAS THE EQUIPMENT USED FOR PULLING CASING PROPERLY SIZED AND RIGGED TO PULL 150% OF THE HEAVIEST STRING OF PIPE EXPECTED TO BE PULLED?  YES NO
5. DID THE OPERATOR GIVE THE INSPECTOR PROPER NOTICE?  YES NO
6. WERE ACCURATE PLUGGING RECORDS KEPT BY THE OPERATOR?  YES NO
7. WAS A PROPER MONUMENT SET WITH API NUMBER ATTACHED?  YES NO
8. DID WELL SITE AND ACCESS ROAD MEET THE FOLLOWING RECLAMATION REQUIREMENTS?
- A. RECLAIMED  YES NO
  - B. FENCES REPLACED  YES NO
  - C. MULCHED  YES NO
  - D. PROPER DRAINAGE  YES NO
  - E. SEEDED  YES NO
  - F. ALL EQUIPMENT REMOVED  YES NO
  - G. PIT BACKFILLED  YES NO

10/18/21

DATE RELEASED

[Signature]

INSPECTOR'S SIGNATURE

RECORD ALL VISITS TO THIS WELL ON PAGE 2

10/22/2021