



west virginia department of environmental protection

Office of Oil and Gas
601 57th Street, S.E.
Charleston, WV 25304
(304) 926-0450
fax: (304) 926-0452

Harold D. Ward, Cabinet Secretary
www.dep.wv.gov

Tuesday, September 16, 2025
NOTICE OF PERMIT CANCELLATION
Horizontal 6A / Horizontal 6A Well - 1

ANTERO RESOURCES CORPORATION
1615 WYNKOOP STREET

DENVER, CO 80202

Re: Permit cancellation for SNODGRASS UNIT 3H
47-085-10288-00-00

The FINAL INSPECTION REPORT for the CANCELLED PERMIT, issued for U.S. Well Number 47-085-10288-00-00 , has been received by the Office of Oil and Gas. The permit has been cancelled as of 9/16/2025

If there are any questions, please feel free to contact me at (304) 926- 0450.

James A. Martin
Chief

A handwritten signature in blue ink, appearing to read "James A. Martin", is written over the printed name and title.

Operator's Well Number: SNODGRASS UNIT 3H
Farm Name: GOFF, RANDALL
U.S. WELL NUMBER: 47-085-10288-00-00
Horizontal 6A Horizontal 6A Well - 1
Date Cancelled: 9/16/2025

Promoting a healthy environment.

09/19/2025

PAGE 1

GPS YES ☐ NO ☐

DATE STARTED/LOCATION: **Canceled** API #: **47-085-10288** WELL NO. **SNODGRASS UNIT 3H**
DRILLING COMMENCED: **Canceled** OPERATOR: **ANTERO RESOURCES CORPORATION**
TD DATE: DEPTH: FARM: **GOFF, RANDALL**
COAL DEPTHS

WATER DEPTHS

QUESTIONS FOR THIS REPORT ARE IN ACCORDANCE OF WV CODE 22-6-30

AND REGULATIONS 35CSR 4-12.1 AND 35CSR 4-16 AND THE GENERAL WATER POLLUTION CONTROL PERMIT

POINTS ARE TO BE GIVEN UP TO MAXIMUM AS SHOWN BASED ON PERFORMANCE.

1. DID OPERATOR GIVE PROPER NOTICE TO INSPECTOR BEFORE THE FOLLOWING:

A. CONSTRUCTION YES ☐ NO ☐ (2 PTS) B. DRILLING YES ☐ NO ☐ (2 PTS)(4 PTS) 2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE
DIRT WORK STARTED? YES ☐ NO ☐ (4 PTS)(4 PTS) 3. ARE ALL LOCATION AND/OR ROAD BANKS BEING SLOPED? YES ☐ NO ☐ (4 PTS)(4 PTS)

4. CONSTRUCTION:

WERE THE FOLLOWING SEDIMENT CONTROL STRUCTURES PROPERLY INSTALLED/MAINTAINED?

A. ROAD DITCHES 1 ☐ 2 ☐ 3 ☐ 4 ☐ (PTS)B. CROSS DRAINS 1 ☐ 2 ☐ 3 ☐ 4 ☐ 5 ☐ (PTS)C. CULVERTS 1 ☐ 2 ☐ 3 ☐ 4 ☐ 5 ☐ (PTS)D. CREEK CROSSINGS 1 ☐ 2 ☐ 3 ☐ (PTS)E. DIVERSION DITCHES 1 ☐ 2 ☐ 3 ☐ (PTS)F. BARRIERS 1 ☐ 2 ☐ 3 ☐ (PTS)G. TEMPORARY SEEDING YES ☐ NO ☐ (10 PTS)**POINTS AVAILABLE FOR QUESTION 4:** (33 PTS) 5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES ☐ NO ☐ (2 PTS)(2 PTS) 6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES ☐ NO ☐ (9 PTS)(9 PTS)

7. RECLAMATION:

A. ROADWAY 1 ☐ 2 ☐ 3 ☐ (PTS)B. LOCATION 1 ☐ 2 ☐ 3 ☐ (PTS)C. PITS 1 ☐ 2 ☐ 3 ☐ (PTS)D. PIPELINES 1 ☐ 2 ☐ 3 ☐ (PTS)E. TANK DIKES 1 ☐ 2 ☐ 3 ☐ (PTS)F. API INSTALLED YES ☐ NO ☐ (3 PTS)G. ADEQUATE SEEDING MATERIALS 1 ☐ 2 ☐ 3 ☐ (PTS)H. WAS SEED BED ADEQUATE 1 ☐ 2 ☐ 3 ☐ (PTS)**POINTS AVAILABLE FOR QUESTION 7:** (24 PTS)

8. WAS RECLAMATION COMPLETED WITHIN:

A. CONVENTIONAL:

6 MTHS OF TD ☐ 6 PTS ONLY; 4 MTHS OF TD ☐ 12 PTS ONLY; 2 MTHS OF TD ☐ 19 PTS ONLY.

B. HORIZONTAL:

3 YRS OF PAD COMPLETION ☐ 19 PTS ONLY; 4 YRS OF PAD COMPLETION ☐ 16 PTS ONLY;5 YRS OF PAD COMPLETION ☐ 13 PTS ONLY**MAXIMUM POINTS AVAILABLE FOR QUESTION 8:** (19 PTS) **TOTAL MAXIMUM POSSIBLE SCORE OF 99.****TOTAL RECLAMATION SCORE:**

9/16/25

DATE RELEASED

Jeremy Newlon

INSPECTOR

09/19/2025