PAGE 1			GPS YES NO	
DATE STARTED/LOCATION:		API#:	910 /355 WELL NO.	T.1 205
DRILLING COMMENCED:		DPERATOR:		Johnson 205
TD DATE:	DEPTH:		FARM: RESOURCES	Z = 2
WATER DEPTHS			AL DEPTHS	507
QUESTIONS FOR THIS REPORT ARE AND REGULATIONS 35CSR 4-12.1 A	E IN ACCORDANG ND 35CSR 4-16 A	CE OF WV CO	ODE 22-6-30 NERAL WATER POLLUTION CON	TROL PERMIT
POINTS ARE TO BE GIVEN UP TO	MAXIMUM AS S	SHOWN BAS	ED ON PERFORMANCE.	
1. DID OPERATOR GIVE PROPER NO A. CONSTRUCTION YES NO	TICE TO INSPEC (2 PTS)	CTOR BEFOR B. DRILLING	E THE FOLLOWING: G YES NO (2 PTS)	(4 PTS)
2. WAS THE TIMBER CUT, STACKED, AND BRUSH USED FOR SEDIMENT BARRIERS BEFORE DIRT WORK STARTED? YES NO (4 PTS)				(4 PTS)
3. ARE ALL LOCATION AND/OR RO	AD BANKS BEIN	NG SLOPED?	YES NO (4 PTS)	(4 PTS)
4. CONSTRUCTION: WERE THE FOLLOWING SEDIMENT	CONTROL STR	UCTURES PR	OPERLY INSTALLED/MAINTAIN	ED?
A. ROAD DITCHES 1 2 3 4	(PTS)		S DRAINS 1 2 3 4 5	
C. CULVERTS 1 2 3 4 5	(PTS)		K CROSSINGS 1 2 3 (P)	
E. DIVERSION DITCHES 1 2 3	=		IERS 1 2 3 (PTS)	.5)
G. TEMPORARY SEEDING YES			AVAILABLE FOR QUESTION 4:	(33 PTS)
5. HAS TOP SOIL (IF ANY) BEEN STOCKED PILED? YES O NO (2 PTS)				(2 PTS)
6. IS THE PIT PROPERLY INSTALLED AND MAINTAINED? YES NO (9 PTS)				(9 PTS)
7. RECLAMATION:				
A. ROADWAY 1 2 3 (PTS)	B. LOC	ATION 1	23(PTS)	
C. PITS 1 2 3 (PTS)	D. PIPEI	LINES 1	23(PTS)	
E. TANK DIKES 1 2 3 (PTS) F. API II	NSTALLED	YES \bigcirc NO \bigcirc $(3 PTS)$	
G. ADEQUATE SEEDING MATERIAL	S 1 2 3	(PTS)		
H. WAS SEED BED ADEQUATE 1			VAILABLE FOR QUESTION 7:	(24 PTS)
8. WAS RECLAMATION COMPLETED	WITHIN:			
6 MTHS OF TD6 PTS ONLY;	4 MTHS OF TD	12 PTS C	ONLY; 2 MTHS OF TD 19 P	TS ONLY.
			VAILABLE FOR QUESTION 8:	
TOTAL MALENTANA AND AND AND AND AND AND AND AND AND				
TOTAL MAXIMUM POSSIBLE S	CORE OF 99.		TOTAL RECLAMATION	N SCORE.
INCRECTIONS			TOTAL RECLAMATION	N SCORE:
INSPECTIONS:	Cancel			
3.29-21 A	eyen Harn			
DATE RELEASED	INSPECTO	K		

INSPECTOR

04/02/2021